

## भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0674-2352463: TeleFax: 0674-2352490; ro.bhubaneshwar@ibm.gov.in Plot No.149, Pokhariput BHUBANESWAR-751016

Date: 09/07/2018

Date:09.07.2018

REGD/AD

No.: ORI/IRON/MB/MCDR—1/BBS/ VOL-II/

सेवा में.

Shri Rajkumar Misra,

Director & Nominated Owner,

Badampahar Iron Ore Mines, M/s Lal Traders & Agencies (P) Ltd

Po: Rairangpur (near railway crossing),

Dist: Mayurbhnaj, Odisha-757043.

Sub: Violation of provisions of MCDR, 2017 in respect of your Badampahar Iron Mine over an area of 129.61 hectare in Mayurbhanj district of Odisha.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 04.07.2018 by the undersigned along with Shri Dilip Jain, JMG accompanied by S/Shri M.D.Nayak, Assistant Mining Officer (Baripada) Shri H.N.Das, Mining Engineer, and Rajesh Kumar Mahanta, Mine Manager of your mine.

Rule No.	Proposed in the approved mining plan / Rule	Violation
31 (4)	The plans and sections required under these rules shall be maintained up to date with in three months in case of category 'A' mines.	During inspection it is observed that surface plan was not updated within three months. The last updated plan was till March 2018.
54 (c)	Holder of mining lease shall maintain the sub grade or mineral reject stack register along with grade.	During inspection it is observed that sub-grade or mineral reject stack register along with grade not maintained.

02. It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

Senior Assistant Controller of Mines Indian Bureau of Mines

- ol - 100/18

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- The Controller of Mines (EZ),भारतीय खान ब्यूरो / Indian Bureau of Mines, Kolkata-700091.
- (2) डायरेक्टर ऑफ माइन्स /The Director of Mines, डायरेक्टोरेट ऑफ माइन्स / Directorate of Mines, उड़ीसा सरकार / Government of Orissa, हेडस ऑफ डिपार्टमेंट बिल्डिंग / Heads of Department Building, न्यू कैंपिटल / New Capital, भुवनेश्वर / Bhubaneswar-751 001: For information & further necessary action on following:

(Ramkishan R)

Senior Assistant Controller of Mines

कृते क्षेत्रीय खान नियंत्रक/For Regional Controller of Mines