



Hkkjr Lkjckj  
[kku ea-ky;  
Hkkjr; [kku C; yjks  
{ks-h; [kku fu; a-d clk dk; ky;  
i k&V&OkV&Mk] eMx&M] nf{k.k xksok 403602

GOVERNMENT OF INDIA  
MINISTRY OF MINES  
INDIAN BUREAU OF MINES  
OFFICE OF REGIONAL CONTROLLER OF MINES  
P.O. Fatorda, Madgao, South Goa - 403602

No. KNT/BJP/Lst-62/Goa

Minecode 38KAR26059

Date: 07.09.2013

To,

Shri M. Ramappa, Sr. G.M. (Mines),  
J.K. Cement Works, a unit of M/s J.K. Cement Limited,  
Muddapur, Taluka-Mudhol,  
Bagalkot-587122

Sub : Violation of provisions of Mineral Conservation and Development Rules, 1988, in respect of your Halki limestone Mine (M.L. No. 2344A) over an extent of 124.24ha in Village- Halki, Taluka-Mudhol, District-Bagalkot of Karnataka state.

Sir,

The following provisions of the MCDR, 1988 were found violated in your above mine during the inspection on 06.09.2013 by undersigned in presence of Shri Pawankumar Deshmukh, Dy. Mines Manager.

Rule No	Nature of Violations observed
13(1)	The mining operations in the lease area are not carried out as per approved scheme of mining and following deviations are observed during inspection. a) As per plate 8, it was proposed to stack dolomite and sub-grade mineral in SE side of working pit. It was anticipated that 3,38,000t dolomite & sub-grade mineral will be generated during 2012-13. It was observed during the inspection that dolomite & sub-grade mineral generation was not reported during 2012-13 and it is not stacked as per proposals for previous years also.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of Mineral Conservations and Development Rules, 1988.

03. The mining operations can be suspended under rule 13(2), if compliance of rule 13(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

(G. K. Jangid)

Deputy Controller of Mines  
Indian Bureau of Mines

Copy forwarded to :

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mines & Geology, 49, Khanij Bhawan, Race Course Road, Bangalore-560001
3. The Deputy Director, Department of Mines & Geology, 63A, Navanagar, Bagalkot -587103

Deputy Controller of Mines  
Indian Bureau of Mines