



GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF REGIONAL CONTROLLER OF MINES



FAX : 080- 23371027 / 23373287
Tel : 080-23371027 / 23375366 / 67
Email ID: ro.bangalore@ibm.gov.in
rcombng@rediffmail.com

29, Industrial Suburb, II Stage,
Tumkur Road, Gorguntapalya,
Yeshwantpur,
Bangalore- 560 022.

Dated: 28.02.2014

No.KNT/BLR/Fe-403/BNG

To:
Sri Faisal Shareef
Managing Partner
M/s.Nadeem Minerals
No.419, Ground floor,
6th B Cross, 20th Main
6th Block, Koramangala
Bangalore 560 095.

Sub: Violation of provisions of MCDR 1988 in respect of Donimalai Iron ore Mine (ML No 2526) over an extent of 53.20 ha in Bhujanagar village, Bellary district, Karnataka State ... reg
Sir,

The following provisions of the Mineral Conservation and Development Rules 1988 were found violated in your above mine during the inspection on 06.01.2014 by the undersigned in the presence of Shri Bharathi Dasan, Mines Manager.

| | |
|--------------------|---|
| Rule 13(1) | The Scheme of Mining was approved vide letter No.KNT/BLR/MS/Fe-189/SZ dated 12/09/2012 for the period from 2011-12 to 2015-16. The deviations observed in mining operations visa-vis approved document are given below: (i) Against the proposals of afforestation during the period 2012-13, 1875 saplings were required to be planted but only 1350 plants have been planted. (ii) Garland drain during 2012-13 was proposed to be constructed for a length of 782 m whereas only 600 m drain has been constructed. (iii) As per one of the condition No.(xi) of the approved Scheme of Mining, the data on environmental monitoring has not been maintained in a bound page register. |
| 42(1)(c)(i) | A whole time Mining Engineer possessing degree in Mining has not been appointed in accordance with this rule. |

02. In this connection, it is to bring to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988. Further, the violation of Rule 13(1) of MCDR may also attract provision of Rule 13(2) of MCDR 1988 regarding suspension of mining operations till the compliance of the violations.

03. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

(B RAM MOHAN)
REGL. CONTROLLER OF MINES

Copy for kind information to :

1. The Controller of Mines(SZ), IBM, Bangalore.
2. The Director, Dept. of Mines & Geology, Govt. of Karnataka, Khanij Bhavan, Race Course Road, Bangalore 560 001.
3. Sri Bharathi Dasan, Mines Manager, M/s.Nadeem Minerals, No.419, Ground floor, 6th B Cross, 20th Main, 6th Block, Koramangala, Bangalore 560 095.for necessary action.

(B RAM MOHAN)
REGL. CONTROLLER OF MINES