



GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF REGIONAL CONTROLLER OF MINES



FAX : 080- 23371027 / 23373287
Tel : 080-23371027 / 23375366 / 67
Email ID: ro.bangalore@ibm.gov.in
rcombng@rediffmail.com

29, Industrial Suburb, II Stage,
Tumkur Road, Gorguntapalya,
Yeshwantpur,
Bangalore- 560 022.

Dated: 03.04.2014

No.KNT/BLR/Fe-437/BNG

To:
Sri P Sreenivasa Rao, DGM(Mines)
Haddinapade iron ore mine of
Sri B Rudra Gouda
#2198, BKG House
KHB Colony
Sandur 583 119
Bellary district, Karnataka.

Sub: Violation of provisions of MCDR 1988 in respect of Haddinapade Iron ore Mine (ML No 2516) over an extent of 54.23 ha in Hulakunte village, Sandur taluk, Bellary district, Karnataka State ...
reg

Sir,

The following provisions of the Mineral Conservation and Development Rules 1988 were found violated in your above mine during the inspection on 07.01.2014 by the undersigned in the presence of Shri P Sreenivasa Rao, DGM(Mines) and B Rudra Gouda, Owner.

Rule 13(1)	<p>The Scheme of Mining was approved vide letter No.KNT/BLR/MS/Fe-186/SZ /922 dated 10/09/2012 for the period from 2011-12 to 2015-16. The deviations observed in mining operations visa-vis approved document are given below:</p> <p>(i) During 2012-13 and 2013-14, the dumping of waste has been proposed in the southern block on the NW side between the coordinates N-1662250 to N 1662315 and E-665940 to E 666050 (Refer Plate 6A & B), but during the inspection, dumping was found being carried out 350 mts below the proposed location resulting in deviation of the proposals.</p> <p>(ii) As per condition No.(11) of the approved Scheme of Mining, the data on environmental monitoring has not been maintained in a bound page register.</p>
Rule 48	<p>The particulars of boreholes drilled has not been maintained in a bound page register as per Form-K</p>

02. In this connection, it is to bring to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR 1988. Further, the violation of Rule 13(1) of MCDR may also attract provision of Rule 13(2) of MCDR 1988 regarding suspension of mining operations till the compliance of the violations.

03. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully,

(B RAM MOHAN)
REGL. CONTROLLER OF MINES

Copy for kind information to :

1. The Controller of Mines(SZ), IBM, Bangalore.
2. The Director, Dept. of Mines & Geology, Govt. of Karnataka, Khanij Bhavan, Race Course Road, Bangalore 560 001.

(B RAM MOHAN)
REGL. CONTROLLER OF MINES