

## VIOLETION LETTER

REGD/ A D

Hkkjr ljdkj  
[kku ea=ky;  
Hkkjrh; [kku C;wjks  
{ks=h; [kku fu;a=d dk  
dk;kZy;  
[ibmbbsr@dataone.in](mailto:ibmbbsr@dataone.in)



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of the Regional Controller of Mines.  
Ph-(0674)2742463 / Fax-0674 2744430

File No. ORI/IRON-MN/SNG/MCDR-13 /BBS	Mahani Complex, 2 <sup>nd</sup> Floor 308, District Centre, Chandrasekharpur Bhubaneswar-751 016
---------------------------------------	--

To,

Date : 31.07.2013

**Mr. Pradeep Kumar Saraf, Director & Nominated Owner**  
**Aryan Mining & Trading Corp. (p) Ltd.**  
**Aryan House, P 1, Hide Lane,**  
**Johar Building , 8<sup>th</sup> Floor,**  
**Kolkata- 700 073, Fax- 033 2236 4602**

**Sub: Violation of provisions of MCDR, 1988 in respect of Narayanposhi Iron & Manganese Mine, (over 349.254 Ha) of M/s Aryan Mining & Trading Corp. (p) Ltd in Sundergarh District of Odisha State.**

Sir,

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above said mine during inspection on 24.06.2013 by the undersigned, accompanied by Mr. D. Patel (DGM-Mines) & Mr. S. Mohanty (Principal Geologist) of your mine.

Rule No.	Nature of Violation
13(1)	Mining operations have not been carried out in accordance with the Modification of Scheme of Mining approved dated 30.05.2013 to the extent indicated below :- Retaining wall along with garland drain and check dams have not been constructed all around the toe of the Natural Fines stacks No.- 4 & 5 situated near ML boundary pillar- BP51/7 and Iron Quarry No. - 6 to prevent surface wash off and escape of material.
42 (1) (C)	Mining Engineer employed i.e. Mr. I.K.Saha is not having ten years of professional experience of working in a supervisory capacity in the field of mining as required under this rule.

**02.** In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR, 1988.

Besides, inability to comply the provision of Rule 13 (1) is also liable for suspension of mining operations according to Rule 13 (2) of MCDR, 1988.

**03.** You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (forty-five) days** from the date of issue of this letter.

Yours faithfully,

(PREM PRAKASH)

Sr. Assistant Controller of Mines

ewy izfr ij ugh / Not on Original izfrfyfi fuEu dks lknj lwpukFkZ vxzsf"kr

- (1) [kku fu;a=d(e/;kazpy)/The Controller of Mines (CZ),Hkkjrh; [kku C;wjks@Indian Bureau of Mines, ukxiqj /Nagpur-440 001.
- (2) Mk;jsDVj vkWQ ekbUI /The Director of Mines,Mk;jsDVksjsV vkWQ ekbUI@Directorate of Mines,mM+hlk ljdkj /Government of Orissa, gsMI vkWQ fMikVZesaV fcfYMax /Heads of Department Building, U;w dSfiVy /New Capital, Hkqous'oj /Bhubaneswar-751 001.

(PREM PRAKASH)

Sr. Assistant Controller of Mines

d`rs {ks=h; [kku fu;a=d/For Regional Controller of Mines