



भारत सरकार Government of India

खान मंत्रालय Ministry of Mines

भारतीय खान ब्यूरो Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय Office of the Regional Controller of Mines

100, ओल्ड नेहरु कॉलोनी, देहरादून (उत्तराखण्ड) 248001 / 100 Old Nehru Colony, Dehradun (U.K.) 248001

TEL- 0135-2676350 / 2671896, E-mail - ro.dehradun@ibm.gov.in



फाईल संख्या File No: HP/SRM/LST-27

Mine Code: 38HPR100029

दिनांक, 10, July 2020

सेवा में To: मै. सोहनसिंह मीतसिंह एण्ड संस,

E-mail: sohansinghmeetsingh@gmail.com

ग्राम व पो- 0 कमरऊ,

तह - 0 पावंटा साहिब,

जिला - सिरमौर, हिमाचल प्रदेश

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Bhimgoda Limestone Mine, Mining Lease over an area of 3.32 ha located near Village-Kamroo, Tehsil-Paonta Sahib in Sirmour district of Himachal Pradesh State-Reg.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the inspection made by the undersigned on 23.01.2020 in the presence of Shri Som Prakash Tomar, Mine Manager and the same was communicated to you vide our letter of even number dated on 31-03-2020

RULE NO.	NATURE OF VIOLATION OBSERVED
11(1)	Mining operation were not carried out in accordance with the approved modified mining plan vide letter no 614(2)/MP-B-288/08- DDN dated 22.02.2019 to the following extent: As per proposal during the year 2019-20, it was proposed to carry out mining operation from 2045 to 1985 mRL by formation of benches 6 mtr height. During the inspection height of benches has been observed up to 10 mtrs whereas as per approved modified mining plan it should be six meter.
29	" Mine was found in operation, whereas Intimation of re-opening of mine through Form-C has not been submitted to the authorized officer in the prescribed form on resumption/ re- start of mining operation after temporary discontinuance, so as to reach this office within 15 days from the date of such reopening"
55	Every holder of mining lease shall employ a geologist in the mine. But geologist has not been appointed in the mine.

- In connection to above you have not submitted the compliance of violated rules, thus it has been considered that you do not intend to comply the violated rules and the violation of Rules 11(1), 29 & 55 of MCDR, 2017 still persists.
- In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
- Mining Operation can be suspended as per rule 11(2) in case of non compliance of rule 11(1) of MCDR 2017.
- May initiate appropriate action in accordance with any competent orders/directives etc.
- You are therefore directed to show cause within a period of thirty (30) days from the date of issue of this letter, as to why you should not be prosecuted and / or why mining operation can be suspended under statutory provisions.

Please note that no further notice will be given to you in this regard.

भवदीय Yours faithfully,


16-07-2020
(दामोदर प्रसाद शर्मा / D P Sharma)

सहायक खान नियंत्रक / Assistant Controller of Mines
भारतीय खान ब्यूरो / Indian Bureau of Mines

प्रतिलिपि सूचनार्थ प्रेषित :-

- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुरा (zo.udaipur@ibm.gov.in)
- निदेशक, उद्योग निदेशालय, हि० प्र० सरकार, उद्योग भवन, शिमला (हि० प्र०), (geologicalwing@gmail.com)
- साई फाइल
- खान फाइल

सहायक खान नियंत्रक / Assistant Controller of Mines