

भारत सरकार /Government of India

खान मंत्रालय/Ministry of Mines

भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757

Fax No. : (0832) –2741758

E-Mail : [ro.goa@ibm.gov.in](mailto:ro.goa@ibm.gov.in)

File No:- MAH/RTG/BX-10/GOA

Opp.Old R.T.O.'s Office,

P.O. FATORDA - 403602,

Margao-GOA

Date:- 24.05.2019

To,

Mr. Milind Sardessai, Nominated Owner  
M/s Infrastructure Logistics Pvt. Ltd., Cidade De Goa,

Vainguinim Beach, Goa – 403004

Sub : Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Gudeghar Bauxite Mine,(Mine Code 07MSH20006, area 91.58 Ha) M/s Infrastructure Logistics Pvt. Ltd situated in Gudeghar Village of Mandangad taluka, Ratnagiri District of Maharashtra.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 13/05/2019 by the undersigned in presence of Mr. Pramod Sarode, Mines Manager and Mining Engineer.

Rule	Nature of Violation observed
11(1)	<p>Mining Operation have not been carried out in accordance with the Scheme of Mining(SOM) approved vide letter no. MSH/Mech-75(MAH)/Goa/2014-15, dated 18.02.2015 to the extent indicated below:-</p> <p>(i) Exploration was proposed to be carried out from 2015-16 to 2017-18 by drilling 40 core boreholes at earmarked place to cover the entire lease area. Although some boreholes were reported carried out and further the exploratory drilling machine was also observed in place. However, the aforesaid proposal were not completed in the earmarked places as approved in SOM.</p> <p>(ii) The excavation was proposed to be carried out between the section lines 300650 to 300750 in the year 2018-19. However, it has observed during the inspection that excavation was carried out between the sectional grid lines 300500 to 300600.</p> <p>(iii) Large quantity of mineral stacks were observed without safeguarding the substantial environmental protective measures to control from the washoff of material.</p>

02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,

(S.Prasad)  
Deputy Controller of Mines  
Indian Bureau of Mines

Copy forwarded to: -

1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
2. The Dy. Director, Directorate Mines and Geology, Govt.of Maharashtra, Udyog Bhavan,Nagala Park,Kolhapur.

(S.Prasad)  
Deputy Controller of Mines  
Indian Bureau of Mines