

**INDIAN BUREAU OF MINES
MINERALS DEVELOPEMMENT AND REGULATION DIVISION**

MCDR INSPECTION REPORT

Hyderabad regional office

Mine file No : AP/CDP/FE-9/HYD

Mine code : 30APR04009

- (i) Name of the Inspecting : **AP03**) **A.Prabhakar Rao**
Officer and ID No.
- (ii) Designation : Assistant Mining Geologis
- (iii) Accompanying mine : NAIK Lessee"s Representative
Official with
Designation
- (iv) Date of Inspection : 16/02/2017
- (v) Prev.inspection date :

PART-I : GENERAL INFORMATION

1. (a) **Mine Name** : **THUMALUR(148.74 HA)**
- (b) **Registration NO.** :
- (c) Category : B Manual
- (d) Type of Working : Opencast
- (e) Postal address
State : ANDHRA PRADESH
District : CUDDAPAH
Village : THUMMALUR
Taluka : NANDIMANDALAM
Post office : THUMMALUR
Pin Code : 516218
FAX No. : -
E-mail : -
Phone : 9440164225
- (f) Police Station : Pendlimarri
- (g) First opening date : 28/02/2008
- (h) Weekly day of rest : SUN
2. Address for : S.K.JAIN,POWER OF ATTONEY HOLDER,DNO.20/1054
correspondance R.K.NAGAR ,COOPERATIVE COLONY ,KADAPA
3. (a) Lease Number : APR2481
- (b) Lease area : 148.8
- (c) Period of lease : 20
- (d) Date of Expiry : 13/12/2027
4. Mineral worked : IRON ORE Main

5. Name and Address of the

Lessee : S.V.SIVA REDDY
1-397/1,COURT ROAD KADAPA
CUDDAPAH ANDHRA PRADESH
Phone:
FAX :

Owner : S.K.JAIN POWER OF ATTONEY HOLDER OF S.V.SIVAREDDY
M/S PACIFIC MINING PVT LTD
DNO.20/1054,R.K.NAGAR ,
COOPERATIVE COLONY KADAPA
CUDDAPAH ANDHRA PRADESH
Phone: 9440164225
FAX : -

Manager
Name : D.RAJA RAMI REDDY
Qualification : Dip.in Mining
Appointment/ :
Termination date

6. Date of approval of Mining : Fresh under rule 22 MCR1960 19/09/2005
Plan/Scheme of Mining

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	-	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

1b	Exploration over lease area for geological axis 1 or 2	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	-	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
1c	Exploration Agencies and Expenditure in lakh rupees during the year	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	-	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

1d	Balance area to be explored to bring Geological axis in 1 or 2	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	-	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
1e	Balance reserve as on 01/04/20	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	-	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

1f	General remarks of inspecting officers on geology, exploration etc	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	-	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
----	--	--	---	--

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

2a	Location of development w.r.t.lease area	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 on 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 on 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>

2c	Stripping ratio or ore to OB ratio	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 on 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>
2d	Quantity of topsoil generation in m3	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 on 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>

2e	Quantity of overburden generation in m3	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended undewr Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

- 3a Number of pit proposed for production
- Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
- For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
- 3b Quantity of ROM mineral production proposed
- Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
- For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

3c	Recovery of sailable/usable mineral from ROM production	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
3d	Quantity of mineral reject generation	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

- 3e Grade of mineral rejects generation and threshold value declared. Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
- 3f Quantity of sub grade mineral generation. Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

- 3g Grade of sub
grade mineral
generation
- Modifications -
of Approved
Mining Plan
vide letter no
.659(539)Fe/20
05
Hyd,dated19.09
.2005 for the
period2008-09
to 2013-14,
For non com-
pliance of
Rule13(1) of
MCDR 1988
Mining
operations
were suspended
under Rule
13(2) of MCDR
1988 ON
10/01/2013 .As
on date of
inspection no
valid document
for this mine
- For non com-liance
of Rule13(1) of
MCDR 1988 Mining
operations were
suspended under
Rule 13(2) of MCDR
1988 ON 10/01/2013
.As on date of
inspection no
valid document for
this mine
- 3h Manual /
Mechanised
method adopted
for segregating
from ROM
- Modifications -
of Approved
Mining Plan
vide letter no
.659(539)Fe/20
05
Hyd,dated19.09
.2005 for the
period2008-09
to 2013-14,
For non com-
pliance of
Rule13(1) of
MCDR 1988
Mining
operations
were suspended
under Rule
13(2) of MCDR
1988 ON
10/01/2013 .As
on date of
inspection no
valid document
for this mine
- For non com-liance
of Rule13(1) of
MCDR 1988 Mining
operations were
suspended under
Rule 13(2) of MCDR
1988 ON 10/01/2013
.As on date of
inspection no
valid document for
this mine

- 3i Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects. Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine NO For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
- 3j Provision of drilling and blasting in mineral benches Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine NO, One bench was formed in Ore dimensions are: Length =150.0 m(EAST - WEST)XWidrth= 5.0 m (NORTH -SOUTH),Hight 3.0 m Two benches were formed in ORE DIMENSIONS ARE: 1)Length =120.0 m(EAST - WEST)XWidrth= 5.0 m (NORTH -SOUTH),Hight 3.0 m 2)Length =120.0 m(EAST - WEST)XWidrth= 5.0 m (NORTH -SOUTH),Hight 3.0 m For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine NO For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

- 3k Provision of mining machineries in mineral benches Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine NO For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
- 31 Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine One bench was formed in Ore dimensions are: Length =150.0 m(EAST - WEST)XWidrth= 5.0 m (NORTH -SOUTH),Hight 3.0 m Two benches were formed in ORE DIMENSIONS ARE: 1)Length =120.0 m(EAST - WEST)XWidrth= 5.0 m (NORTH -SOUTH),Hight 3.0 m 2)Length =120.0 m(EAST - WEST)XWidrth= 5.0 m (NORTH -SOUTH),Hight 3.0 m For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

3m	Total area covered under excavation/pits	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	1.2 hectars old excavations Pit no 1,length =150.0meters(EAST -WEST) X Wdth=80.0 meters (north -south) Depth =20.0 meters	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
3n	Ore to OB ratio for the pit/mine during the year.	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL

- 3o Total area put in use under different heads at the end of year Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine 1.2 Hectars pit excavatiions For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
- 3p Production of ROM mineral during the last five year period as applicable Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine - For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

3q	General remarks of inspecting officers on method of mining etc.	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL
----	---	---	---	-----

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

4b	Location of topsoil, OB and mineral reject dumps	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
4c	Number of dumps within lease area and outside of lease area	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
4e	Number of active and alive dumps.	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

4f	Number of dead dumps.	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
4g	Number of dumps established.	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

- 4h Whether Retaining wall or garland drain all along dumps are there. Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine No retaining wall or garland drain all along the dumps were formed For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
- 4i Length of Retaining wall or garland drain all along dumps Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine No retaining wall or garland drain all along the dumps were formed For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine

4j	Number of settling ponds	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NO seettling ponds were formed	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine
4k	Specific comments of inspecting officer on waste dump management	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>Part full extraction of mineral from minedout area not completed</p>
5b	Area under backfilling of mined out area	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	NIL

5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>top soil not used for restoration of mineral out area</p>
5d	Total area fully reclaimed and rehabilitated	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>Not mature4d for reclamation</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>

5e	General remarks of inspecting officers on backfilling and reclamation etc.	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL
----	--	--	---	-----

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	Not submitted

6b	Area available for rehabilitation (ha) .	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	Not matured for rehabilitation
6c	afforestation done (ha).	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	NIL

6d	No. of saplings planted during the year	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	NIL
6e	Cumulative no .of plants	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	Not carriedout

6f	Any other method of rehabilitation	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	NIL
6g	Cost incurred on watch and care during the year	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	NIL

6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non com-liance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non com-liance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non com-liance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non com-liance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL

6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestation on on backfilled area	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL

61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non com- liance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non com-liance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non com- liance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non com-liance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL

6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL
6p	Compliance of environmental monitoring (core zone and buffer zone)	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	Not complied

6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL
----	---	---	---	-----

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	Mine was under suspension

7b	Method of grade-wise mineral sorting i.e. manual or mechanical.	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	NIL
7c	Different grade of mineral sorted out at mines.	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	Different grades of mineral not sorted out

7d	Any beneficiation process at mines .	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NOo beneficiation process adopted in the mine
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	Modifications of Approved Mining Plan vide letter no .659(539)Fe/20 05 Hyd,dated19.09 .2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL

Environment :

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

8a	Separate removal and utilization of topsoil (Rule 32)	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	Minewas networking
8b	Concurrent use or storage of topsoil	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	Minewas networking

8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>no seperate dumps for overburden waste rock rejects and fines were not found</p>
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	NIL

8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	Not available
8g	Survival rate	<p>Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	<p>For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine</p>	NIL

8h	Water sprinkling on roads to control airborne dust	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	Minewas notworking
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

9a	Status of submission of Monthly and Annual returns	Annual Returnfor year 2011-, Monthly Return for the monthof February 2014 received from the lessee Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	The mine was under suspension on 10/01/2013.The mine was not working
----	--	--	---	--

9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Annual Returnfor year 2011-, Monthly Return for the monthof February 2014 received from the lessee Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	The mine was under suspension on 10/01/2013.The mine was not working
----	---	--	---	--

9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Annual Returnfor year 2011-, Monthly Return for the monthof February 2014 received from the lessee Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	The mine was under suspension on 10/01/2013.The mine was not working
----	---	--	---	--

9d	Scrutiny of Annual return on afforestation	Annual Return for year 2011-, Monthly Return for the month of February 2014 received from the lessee Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd, dated 19.09.2005 for the period 2008-09 to 2013-14, For non compliance of Rule 13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule 13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	NIL
----	--	--	--	-----

9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Annual Returnfor year 2011-, Monthly Return for the monthof February 2014 received from the lessee Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	The mine was under suspension on 10/01/2013.The mine was not working
----	---	--	---	--

9f	Scrutiny of Annual return on ROM stock and/or graded ore	Annual Returnfor year 2011-, Monthly Return for the monthof February 2014 received from the lessee Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	The mine was under suspension on 10/01/2013.The mine was not working
----	--	--	---	--

9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Annual Returnfor year 2011-, Monthly Return for the monthof February 2014 received from the lessee Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	The mine was under suspension on 10/01/2013.The mine was not working
----	---	--	---	--

9h	Scrutiny of Annual return on fixed assets	Annual Returnfor year 2011-, Monthly Return for the monthof February 2014 received from the lessee Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	The mine was under suspension on 10/01/2013.The mine was not working
----	---	--	---	--

9k	Scrutiny of Annual return on mining machineries	Annual Returnfor year 2011-, Monthly Return for the monthof February 2014 received from the lessee Modifications of Approved Mining Plan vide letter no .659(539)Fe/2005 Hyd,dated19.09.2005 for the period2008-09 to 2013-14, For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	For non compliance of Rule13(1) of MCDR 1988 Mining operations were suspended under Rule 13(2) of MCDR 1988 ON 10/01/2013 .As on date of inspection no valid document for this mine	The mine was under suspension on 10/01/2013.The mine was not workingL
----	---	--	---	---

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed		Show cause position	
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on

Date :

(A.Prabhakar Rao)

Indian Bureau of Mines