REGD/ A D VIOLATION CUM SHOW CAUSE NOTICE

Tel: (0712) 2565089,2562794 Fax: (0712) 2565089,2565603 Email: rcom_nr@ibm.mah.nic.in GOVERNMENT OF INDIA MINISTRY OF MINES 6th Floor, Block B & C Indira Bhavan, Civil Lines, Nagpur - 440001

INDIAN BUREAU OF MINES

Office of the Regional Controller of Mines

No. MP/BGT/MN-61/NGP

Nagpur, Dated 04.10.2013

To, Shri Rahul Agarwal, Nominated Owner, M/s Jain Carbiides and Chemicals Ltd.. Plot No. 557, 563 and 564, Urla industrial Area Raipur – 493221, Chhatisgarh.

Sub: Violation of provisions of MCDR, 1988 in respect of Jagantola Manganese Ore Mine (Area 6.264 ha)

Sir

The following provisions of Mineral Conservation & Development Rules, 1988 are found violated in your above mine during inspection on 29/09/2013 by ShriHarkeshMeena, Deputy Controller of Mines, Jabalpur (Team Leader) and **Dr.** A. K. Ghoshal, Junior Mining Geologist, Nagpur Regional Office, accompanied by Shri R. P. Kamlesh, Assistant Mining Officer, A. K. Nagle, Mining Inspector and M. A. Quereshi, Mining Surveyor, DGM, Balaghat, Govt. of M.P. and Shri N. K. Babar, General Manager and K. Maleshappa, Mine Manager, of your mine.

Rule No.	Nature of Violation							
13(1)	Every holder of a mining lease shall carryout mining operations in accordance with the approved mining plan / scheme of mining with such conditions as may have been prescribed under Sub Rule (2) of Rule 9 or such modifications if any, as permitted under Rule 10 or the mining plan or scheme of mining approved under Rule 11 or 12 as the case may be. It was observed that the scheme of mining was approved vide letter No. BGT/Mn/MPLN-483/NGP dated 31.03.2009. The Scheme of mining approved is valid upto.31.03.2014. The details of cumulative development are as on 29.09.2013:							
	Г	Sr	Winze	Depth	Incline	Length	Level No.1]
		No.	No.	in m	No.	in m	Development in m	
		1	4	10.4	4	40	0	
		2	5	13.30	5	69	26	
		3	6	13.40	6	72	30	
		4	7	13.20	7	55	12.8	
		5	8	14.40	8	38.7	0	
		6	9	15.0	9	10.30	19	
	It was proposed in the approved scheme of mining that the deposit shall be developed by 12 vertical winzes from surface starting at 605 to 608 mRL bench (open cast pit) to intersect the ore then follow the ore body along the dip. But it was observed during inspection that only six winzes of above mentioned depth were developed. Hence it is lacking in development against the proposals given for the year 2009-10 to 2013-14 thus attracting the violation of Rule 13(1) of MCDR 1988, which may lead to suspension of mining operations in accordance to the Rule 13(2) of the MCDR 1988.							

- It is brought to your notice that the above violations constitute an offence punishable under rule 58 of MCDR, 1988.
- 04. You are therefore directed to **SHOW CAUSE** within a period of 30 days from the date of issue of this letter, as to why mining operations in your mine should not be suspended under rule 13(2) for the violation of provision of rule 13(1) as above.
- OF Please note that no further notice will be given to you in this regard.

Yours faithfully,

Dr. A. K. Ghoshal) Junior Mining Geologist

Copy forwarded, for information to:

- (1) The Controller of Mines (CZ), 6th Floor, 'D' Block, Indian Bureau of Mines, Nagpur-440001.
- (2) The Director, Directorate of Geology and Mining, Govt. of Madhya Pradesh, 29 A, Arera Colony, KhanijBhavan, **Bhopal 462016** (Madhya Pradesh).
- (3) The Collector, Office of the District Collectorate, At & P.O. Balaghat-481001, Madhya Pradesh.

(**Dr.** A. K. Ghoshal) Junior Mining Geologist