

MCDR INSPECTION REPORT

1.0 GENERAL

SN	Particulars	Details
1 (a)	Name of the Mine	Tanasava Limestone Mine
1(b)	Name of Inspecting Officer & Designation	G.Ram, Sr.ACOM
1(c)	Accompanying Mines Representatives	Mr Parbhatbhai Baria
1(d)	Type of Inspection	MCDR-Star Rating
1(e)	Date of Inspection	30.6.2021
2	Total Lease Area (Ha), Non-forest and forest land	4.0 ha (Non Forest Land)
3	Mine Code	38GUJ13003
4	IBM Registration Number under rule 45 of MCDR	IBM/9913/2012
5	Name of the lessee, Address, phone, email and fax number	Smt Ramilaben Parbatbhai Baria, Jirapa Plot, Tagor Road, Garbi Chawk, Village – Upleta, Talika – Upleta, Dist – Rajkot, Pin-360490,9909923131, Email – udayminerals181@gmail.com
6	Village	Upleta
7	Taluka/Mandal	Upleta
8	District	Rajkot
9	Pin code	360490
10	State	Gujarat
11	Post office	Upleta
12	Nearest police station	Upleta
13	Nearest Railway station	Upleta
14	Date of Grant of Mining Lease	30 th July 2009
15	Date of Execution	19 th September 2009
16	Date of opening of Mine	---
17	Date of first Renewal, if applicable and its period & expiry	NA
18	Date of second Renewal, if applicable, its period & expiry	NA
19	Date of submission of renewal application if Mining Operations are continuing under deemed extension	NA
20	Name of the Nominated Owner with Address, phone, email, fax number and date of appointment	Smt Ramilaben Parbatbhai Baria, Jirapa Plot, Tagor Road, Garbi Chawk, Village – Upleta, Taluka – Upleta, Dist – Rajkot, Pin-
21	Name of the Mine Agent with Address, phone, email, fax number and date of appointment	---
22	Name of the Mines Manager with Address, phone, email, fax number and date of appointment in mines	---
23	Name of the Mining Engineer, Qualification and total experience with Address, phone, email, fax number and date of appointment in mine	---
24	Whether Geologist and Mining Engineer appointed in mines satisfy the rule 55 & carrying out their duties	---
25	Date of Approval of MP/MMP with five-year period, specific condition in approval letter, if any.	682(23)(656)/2009/KHANIKHAS(N)/UDP Dated 14/7/2009
26	Date of Approval of SOM with five-year period and specific condition in approval letter, if any.	684(4)(1)/MP-212/2019, MDRD/(UDP)/GNR Dated 9 th April 2019 for 2019-20 to 2023-24.
27	Mineral(s) granted in lease and proved for mining	Limestone
28	Method of Mining(Opencast, Underground)	Opencast
29	Category (Fully Mechanised, Others or Manual)	Mechanised
30	Captive/Non Captive	Non Captive

Scientific Mining: Compliance of proposals of approved mining plan/scheme of mining. –

Exploration

SN	Item	Proposals (2020-21)	Actual work	Remarks
1a	Backlog of previous year	Not Proposed	Not done	
1b	Exploration over lease area for Geological axis 1 or 2.	----	-----	
1c	Exploration Agency & Expenditure in lakh Rs in yr.	Not Proposed	As per Proposal	
1d	Balance area to be explored in Geological axis in 1/ 2	Not Proposed	As per proposal	
1e	Balance reserves as on 01.04.2021.	Reserves-111,121&122-467965T		
1f	General remarks of inspecting officer on geology, exploration etc.	Entire lease area is explored in past, hence not proposed & done.		

2.0 Development

SN	Item	Proposals (2020-21)	Actual work	Remarks
2a	Location of development w.r.t. lease area	Not Proposed	Not done	

2b	Separate benches in topsoil, overburden and mineral	Not Proposed	NIL	
2c	Stripping ratio or ore to OB ratio	1:0	1:0	
2d	Quantity of topsoil generation in m3	Not Proposed	NIL	
2e	Quantity of OB generation in m3	Not Proposed	NIL	
2f	General remarks of I/officer on development of pit w.r.t. type of deposit	Lease area is developed by mine pit with irregular shape & size.		

3.0 Exploitation

SN	Item	Proposals (2020-21)	Actual work	Remarks
3a	Number of pits proposed for production	One Pit	One pit	Legging in ROM
3b	Quantity of ROM mineral production proposed	92,000	38,500T	
3c	Recovery of salable/usable mineral from ROM	100 %	100%	
3d	Quantity of mineral reject generation	Not Proposed	NIL	
3e	Grade of mineral reject generation and THV declared	Not Proposed	NIL	
3f	Quantity of sub-grade mineral generation	Not Proposed	NIL	
3g	Grade of sub-grade mineral generation	Not Proposed	NIL	
3h	Manual / Mechanised method adopted for	Manual/Mech.	NIL	
3i	Any analysis or beneficiation study proposed & carried out for sub-grade mineral and reject	Not Proposed	NIL	
3j	Provision of drilling & blasting in mineral benches	Not Proposed	As per Proposal	
3k	Provision of mining machineries in mineral benches	JCB, Loader, tipper	As per proposal	
3l	Height of benches in OB/ mineral suitable for method of mining proposed in MP/SOM	Bench Height – 6 mt	3 mt in Ore	
3m	Total area covered under excavation/pits	---	About 3Ha	
3n	Ore to OB ratio for the pit/mine in year	No OB to be generated	NIL	
3o	Total area put in use under different heads at end of yr.	---	3.195 ha	
3p	Production of ROM mineral during last five-year period, as applicable	2017-18 – 52002T 2018-19 – 52785 T 2019-20- 75965.2T 2020-21- 92000T 2021-22- 100000T	2017-18 – 39200T 2018-19 – 44000T 2019-20- 73000T 2020-21- 38500T (MR) 2021-22-NIL (Till)	VL pointed for discontinuance notice (Till May,21)
3q	General remarks of I/ officer on method of mining etc.	Mining area needs to be covered with fencing.		

4.0 Solid Waste Management-Dumping

SN	Item	Proposals (2020-21)	Actual work	Remarks
4a	Separate dumping of topsoil, OB & mineral reject	Not Proposed	Nil	
4b	Location of topsoil, OB & mineral reject dumps	Not Proposed	Nil	
4c	Number of dumps within lease area and outside lease	Not Proposed	Nil	
4d	Location of dumps w.r.t. ultimate pit limit	Not Proposed	Nil	
4e	Number of active & alive dumps	Not Proposed	Nil	
4f	Number of dead dumps	Not Proposed	Nil	
4g	Number of dumps stabilised	Not Applicable	Nil	
4h	Whether Retaining wall/ garland drain all along dumps	Not Applicable	Nil	
4i	Length of Retaining wall/ garland drain all along dump	Not Applicable	Nil	
4j	Number of settling ponds	Not Applicable	Nil	
4k	Specific comments of inspecting officer	Nil		

5.0 Solid Waste Management-Backfilling

SN	Item	Proposals (2020-21)	Actual work	Remarks
5a	Status on part or full extraction of mineral from mined out area before starting backfilling	Not Proposed	Nil	
5b	Area under backfilling of mined out area	Not Proposed	Nil	
5c	Concurrent use of topsoil for restoration or rehabilitation of mined out area	Not Proposed	Nil	
5d	Total area fully reclaimed & rehabilitated	Not Proposed	Nil	
5e	General remarks of inspecting officer on backfilling, reclamation etc	As per proposal		

6.0 Progressive Mine Closure Plan

SN	Item	Proposals (2020-21)	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly - Rule 26(2)	Not Submitted to IBM. Violation of rule 26(2) has been pointed out in this regard.		

6b	Management of worked/mined out benches i) Area available for rehabilitation (ha) ii) Afforestation done (ha) iii) No. of saplings planted during the year iv) Cumulative no. of plants v) Any other specific method of rehabilitation vi) Cost incurred on watch care during yr	Not Proposed	NIL	
6c	Compliance on reclamation and rehabilitation by backfilling i) Voids available for backfilling (L X B X D) ii) Void filled by waste/tailings iii) Afforestation on the backfilled area iv) Rehabilitation by making water reservoir v) Any other specific means	Not Proposed	NIL	
6d	Compliance of Rehabilitation of waste land within lease i) Afforestation ii) Area rehabilitated (ha) iii) Method of rehabilitation	Plantation - 0.025 ha Proposed – 25 no	Plantation - 0.025 ha Proposed – 25 no	Poor survival
6e	Compliance of Env. monitoring (core & buffer zone)	Proposed		
6f	General remarks of inspecting officer on PMCP compliance & progressive	Violation of rule 26(2) has been pointed out.		

7.0 Mineral Conservation

SN	Item	Proposals (2020-21)	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within ML	Not Proposed	As per proposal	
7b	Method of grade-wise mineral sorting i.e. manual/ mech.	Not Proposed	As per proposal	
7c	Different grade of mineral sorted out at mines	Not Proposed	As per proposal	
7d	Any beneficiation process at mines	Not Proposed	As per proposal	
7e	General remarks of inspecting officer on Mineral conservation & beneficiation issues	As per proposal		

8.0 Environment

SN	Item	Proposals (2020-21)	Actual work	Remarks
8a	Separate removal and utilization of topsoil	Not Proposed	As per proposal	
8b	Concurrent use or storage of topsoil	Not Proposed	As per proposal	
8c	Separate dumps for overburden, waste, rejects and fines	Not Proposed	As per proposal	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	Not Proposed	As per proposal	
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc.)	Not Proposed	As per proposal	
8f	Baseline information on existence of plantation & additional plantation done	Proposed	Not as per proposal	
8g	Survival rate	50 %		
8h	Water sprinkling on roads to control airborne dust	Not Proposed	As per proposal	
8i	General remarks of inspecting officer on aesthetic beauty in and around mines are	The environment in & around the mine is good.		

9.0 Compliance of Rule 45

S.N	Item	COMMENTS		Remarks
	Status of submission of Monthly and Annual returns	MR/AR-submitted on time & 2020-21 is not submitted.		
S.N	Item	Details GIVEN (A.R)	Obs. of I/Officer	Remarks
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Lessee has not submitted the monthly & annual return for 2020-21 till date	Lessee has not submitted the monthly & annual return for 2020-21 till date	Violation under provision of rule & 45(5)© pointed out to lessee for non-submission
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.			
9d	Scrutiny of Annual return on afforestation			
9e	Scrutiny of Annual return on mineral reject generation			
9f	Scrutiny of Annual return on ROM stock			
9g	Scrutiny of AR on sale value, Ex. Mine price & Cost			
9i	Scrutiny of Annual return on fixed assets			
9k	Scrutiny of Annual return on mining machineries			

10- Details of violations observed during current inspection and compliance position of earlier violation pointed out:- Presently mine was inspected for Star Rating & during inspection, lease boundary pillars were not available/erected & maintained as per statute & working appears outside. Presently violation of 26(2), 28(1), 33, 45(5) (c),55(1)©(i) pointed out for rectification. Star rating (03 star) validation done.
