


**VIOLATION LETTER**

REGD/AD

भारत सरकार GOVERNMENT OF INDIA  
खान मंत्रालय MINISTRY OF MINES  
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक के कार्यालय  
OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0674-2352463;

TeleFax: 0674-2352490;

eMail:

ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput

BHUBANESWAR-751016

Date:26.07.2017

No.: ORI/LST&amp;DOL/SNG/MCDR-5/BBS/

Date: 26/07/2017

सेवा में

The AED (Mines)/ Mines Agent  
Lanjiberna Limestone and Dolomite Mines  
M/s OCL India Limited,  
Regd. office – OCL India Limited., Rajgangpur, Dist: Sundargarh,  
State: Odisha) Pin Code-770017.

**Sub: Violation of provisions of MCDR, 2017 in respect of your Lanjiberna Limestone & Dolomite Mine over an area of 873.057 hectare in Sundargarh district of Odisha.**

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 17.07.2017 by the undersigned accompanied by S/Shri Lokesh Shrimali, Mine Manager, B Jagadeesh Kumar, Mining Engineer and Udayanth Sahoo, Geologist of your mine.

Rule No.	Proposed in the approved mining plan / Rule	Violation
11 (1)	As per the approved mining scheme dated 25/03/2015, Bench width of minimum 12 m shall be maintained in quarry 4-5.	During inspection it was observed that the bench widths are less than 12 m in southern side of quarry 4-5 between 4600E-5100E.
37 (2)	The dumps shall be properly secured to prevent escape of material therefrom in harmful quantities which may cause degradation of environment and to prevent causation of floods.	During inspection it was observed that there are no protective measures like retaining wall and garland drain in northern side of active waste dump over reclaimed area.
45 (7)	Holder of mining lease shall not submit incomplete or wrong or false information in daily or monthly or annual returns.	During scrutiny of annual return it is found that information furnished under item 3 of part-IV and item 4.2 (c) of part-V are contradicting each other.

**02.** It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR, 2017.

*Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.*


*Further, in view of the above position, the information furnished under Rule 45(5) in the Annual return is construed as furnishing wrong or false information, which leads this office to advise the state government under rule 45 (7) to,-*

*(i) Order suspension of all mining operations in the mine and to revoke the order of suspension only after ensuring proper compliance;*

- ii) Take action to initiate prosecution under these rules;  
(iii) Recommend termination of the mining lease, in case such suppression or misrepresentation of information indicates abetment or connivance of illegal mining;

03. You are advised to rectify the above violations immediately and intimate the position to this office within **45 (forty-five) days** from the date of issue of this letter.

Yours faithfully,

  
(Ramkishan R)

Senior Assistant Controller of Mines  
Indian Bureau of Mines

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- (1) खान नियंत्रक(मध्यमंचल)/**The Controller of Mines (CZ/EZ)**, भारतीय खान ब्यूरो /  
**Indian Bureau of Mines, Nagpur-440001/Kolkata-700091.**
- (2) डायरेक्टर ऑफ माइन्स /**The Director of Mines**, डायरेक्टोरेट ऑफ माइन्स /**Directorate of Mines**, उड़ीसा सरकार /**Government of Orissa**, हेडस ऑफ डिपार्टमेंट बिल्डिंग /**Heads of Department Building**, न्यू कैपिटल /**New Capital**, भुवनेश्वर /**Bhubaneswar-751 001 : For information & further necessary action on following :**



(Ramkishan R)

Senior Assistant Controller of Mines  
कृते क्षेत्रीय खान नियंत्रक/For Regional Controller of Mines