INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR inspection REPORT

Jabalpur regional office

Mine f	file No : MP/KTN/LST-8	7		Mine code : 38MPR18123
(i)	Name of the Inspecting Officer and ID No.	:	CQ04) ROBERT SIMON C	
(ii)	Designation	:	Assistant Controller Mine	
(iii)	Accompaning mine Official with Designation	:		
(iv)	Date of Inspection	:	18-DEC-21	
(v)	Prev.inspection date	:	14-DEC-17	
	PAF	۲T-	I : GENERAL INFORMATION	
(a)	Mine Name	:	KACHHGAON (1.821 HA)	
(b)	Registration NO.	:		
(f) (g) (h)	Category Type of Working Postal address State District Village Taluka Post office Pin Code FAX No. E-mail Phone Police Station First opening date Weekly day of rest	: : : : : : : : : : : :	KATNI KACHHGAON VIJAYRAGHAVGARH DIWAN SIDING 483880 07622- 230466 N. A. 07622- 230388 13-JUL-84 SUN	
corre	spondance		ANIL KUMAR NAGRATH BHARAT LIME CO., CIVIL LII KATNI (M.P.) 483501	NES,
(c)	Lease Number Lease area Period of lease Date of Expiry	::	MPR0190 1.82 10 22-MAY-92	
Miner	al worked	:	LIMESTONE Mai	n

1.

2.

3.

4.

5.	Name and Address of t	che		
	Lessee	:	ANIL KUMAR NAGRATH	
			CIVIL LINES KATNI MADHYA	
			PRADESH	
			Phone:N. A.	
			FAX :N. A.	
	Owner	:	ANIL KUMAR NAGRATH	
			BHARAT LIME CO. CIVIL LINES	
			KATNI MADHYA PRADESH	
			Phone: 07622- 230388	
			FAX : 07622- 230466	
6.	Date of approval of M	1ini	ng : Renewal under rule 22 MCR1960	13-JAN-95
	Plan/Scheme of Mining	3	Mining Scheme rule 12 MCDR1988	09-AUG-00
			Mining Scheme rule 12 MCDR1988	09-AUG-00
			Mining Scheme rule 12 MCDR1988	22-JUL-05
			Renewal under rule 24 MCR1960	
			MP modif under MCR 1960	12-APR-16

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
la	Backlog of previous year	No proposals	Not applicable	No backlog of previous year as the mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed
1b	Exploration over lease area for geological axis 1 or 2		The lease area already explored upto G1	
1c	Exploration Agencies and Expenditure in lakh rupees during the year	No proposals	NA	
1d	Balance area to be explored to bring Geological axis in 1 or 2	No proposals	The area already explored upto G1	
1e	Balance reserve as on 01/04/20	No proposals	As on 08.12.2021 111-259458 tonnes 122-324314 tonnes 211-125228 222-125228 tonnes	fresh estimation as per MEMC rule 2015 done.
lf	General remarks of inspecting officers on geology, exploration etc			The ML area lies along the foot hill of the Kymore hill range. The lease area from a part of the Semri Group and comprises rocks belonging to Rohtas formation of lower Vindhyan system consists limestone which is grey, light gray, fine to Medium Grained and Slightly fractured.

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	No proposals	Not applicable	There was no proposal for the last year as the mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	No proposals	NA	
2c	Stripping ratio or ore to OB ratio	No proposals	NA	
2d	Quantity of topsoil generation in m3	No proposals	NA	
2e	Quantity of overburden generation in m3	No proposals	NA	
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc			The mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	No proposals	Not applicable	There was no proposal for the last year as the mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.
3b	Quantity of ROM mineral production proposed	No proposals	NA	

3с	Recovery of sailable/usable mineral from ROM production	No	proposals	NA
3d	Quantity of mineral reject generation	No	proposals	NA
3e	Grade of mineral rejects generation and threshold value declared.	No	proposals	NA
3f	Quantity of sub grade mineral generation.	No	proposals	NA
3g	Grade of sub grade mineral generation	No	proposals	NA
3h	Manual / Mechanised method adopted for segregating from ROM	No	proposals	NA
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No	proposals	NA
3j	Provision of drilling and blasting in mineral benches	No	proposals	NA
3k	Provision of mining machineries in mineral benches	No	proposals	NA
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	No	proposals	NA
Зm	Total area covered under excavation/pits	No	proposals	1.10 hect

3n	Ore to OB ratio for the pit/mine during the year.	No proposals	NA	
30	Total area put in use under different heads at the end of year	No proposals	1.41 hect	
3р	Production of ROM mineral during the last five year period as applicable		2017-18 Nil 2019-20 Nil 2019-20 Nil	
3q	General remarks of inspecting officers on method of mining etc.			There was no proposal for the last year as the mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	No proposals	NA	The mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.
4b	Location of topsoil, OB and mineral reject dumps	No proposals	NA	
4c	Number of dumps within lease area and outside of lease area	No proposals	02 dumps existing within lease	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	No proposals	within UPL	

4e	Number of active and alive dumps.	No proposals	NA	
4f	Number of dead dumps.	No proposals	NA	
4g	Number of dumps established.	No proposals	NA	
4h	Whether Retaining wall or garland drain all along dumps are there.	No proposals	NA	
4i	Length of Retaining wall or garland drain all along dumps	NA	NA	
4j	Number of settling ponds	No proposals	Nil	
4k	Specific comments of inspecting officer on waste dump management			The mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposals	Nil .	As per the latest approved mining plan full extraction of mineral is proposed before starting backfilling
5b	Area under backfilling of mined out area	No proposals	Nil	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No proposals	Nil	

5d Total area No proposals Nil
fully reclaimed
and
rehabilitated
5e General remarks
of inspecting
officers on
backfilling and
reclamation etc.

The mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	No proposals.	NA	The mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.
6b	Area available for rehabilitation (ha) .	No proposals	NA	
6c	afforestation done (ha).	No proposals	Nil	
6d	No. of saplings planted during the year	No proposals	Nil	
6e	Cumulative no .of plants	No proposals	NA	
6f	Any other method of rehabilitation	No proposals	NA	
6g	Cost incurred on watch and care during the year	No proposals	NA	
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	No proposals	NA	

6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No	proposals	NA
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	No	proposals	NA
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No	proposals	NA
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No	proposals	NA
бm	Compliance of rehabilitation of waste land within lease (i)afforestation	No	proposals	NA
бn	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	No	proposals	NA
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	No	proposals	NA

бр	Compliance of environmental monitoring (core zone and buffer zone)	No	proposals	Nil
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.			

The mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	No proposals	NA	The mine was not in operation and no approved document since 2019-20 and the year 2020-21 is lapsed.
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	No proposals	NA	
7c	Different grade of mineral sorted out at mines.	No proposals	NA	
7d	Any beneficiation process at mines •	No proposals	NA	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			The mine was not in operation and no approved document since 2019-20 and the years 2019-20 to 2020-21 is lapsed.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks

8a	Separate removal and utilization of topsoil (Rule 32)	No	proposals	NA
8b	Concurrent use or storage of topsoil	No	proposals	NA
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	No	proposals	NA
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No	proposals	NA
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No	proposals	NA
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	No	proposals	NA
8g	Survival rate	No	proposals	NA
8h	Water sprinkling on roads to control airborne dust	No	proposals	NA

8i General remarks
of inspecting
officer on
aesthetic beauty
in and around
mines area

The mine was not in operation and no approved document since 2019-20 and the years 2019-20 to 2020-21 is lapsed. Aesthetic beauty in and around mine area needs to be improved.

2020-21 is lapsed.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	AR & MR online submitted		The mine was not in operation and no approved document since 2019-20 and the years 2019-20 to 2020-21 is lapsed
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	No proposals	The mine was not in operation and no approved document since 2019-20 and the years 2019-20 to 2020-21 is lapsed. Hence no information on Mining Engineer, Geologist and Manager is furnished.	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	No proposals	Already exploited & abandoned by opencast (O/C) mining-1.821	
9d	Scrutiny of Annual return on afforestation	No proposals	Nil	The mine was not in operation and no approved document since 2019-20 and the years 2019-20 to

9e Scrutiny of No proposals Nil Annual return on mineral reject generation (Grade and quantity)

9f Scrutiny of No proposals Nil Annual return on ROM stock and/or graded ore

9g Scrutiny of No proposals Nil Annual return on sale value, Ex. Mine price and production cost

9h Scrutiny of No proposals Nil Annual return on fixed assets
9k Scrutiny of No proposals Nil Annual return on mining machineries The mine was not in operation and no approved document since 2019-20 and the years 2019-20 to 2020-21 is lapsed.

The mine was not in operation and no approved document since 2019-20 and the years 2019-20 to 2020-21 is lapsed.

The mine was not in operation and no approved document since 2019-20 and the years 2019-20 to 2020-21 is lapsed.

Details of violations observed during current inspection and compliance position of violation pointed out					
Violation observed			Sho	ow couse position	
Rule NO.	Issued on	Compliance on	Rule NO	. Issued on Compliance on	

Date :

(ROBERT SIMON C)

Indian Bureau of Mines