INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR inspection REPORT

Jabalpur regional office

Mine file No : UP/SONEBHADRA/LST-5 Mine code : 38UPR56001

(i) Name of the Inspecting : SQ23) SANDEEP KUMAR SINGH

Officer and ID No.

(ii) Designation : Deputy Controller Mines

(iii) Accompaning mine : Sh Atul Gahrana (Geologist)

Official with Designation

(iv) Date of Inspection : 20-SEP-21

(v) Prev.inspection date :

PART-I : GENERAL INFORMATION

1. (a) Mine Name : DALLA(KAJRAHAT)(751.0HA)

(b) Registration NO. :

(c) Category : A Fully Mechanised

(d) Type of Working : Opencast

(e) Postal address

State : UTTAR PRADESH
District : SONBHADRA

Village : Taluka : Post office : Pin Code : NA E-mail : NA Phone : NA

(f) Police Station :

(g) First opening date : 01-FEB-07

(h) Weekly day of rest : SUN

2. Address for : M/S JAIPRAKASH ASSOCIATES LIMITED

correspondance DALLA CEMENT FACTORY, VILL. KOTA, P.O. DALLA,

DISTT. SONEBHADRA (U.P.)

3. (a) Lease Number : UPR0007
(b) Lease area : 751
(c) Period of lease : 20

(d) Date of Expiry : 30-APR-16

4. Mineral worked : LIMESTONE Main

5. Name and Address of the

Lessee : JAIPRAKASH ASSOCIATES LIMITED

P.O.DALLA, DISTT.

SONEBHADRA (U.P.) 231207 SONBHADRA UTTAR PRADESH

Phone: FAX:

Owner : JAIPRAKASH ASSOCIATES LIMITED

P.O.DALLA, DISTT.

SONEBHADRA (U.P.) 231207 SONBHADRA UTTAR PRADESH

Phone: FAX:

6. Date of approval of Mining : Mining Scheme rule 12 MCDR1988 28-AUG-07

Plan/Scheme of Mining

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	NA	NA	
1b	Exploration over lease area for geological axis 1 or 2	NA	NA	
1c	Exploration Agencies and Expenditure in lakh rupees during the year	NA	NA	
1d	Balance area to be explored to bring Geological axis in 1 or 2	NA	G1-2.199 ha G4-103.648 ha	
1e	Balance reserve as on 01/04/20		111- 352836 T 221-1491801 T 331-65584 T 334-52497594 T	
1f	General remarks of inspecting officers on geology, exploration etc			There is no valid mining plan for last two 5 years block period

Development :

	_			
Sl.No.	Item	Propasals	Actual work	Remarks
2a	=	document for	Two old pit Pit 1&2 - 130x35 mtr Pit 3-140x75 mtr	
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	document for	NA	
2c	Stripping ratio or ore to OB ratio		NA	
2d	Quantity of topsoil generation in m3	document for	NA	

2e	Quantity of	No approved	NA
	overburden	document for	
	generation in m3	the RY.	

2f General remarks of inspecting officers on development of pit w.r.t. type of deposit etc

Mines is not in operation for last many years.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	No approved document for the RY.	NA	
3b	Quantity of ROM mineral production proposed	No approved document for the RY.	NA	
3с	Recovery of sailable/usable mineral from ROM production	No approved document for the RY.	NA	
3d	Quantity of mineral reject generation	No approved document for the RY.	NA	
3e	Grade of mineral rejects generation and threshold value declared.	No approved document for the RY.	NA	
3f	Quantity of sub grade mineral generation.	No approved document for the RY.	NA	
3g	Grade of sub grade mineral generation	No approved document for the RY.	NA	
3h	Manual / Mechanised method adopted for segregating from ROM	No approved document for the RY.	NA	

Remarks

3j Provision of drilling and document for blasting in the RY. mineral benches 3k Provision of Mo approved Ma document for machineries in mineral benches 3l Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM 3m Total area Covered under covered under document for during the year. The RY. 3n Ore to OB ratio for the RY. 3o Total area put in use under different heads at the end of year 3p Production of No approved NA document for during the last five year period as applicable 3q General remarks of inspecting officers on method of mining in motion operation.	3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No approved document for the RY.	NA	
mining document for the RY. mineral benches 31 Whether height No approved of benches in document for overburden and mineral suitable for method of mining proposed in MP/SOM 3m Total area No approved NA document for excavation/pits 3n Ore to OB ratio for the pit/mine during the year. 3n Total area put in use under different heads at the end of year 3p Production of No approved NA document for during the last the LAST 10 five year period as applicable 3q General remarks of inspecting method of mining 3q General remarks of inspecting method of mining 31 Whether height No approved NA NA document for the five years, method of mining mine is not in	3j	drilling and blasting in	document for	NA	
of benches in overburden and mineral suitable for method of mining proposed in MP/SOM 3m Total area No approved NA covered under excavation/pits the RY. 3n Ore to OB ratio for the pit/mine document for during the year. the RY. 3o Total area put No approved NA for the pit/mine document for during the year. the RY. 3o Total area put No approved NA in use under document for different heads at the end of year 3p Production of No approved NA ROM mineral document for during the last five year period as applicable 3q General remarks of inspecting of inspecting officers on method of mining mine is not in	3k	mining machineries in	document for	NA	
covered under excavation/pits the RY. 3n Ore to OB ratio No approved NA for the pit/mine document for during the year. the RY. 3o Total area put No approved NA in use under document for different heads at the end of year 3p Production of No approved NA ROM mineral document for during the last the LAST 10 five year period as applicable 3q General remarks of inspecting officers on method of mining NA no approved no last 10 years, mine is not in	31	of benches in overburden and mineral suitable for method of mining proposed	document for	NA	
for the pit/mine document for during the year. the RY. 30 Total area put No approved NA in use under document for different heads the RY. at the end of year 3p Production of No approved NA ROM mineral document for during the last the LAST 10 five year period YEARS. as applicable 3q General remarks of inspecting officers on method of mining NA NA No approved document for the last 10 years, mine is not in	3m	covered under	document for	NA	
in use under document for different heads the RY. at the end of year 3p Production of No approved NA ROM mineral document for during the last the LAST 10 five year period YEARS. as applicable 3q General remarks of inspecting officers on method of mining mine is not in	3n	for the pit/mine	document for	NA	
ROM mineral document for during the last the LAST 10 five year period YEARS. as applicable 3q General remarks No approved document for the officers on last 10 years, method of mining mine is not in	30	in use under different heads at the end of	document for	NA	
of inspecting document for the officers on last 10 years, method of mining mine is not in	3p	ROM mineral during the last five year period	document for the LAST 10	NA	
	3q	of inspecting officers on method of mining			document for the last 10 years, mine is not in

Propasals Actual work

Solid Waste Management - Dumping:

Sl.No. Item

Remarks

4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	No approved document for the RY.	NA	
4b	Location of topsoil, OB and mineral reject dumps	No approved document for the RY.	NA	
4c	Number of dumps within lease area and outside of lease area	No approved document for the RY.	NA	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	No approved document for the RY.	NA	
4e	Number of active and alive dumps.		NA	
4f	Number of dead dumps.	No approved document for the RY.	NA	
4g	Number of dumps established.	No approved document for the RY.	NA	
4h	Whether Retaining wall or garland drain all along dumps are there.	No approved document for the RY.	NA	
4i	Length of Retaining wall or garland drain all along dumps	No approved document for the RY.	NA	
4 ј	Number of settling ponds	No approved document for the RY.	NA	
4 k	Specific comments of inspecting officer on waste dump management	No approved document for the RY.	NA	No approved document for the RY.

Solid Waste Management - Backfilling:

Propasals Actual work

Sl.No. Item

5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No approved document for the RY.	NA	
5b	Area under backfilling of mined out area	No approved document for the RY.	NA	
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No approved document for the RY.	NA	
5d	Total area fully reclaimed and rehabilitated	No approved document for the RY.	NA	
5e	General remarks of inspecting officers on backfilling and reclamation etc.	No approved document for the RY.	NA	No approved document for the RY. Mine is not in operation for last many years.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).		NA	
6b	Area available for rehabilitation (ha) .	No approved document for the RY.	NA	
6c	afforestation done (ha).	No approved document for the RY.	NA	
6d	No. of saplings planted during the year	No approved document for the RY.	NA	

6e	Cumulative no .of plants	No approved document for the RY.	NA
6f	Any other method of rehabilitation	No approved document for the RY.	NA
6g	Cost incurred on watch and care during the year	No approved document for the RY.	NA
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	1 1	NA
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No approved document for the RY.	NA
6j	Compliance on reclamation and rehabilitation by backfilling (iii) Afforestati on on backfilled area	No approved document for the RY.	NA
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No approved document for the RY.	NA
61	Compliance on reclamation and rehabilitation by backfilling (v) any other specific means.	No approved document for the RY.	NA

6m	Compliance of rehabilitation of waste land within lease (i)afforestation	No approved document for the RY.	NA	
6n	Compliance of rehabilitation of waste land within lease (ii) Area rehabilitation (ha)	No approved document for the RY.	NA	
60	Compliance of rehabilitation of waste land within lease (iii) Method of rehabilitation	No approved document for the RY.	NA	
бр	Compliance of environmental monitoring (core zone and buffer zone)	No approved document for the RY.	NA	
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.			Mine is not in operations. No PMCP work in force.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	No approved document for the RY.	NA	
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	document for	NA	
7c	Different grade of mineral sorted out at mines.		NA	

7d	Any beneficiation process at mines .	No approved document for the RY.	NA	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			Mine is not in operation for last many years.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	document for	NA	
8b	Concurrent use or storage of topsoil	No approved document for the RY.	NA	
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	No approved document for the RY.	NA	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No approved document for the RY.	NA	
8 e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No approved document for the RY.	NA	

8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	No approved document for the RY.	NA	
8g	Survival rate	No approved document for the RY.	NA	
8h	Water sprinkling on roads to control airborne dust	document for	NA	
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area			Mine is not in operation for last many years.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns		As per office records, no Annual Returns submitted for the mine	Mine is not in operation for last many years.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager		No annual returns submitted for RY	
9с	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.		No annual returns submitted for RY	
9d	Scrutiny of Annual return on afforestation		No annual returns submitted for RY	

9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	No annual returns submitted for RY
9f	Scrutiny of Annual return on ROM stock and/or graded ore	No annual returns submitted for RY
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	No annual returns submitted for RY
9h	Scrutiny of Annual return on fixed assets	No annual returns submitted for RY
9k	Scrutiny of Annual return on mining machineries	No annual returns submitted for RY

PAGE : 13

Details of violations observed during current inspection and compliance position of violation pointed out				
Violation observed			Show couse position	
Rule NO.	Issued on	Compliance on	Rule NO	. Issued on Compliance on

Date : (SANDEEP KUMAR SINGH)

Indian Bureau of Mines