



भारत सरकार /GOVERNMENT OF INDIA

खान मंत्रालय/ MINISTRY OF MINES

भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक का कार्यालय, गोवा /OFFICE OF THE RCOM, GOA

(आईएसओ-9001:2008)



Phone No.: 0832-2741757

Fax No. : 0832-2741758

E-mail: ro.goa@ibm.gov.in

Opp. Old R.T.O. Office,

P.O. Fatorda,

MARGAO, GOA. -403 602

No. KNT/BGM/LST-30/Goa

Dated 23rd March 2018

Mine code: **38KAR02038**

To,
Shri T.Venkatesan,
Dy. Managing Director & Nominated Owner,
Dalmia Cement (Bharat) Limited,
Village-Yadwad, Taluka-Gokak,
District- Belgavi,
Karnataka-591 136

Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Yadwad & Kunnal Limestone Mine over an extent of 798.01 Ha. in Belgavi district, Karnataka State.

Sir,

The following provision of the Mineral Conservation and Development Rules, 2017 was found violated in your above mine during the inspection on **16/03/2018** by undersigned in presence of the mine officials Shri Mukesh Kumar Sinha, Mines Manager, Shri Sunil Kumar Sharma, Mining Engineer, Shri Raman Arunachalam, Geologist and other officials of the mines.

Rule No.	Nature of Violations observed
11(1)	<p>The mining operations are required to be carried out in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines (IBM).</p> <p>In the modified Mining Plan approved by IBM vide letter No. MMP/Mech-02/(KNT)/Goa/2017-18 dated 15.12.2017 under Chapter 3.0-Mine Drainage it was proposed during the year 2017-18 to construct two RR dry retention walls at the bottom of the topsoil stocks and dumps with dimensions of 565m x (1-2m) x 1 m and 360m x (1-2m) x 1 m. Although financial year 2017-18 is nearing completion, no progress has been observed for construction of aforesaid retention walls.</p>

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
03. The mining operations can be suspended under rule 11(2) if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully

(Dr. Y.G.KALE)
Regional Controller of Mines
Indian Bureau of Mines

Copy forwarded to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mines & Geology, Government of Karnataka, No.49, Khanija Bhavan, Race Course Road, Bangalore-560001.

(Dr. Y.G.KALE)
Regional Controller of Mines
Indian Bureau of Mines