## भारत सरकार /Government of India खान मंत्रालय/Ministry of Mines

## भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/Office of the Regional Controller of Mines

Phone No.: (0832)- 2741757 Opp.Old R.T.O.'s Office, Fax No. : (0832) -2741758 P.O. FATORDA - 403602,

E-Mail : <u>ro.goa@ibm.gov.in</u> Margao-GOA File No :GOA/Fe/179 Date:-25.1.2018

Mine Code:-30GOA01159

To,

Salitho Ores Pvt ltd., Salgaocar Bhavan, Altinho, Panji, Goa-403001.

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Purmar e Parvedat Iron Ore Mines (T.C.No-86/53), over an extent of 95.3850 Ha. Situated in Pale village, Tq- Bicholim, in North Goa District of Goa State. Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on12/01/2018, by the undersigned in presence of Shri Baburao Desai, Mines Manager.

Rule	Nature of Violation observed
11(1)	a) In the approved Modified Mining plan dated 4/1/2017, there was a proposal to drill 4 core boreholes to a total depth of 400 mtrs in the year 2017-18. During inspection it was observed that no such exploration was started so far by the lessee. b) In the approved document there was a proposal for plantation of 2000 plants in the year 2016-17 and 2000 in the year 2017-18, during inspection it was observed that no such plantation was done by the lessee.
27(1) & 27(2)	The differential financial assurance for the mining and allied activities as per MCDR 2017 is not paid for the entire area as shown in the PMCP chapter of approved Modified mining plan within 90 days from the commencement of MCDR 2017.
Rule 45(5)(c)	a) In the annual returns submitted for the year 2016-17 at para 2 (Production and Stocks of ROM ore at Mine-head) of part VI, Under dump workings about 8241709 tons is shown as opening and closing stack. Under dump working quantity of ore recovered from the dumps should be shown. However it has been shown total waste handling under dump working. Same mistake was made in previous returns also.

55(1)(3)(iii)	The Mining Engineer and Geologist required under the said rule are not
	appointed by the lessee.

02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.

## 03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,

(Kalmata.M.K) Senior Mining Geologist Indian Bureau of Mines

Copy forwarded to: -

- 1. The Controller of Mines, SZ, Indian Bureau of Mines, Bengaluru.
- 2. The Director, Directorate Mines and Geology, Govt.of Goa, Panaji.

(Kalmata.M.K) Senior Mining Geologist Indian Bureau of Mines