

भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो

क्षेत्रीय खान नियंत्रक का कार्यालय

कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग, सेक्टर-

10A गांधीनगर, गुजरात, 382010



Government of India

Ministry of Mines

Indian Bureau of Mines

Office of Regional Controller of Mines

Karmayogi Bhavan, 4th Floor, Block-2, Sector 10A,

Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

फाईल संख्या File No: GUJ/JMNG/BXT-28 Vol-I

Mine Code: 07GUJ107113

दिनांक 13 August 2021

सेवा में To : Owner/Agent/Manager/Mining Engineer
प्रेषित : M/s. SAURASHTRA CEMENT LIMITED,
Near Railway Station Ranavav 36056, Dist.-
Porbandar, Gujarat (India)

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Ran Bauxite Mine over an area of 32.37 ha located near Village-Ran, Tehsil-Kalyanpur, District-Devbhumi Dwarka in Gujarat.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the MCDR inspection made by the undersigned on 19.7.2021 in the presence of Sh. AR Panda, Lessee rep.

<u>RULE NO.</u>	<u>NATURE OF VIOLATION OBSERVED</u>
11(1)	The mining operations are not carried out as per approved Mining Plan vide letter No 684(4)(1)/MP-101/2018-GNR, dated 26/02/2018 for period 2018-19 to 2022-23 to the extent indicated below. <i>Exploration</i> -It was proposed to carried out 30 number of exploratory boreholes in 2018-19 as earmarked in plate No.4 but no such drilling work done & reported to this office till date.
26(2)	A yearly report before 1 st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan for 2019-20 has not been submitted cumulative to this office.
Rule 33	The owner, agent, mining engineer or manager of mine shall submit the digital copy along with a print copy of the Surface Geological plan & section on or before the 30th June of every year. In your case, you have not submitted the aforesaid updated plan & section maintained under rule 32 of MCDR, 2017 to this office till date.
45(7)	While scrutiny of annual return 2020-21, following discrepancies observed, which are furnished as below. Part-IIA, Capital structure, Part-III, Consumption of material, Part-V, Sr.No.5/6/8/9 Machinery detail are mentioned NIL information respectively. Which is not correct. Ex Mine price is decreasing in last six month needs to justify.
55(1)(3)	A full time Geologist has not been employed for the purpose of carrying out mining operations in accordance with these rules.

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

3. Mining operations can be suspended as per rule 11(2) in case of non-compliance of rule 11(1) and any other relevant rules of MCDR 2017 as these rules ensures systematic scientific and responsible mining and/or state Government may be informed to take actions as per competent directives.

4. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from date of issue of this letter for the rules 11(1), 26(2) and 33.

5. You are therefore directed to show cause within a period of thirty (30) days from the date of issue of this letter for the non-compliance of Rule 45(7), as to why you should not be prosecuted and / or penalty/fine etc. to be imposed and /or why the mining operation should not be suspended under relevant statutory provisions and/or why not any other appropriate action can be initiated in accordance with rules and/or any competent orders/directives. Please note that no further notice will be given to you in this regard for Rule 45(7)

6. This

भवदीय Yours faithfully,

(जी.राम/G.Ram)

वरिष्ठ सहायक खान नियंत्रक /Sr.Assistant Controller of Mines

NOO-प्रतिलिपि सूचनार्थ एंव आवश्यक कार्यवाई हेतु प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। (zo.udaipur@ibm.gov.in)
- 2- आयुक्त, भूविज्ञान एवं खनन ,निदेशालय , गुजरात को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित । (cgm@gujarat.gov.in)- *Further during inspection, lease boundary pillars were not available/erected & maintained as per statutes.*
- 3- DDG, MMS Division, भारतीय खान ब्यूरो, नागपुर
- 4- MCDR/गार्ड फाइल

वरिष्ठ सहायक खान नियंत्रक /Sr Assistant Controller of Mines