

भारत सरकार  
खान मंत्रालय  
भारतीय खान ब्यूरो  
क्षेत्रीय खान नियंत्रक का कार्यालय  
कर्मयोगी भवन, चतुर्थ माला, ब्लॉक-2, सी विंग, सेक्टर-10A  
गांधीनगर, गुजरात, 382010



Government of India  
Ministry of Mines  
Indian Bureau of Mines  
Office of Regional Controller of Mines  
Karmayogi Bhavan, 4<sup>th</sup> Floor, Block-2, Sector 10A,  
Gandhinagar, Gujarat-382010

Tel- 079 29750358 /29750359; ई-मेल/ E-mail: ro.gandhinagar@ibm.gov.in

फाईल संख्या File No: GUJ/JMNG/LST-43

Mine Code: 38GUJ07066

दिनांक 11 Aug 2021

सेवा में To: Owner/Agent/Manager/Mining Engineer

प्रेषित: Sh. Anvar Abbas Khira,  
'Legal Heir (sic)' of Abbas Dosmohammed Keara  
Near Railway Station Road, Post-Bhatia, Taluka-  
Kalyanpur, Devbhumi Dwarka-361315 Gujarat

विषय Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Bhatia Limestone Mine (907P) over an area of 49.38ha located near Village- Bhatia, Tehsil-Kalyanpur, District- Devbhumi Dwarka in Gujarat.

महोदय Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 (MCDR, 2017) were found violated in your above mine during the MCDR inspection made by the undersigned on 24.6.2021 in the presence of S/Sh. Molik Davra, QP & JD Dangar, lessee rep.

<u>RULE NO.</u>	<u>NATURE OF VIOLATION OBSERVED</u>
11(1)	<b><i>No holder of a mining lease shall commence or carry out mining operation in any area except in accordance with the approved mining plan, modified or reviewed by the Indian Bureau of Mines, whereas it is found that you have carried out mining operation without approved mining Plan/Review of Mining Plan etc... as follows. Exploitation-It was observed that lessee has been carried out mineral production (ROM) as reported in draft Review of Mining Plan submitted to this office, as follows-2009-10-151863.92T, 2010-11-108847.43T, 2011-12-55774.22T, 2012-13-300T, 2013-14-475T, 2014-15-125T, 2015-16-NIL, 2016-17-571.96T, 2017-18-90553.3T, 2018-19-72115.04T respectively.</i></b>
28(1)	The holder of a mining lease shall send to the authorized officer, as the case may be, and the State Government a notice in Form-E, when the mining & mineral processing operation in the mine or part thereof are dis-continued for a period exceeding ninety days so as to reach them within one hundred and twenty days from the date of such temporary discontinuance. In your case, you have not submitted discontinuance notice to IBM Gandhinagar office so far.
33	The owner, agent, mining engineer or manager of mine shall submit the digital copy along with a print copy of the Surface Geological plan & section on or before the 30th June of every year. In your case, you have not submitted the aforesaid updated plan & section maintained under rule 32 of MCDR, 2017 to this office till date.
45(7)	<b><i>While scrutiny of annual return 2020-21, following discrepancies observed, which are furnished as below. You have submitted the NIL/Incomplete information in Part-I to Part-IV which is not correct. It needs correction.</i></b>

2. In this connection, it is brought to your kind notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.
3. Mining operations can be suspended as per rule 11(2) in case of non-compliance of rule 11(1) and any other relevant rules of MCDR 2017 as these rules ensures systematic scientific and responsible mining and/or state Government may be informed to take actions as per competent directives.
4. Advise the State Government to order suspension of all mining operations in the mines as per provision of Rule 45(7), in case if it is found that the holder of a mining lease, has submitted incomplete or wrong or false information in statutory returns or fails to submit such return within the date specified under Rule 45.
5. You are advised to rectify the above violations immediately and intimate the compliance position to this office within 45 days from date of issue of this letter.

भवदीय Yours faithfully,

(जी०राम/G.Ram)

वरिष्ठ सहायक खान नियंत्रक /Sr.Assistant Controller of Mines

NOO-प्रतिलिपि सूचनार्थ एंव आवश्यक कार्यवाही हेतु प्रेषित :-

- 1- खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर। ([zo.udaipur@ibm.gov.in](mailto:zo.udaipur@ibm.gov.in))
- 2- आयुक्त, भूविज्ञान एंव खनन, निदेशालय, गुजरात को सूचनार्थ एंव आवश्यक कार्यवाही हेतु प्रेषित। ([cgm@gujarat.gov.in](mailto:cgm@gujarat.gov.in))- Further during inspection, lease boundary pillars were not available/erected & maintained as per statutes & workings appears outside lease area.
- 3- DDG, MMS Division, भारतीय खान ब्यूरो, नागपुर
- 4- MCDR/गार्ड फाइल

वरिष्ठ सहायक खान नियंत्रक /Sr Assistant Controller of Mines