

भारत सरकार /Government of India

खान मंत्रालय/ Ministry of Mines

भारतीय खान ब्यूरो/ Indian Bureau of Mines

क्षेत्रीय खान नियंत्रक का कार्यालय/ Office of the Regional Controller of Mines

Phone No.: (0832) - 2741757

Fax No. : (0832) -2741758

E-Mail : [ro.goa@ibm.gov.in](mailto:ro.goa@ibm.gov.in)

Opp. R.T.O.'s Office,

P.O. FATORDA - 403602,

Margao - GOA

**KNT/BJP/LST-95/GOA**

**38KAR26077**

**Dated: 27/06/2016**

To,

Smt.G.A.PATIL (Mine Owner),

M/s. Srinivas Mines & Minerals,

Kadarakoppa Road, Mudhol,

Bagalkot District,

Karnataka - 587 122.

**Sub: Violation of provisions of Mineral Conservation & Development Rules, 1988 in respect of Lokapur Limestone Mine (ML-2509) over an extent of 3.43 Hectares situated in Lokapur Village, Mudhol Taluk, Bagalkot District of Karnataka State.**

Sir,


The following provision of Mineral Conservation & Development Rules, 1988 was found violated during the inspection of your above mine on 05.06.2016 by the undersigned.

13 (1)	Mining operations in the lease area are not carried out as per the last approved Mining Scheme. The following deviation is observed during inspection, a) It was proposed in Para 5.0 & Plate-6 to produce Limestone above co-ordinates N-100. But, on the day of inspection, it was observed, that the no operation were carried out at proposed area and working was observed in existing old pit & un proposed area. b) As per para 6.0 there is an approved dumping proposal for stacking the waste material along the Western Side of the lease area as shown in plate no - 6. During inspection it was noticed that waste has not been dumped at the approved site. c) It is proposed in Para 5.0 to keep all the benches of height at 3m each, whereas in the field it is observed to be more than the proposed height. d) It is proposed in the undertaking to submit the DGPS plan within 180 days from the Mining scheme approval. But till now no plan has been submitted to this office. e) Plate-6 shows the area proposed for Crusher on the Western Side, but during inspection it has noticed that the explosive Magazine is constructed in the proposed area. f) Lr.No. KNT/BJP/LST-95/GOA dated 20/02/2015 has intimated to drill the Core borehole in the lease area, but till now no borehole has been drilled.
23(E)(2)	A yearly report before 1 <sup>st</sup> July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan has not been submitted.
27(4)	The Plans & Sections required under rule 28 have not been maintained up to date in every year.
42(1)(b)(ii)	The mine is being operated without employing the part time or full time Mining Geologist or Mining Engineer required under the provision this rule.
63	A Self-Appraisal Report to be submitted by owner of the mine under Rule 63 of MCDR, 1988 stating extent of implementation of Approved Mining Plan/ Scheme of Mining during the year 2014 - 2015 & 2015 - 2016 along with supporting plans & sections representative photographs in hard as well as soft copy.

366-  
Issued  
27/06/16

2. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 58 of MCDR, 1988.
3. The mining operations can be suspended under Rule 13(2), if compliance of rule 13(1) is not found satisfactory.
4. You are advised to rectify the violation immediately and intimate the position to this office with in a period of 45 (Forty Five) days from date of issue of this letter.

Yours faithfully,



27/6/11

(G.S.Kannan)

Junior Mining Geologist

Copy forwarded for information to: -

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, DMG, 49, Khanji Bhavan, Race Course Road, Bangalore- 560 001, Karnataka.
3. Mine File



27/6/11

(G.S.Kannan)

Junior Mining Geologist

367 ✓  
368 ✓