

भारत सरकार GOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0674-2352463; TeleFax: 0674-2352490; eMail: ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput BHUBANESWAR-751020

Date: 14.08.19

No. ORI/CR/JJP/MCDR-5/BBS/VOL-IV

Plot No. – 149, Pokhariput In front of CPWD office, Bhubaneswar - 751020

सेवा में.

Shri U K Sinha, Mine Agent, M/s Misrilall Mines Private Limited Mineral House 27A, Camac Street, Kolkata-700016

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Saruabil Chromite Mine over an area of 246.858 hectares in Jajpur district of Odisha State.

Sir,

The following provision of Mineral Conservation and Development Rules, 2017 was found violated in your above said mine during inspection on 30.07.2019 by the undersigned in presence of your mine official Shri S.S. Mishra,

Aines Mai	nager.			1 M. difference of Mining	Plan approved	vide Letter No.
Mining C	peration have not been	carried out in	accordance with t	he Modification of Mining	riaii appioved	vide Letter 110.
MPM/FM	1/06-ORI/BHU/2018-19	dated 18.05.20	18 to the extent in			
Rule No.	Proposal			Nature of Violation		
11(1)	It has been proposed in 2018-19 that three small nickel-ferrous dumps ND-A, ND-B & ND-E will be shifted to one large nickel ferrous dump namely ND-C & D.			It has been observed during inspection that shifting of three small nickel-ferrous dumps ND-A, ND-B & ND-E to one large nickel ferrous dump namely ND-C & D has not been done. It has been observed during inspection that shifting of ore		
	It has been proposed in 2018-19 to shift ore from ore stack yard no- 3, 4 & 5 and plantation to be done in the area after shifting of the ore			has not been done from stack yard 3 and 5. However, shifting of ore partly has been done from ore stack yard no.05 and partly the area has been planted with saplings.		
	Bench height and width has been proposed at 8m and 14 m respectively.			It has been observed during inspection that bench height and width has not been maintained in Quarry No-B at location between coordinates W500 to W600 & S700 to S600		
	Number of quarries proposed for production in 2018- 19 was three, namely quarry B, C & D			Number of quarries put for production in 2018-19 was two, namely quarry B & C. Quarry D was not put in operation.		
	It has been proposed in 2018-19 to construct five (05) no of settling tank of dimension (10m x 5m x 3m).			It has been observed during inspection that one no of settling tank of dimension (10m x 5m x 3m) has not been constructed.		
	It has been proposed in 2018-19 to construct retaining wall around Ore stack-2, Ore stack-3 and Nickel-ferrous dump (ND-C&D) of length 220m, 250m and 350m respectively.			Retaining wall has not been constructed around ore stack 2 & ore Stack-3 and partly of around 212m has been constructed around Nickel-ferrous dump (ND-C&D).		
	Plantation schedule			Plantation done		
	Location	Area (in ha)	No of saplings	Location	Area (in ha)	No of saplings
	ND-C & D	2.30	5750	ND-C & D	0.5	1152
	Ore stack yard 3,4 & 5	1.45	3625	Ore stack yard 5	0.5	505
	ND-A, B & E after shifting of nickel- ferrous material	0.524	1310	ND-A, B & E after shifting of nickel-ferrous material	Nil	Nil .
				Plantation has not been done as per proposal in the above locations.		
26 (2)	Rule Position: The submit to the compe	holder of mitent authority	ining lease shall a yearly report as	The yearly report on extent of protective and rehabilitation works carried out as envisaged in the		

per the format specified by the Indian Bureau of Mines, before 1st day of July every year setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan, and if there is any deviation, reasons thereof

approved mine closure plan for the year 2018-19 has not been submitted to the competent authority till date.

02 In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservation and Development Rules, 2017.

03. The mining operation can be suspended under Rule 11(2), if compliance of Rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (fortyfive) days from the date of issue of this letter.

> (SUDIP RANJAN MAZUMDAR) Senior Mining Geologist Indian Bureau of Mines

Copy forwarded to:

The Controller of Mines (EZ) / Indian Bureau of Mines / Kolkata.

2. The Director of Mines / Directorate of Mines / Government of Orissa / Heads of Department Building / New Capital / Bhubaneswar-751 001.

> (SUDIP RANJAN MAZUMDAR) Senior Mining Geologist Indian Bureau of Mines