



भारत सरकार  
GOVERNMENT OF INDIA  
खान मंत्रालय  
MINISTRY OF MINES  
भारतीय खान ब्यूरो  
INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय  
OFFICE OF REGIONAL CONTROLLER OF MINE



फैक्स: (080) 23371027 / 23373287  
दूरभाष: 080-23371027 / 23375366/67  
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,  
गोरगुंटापाल्या येशवंतपुर,  
बेंगलुरु -560022

सं/No.: KNT/TMK//MN/39/BNG

Mine-code: 12KAR19001

दिनांक/Dated: 05/08/2021

To,

**Shri N. Nagaraju**  
Working Partner,  
M/s Jayaram Minerals  
BH Road, Gubbi, Tumkur District – 572216  
E-mail: jminerals2248@gmail.com; anilraj147@gmail.com

**विषय/Subject: Violation of provisions of MCDR 2017 in respect of your Karekurchi Manganese Ore Mine (ML No. 2248) of M/s. Jayaram Minerals over an extent of 11.74Ha. in Karekurchi Village, Tiptur Taluk, Tumkur District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 30.07.2021 by undersigned in presence of Shri Nagaraju, Working Partner, Shri Puttaswamy, Mines Manager and Shri Shivaputra Mining Engineer

Rules	Nature of Violations observed
11(1)	The Mining operations required to be carried out in accordance as per the approved Review and Updation of the Mining Plan vide letter 279/569/97/BNG/1933 dated 06/10/2017. However, during the inspection deviations were observed in mining operation vis-à-vis approved document and is as follows: As per the approved Review and Updation of the Mining Plan vide letter 279/569/97/BNG/1933 dated 06/10/2017, Excavation/development of pit to be carried out by formation of regular benches of height 5-6m and width 5-6m. However, during the inspection, it is observed that the benches are not developed systematically as proposed. At western margin of the Manganese pit (Location E. 685542 N. 1476107 to E. 685550 N. 1476028), the bench height is more than 10m and width of benches less than its height and this resulted in pit slope failure (collapse of benches) at places thereby deviating from the approved proposal.

<b>26(2)</b>	Yearly report on PMCP setting forth the extent of protective and rehabilitative works carried out as per the approved Progressive mine closure plan, has not been submitted for the year 2020-2 as per the provision of this rule.
<b>35(2)</b>	The online self-assessment report of Star Rating template for the financial year 2020-21 have not yet been submitted as per the provision of this Rule.
<b>48</b>	FORM-J has not been prepared and maintained as per the provision of this rule.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

**(Dr. Sudhakara T.L.)**  
Senior Mining Geologist  
Indian Bureau of Mines

*Copy for kind information to:*

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

**(Dr. Sudhakara T.L.)**  
Senior Mining Geologist  
Indian Bureau of Mines