

मेल/त्वरितडाकद्वारा



भारतसरकार /GOVERNMENT OF INDIA
खानमंत्रालय/ MINISTRY OF MINES
भारतीयखानब्यूरो /INDIAN BUREAU OF MINES
क्षेत्रीयखाननियंत्रककार्यालय/ OFFICE OF THE REGIONAL
CONTROLLER OF MINES

फैक्स: (080) 23371027 / 23373287

29, इंडस्ट्रियलसबर्बIIस्टेज,,तुमकुरोड,

दूरभाष: 080-23371027 / 23375366/67

गोरगुंटापाल्यायेशवंतपुर,

Email ID: ro. bangalore@ibm.gov.in.

बेंगलुरु -560022

सं.KNT/BLR/FE/427/BNG

दिनांक:20.07.2021

सेवामें/To,

Dr. Meda Venkataiah

(Mine Agent, Executive Director – Mines)

Baldota Enclave, AHB Road Hospet,

Hospet, Karnataka-583203

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your Iyli Gurunath Iron Ore Mine (ML. No 2593, Mine code:30KAR3139) over an area of 20.23 Ha located in Jaisingpura village, Ramgad Range, Sandur Taluka, Ballari district of Karnataka State

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules 2017 were found violated in your above mine during the inspection carried out by the undersigned along with Shri. H M Shiva Kumar-Assistant Mining Engineer in presence of Shri. Sathyaprakash.M - Manager Mines & Mining Engineer & Sri V .V. N. Raju - Geologist on 23.06.2021

Rule	Nature of violations observed
11(1)	RMP along with PMCP was approved vide letter no.279/624/99/BNG dated 11.01.2019 for a period of 2019-20 to 2023-2024. The deviation observed in mining operation vis-a-vis approved document are given below: During the year 2020-21 backfilling was proposed in location N1676060 to 1676260 and E654929 to 655182. It was observed that 32,000 Tons of graded fines with 58% Fe was stacked in the western part of proposed area causing hindrance and blockage of area for backfilling.

26(1)	Retaining wall & garland drain of 30 Mts as proposed for the backfilled area were not constructed.
45 (7)	As per part VII, in the cost of production table, Royalty, DMF & NMET details have not been furnished to arrive at the total cost of production.
47	As per Form I submitted to this office 11 bore holes had been proposed where as 12 bore holes were drilled. Revised Form I may be submitted to this office

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017. Further, the violation of Rule 11(1) may also attract provisions of Rule 11(2) of MCDR, 2017 regarding suspension of mining operations till the compliance of violations.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुण कुमार)/Arun Kumar

उप खान नियंत्रक/Dy. Controller of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines

प्रतिलिपि सूचनार्थ' /Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhan, R.C. Road, Bangalore-560 001

Sd/-

उप खान नियंत्रक/Dy. Controller of Mines
भारतीय खान ब्यूरो/Indian Bureau of Mines