INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR inspection REPORT

Kolkata regional office

	Mine :	file No : CAL/JHK/SB(V	N)/	FE(M-2) Mine code : 30JHK18003
	(i)	Name of the Inspecting Officer and ID No.	:	KQ04) B.P KERKETTA
	(ii)	Designation	:	Sr. Asst. Contrl. Mines
	(iii)	Accompaning mine Official with Designation	:	Sri Ravi Ranjan, Mines Manager, Sri S.S.Rao, AMIE,Min
	(iv)	Date of Inspection	:	13/03/2020
	(v)	Prev.inspection date	:	07/03/2015
		РА	RT-	I : GENERAL INFORMATION
1.	(a)	Mine Name	:	MANOHARPUR (SUKRI)
	(b)	Registration NO.	:	
	(c) (d) (e) (f) (g) (h)	Category Type of Working Postal address State District Village Taluka Post office Pin Code FAX No. E-mail Phone Police Station First opening date Weekly day of rest		833106 06593-263714 rmdsail@gmail.com 06593-287674 MANOHARPUR 01/01/1911 SUN
2.		ess for espondance	:	STEEL AUTHORITY OF INDIA LTD MANOHARPUR ORE MINES, P.O.CHIRIA, SINGHBHUM(W), JHARKHAND-833106
3.	(d)	Lease Number Lease area Period of lease Date of Expiry	:	BHR0059 38.85 30 31/08/1979
4.	Miner	ral worked	:	IRON ORE Main

5. Name and Address of	tho		
Lessee	:	STEEL AUTHORITY OF INDIA LTD.	
		INDUSTRY HOUSE 5TH & 6TH	
		FLOOR 10, CAMAC STREET	
		KOLKATA WEST BENGAL	
		Phone:033-22822316/0462/3385	
		FAX :033-22822316/0462	
Owner	:	Harinand Rai	
		Steel Authority of India	
		Ltd. Ispat Bhawan, Lodi road New Delhi-110003	
		SINGHBHUM (WEST) JHARKHAND	
		Phone: 011-24367481-86	
		FAX : 011-24367015	
Agent	:	R.P.SINGH	
		MANOHARPUR(Mc LELLAN)IRON	
		ORE MINE	
		P.O.CHIRIA,DIST.WEST SINGHBHUM JHARKHAND STATE	
		SINGHBHUM (WEST) JHARKHAND	
		Phone: 8986881005	
		FAX :	
Mining Enginee	er		
Name	:	S S RAO,Full Time	
Qualification	:	AMIE(MIN)	
= =		04/02/2018	
Termination da	ite		
Geologist			
Name	:	RAJESH KUMAR NAIK,Full Time	
Qualification	:	M.Phil,PhD (Geo)	
Appointment/ Termination da		14/11/2014	
Manager			
Name	:	RAVI RANJAN	
Qualification	:	B.TECH (MINING)	
	:	18/09/2019	
Termination da	ite		
6. Date of approval of Plan/Scheme of Minin		Renewal under rule 24 MCR1960 06	/05/2006 /02/2009 /01/2019

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
la	Backlog of previous year	20nos	Nil	Not working since 21stMarch 2009, for want of Stage II Forest Clearance. Therefore, exploration proposed, could not be done.
1b	Exploration over lease area for geological axis 1 or 2		Nil	Not working since 21stMarch 2009, for want of Stage II Forest Clearance. Therefore, exploration proposed, could not be done.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	M/s. MECL 5.20 Crores	Nil	-do-
1d	Balance area to be explored to bring Geological axis in 1 or 2	16ha	Nil	-do-
le	Balance reserve as on 01/04/20	As on 01/04/2019:- Probable Reserve (121) 3.79million Te Probable Reserve (122) 4.86million Te	Probable Reserve (121) 3.79million Te Probable Reserve (122) 4.86million Te	-do-
lf	General remarks of inspecting officers on geology, exploration etc		Not working since 21stMarch 2009, for want of Stage II Forest Clearance. Therefore, exploration proposed, could not be done.	
Deve	elopment :			
Sl.No.	Item	Propasals	Actual work	Remarks

2a	Location of development w.r.t.lease area	From 656,662,668,67 4,680,686 mRL Benches	Nil	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	Separate benches in top soil, overburden and mineral proposed.	Nil	-do-
2c	Stripping ratio or ore to OB ratio	1:0.11	Nil	-do-
2d	Quantity of topsoil generation in m3	NA	Nil	-do-
2e	Quantity of overburden generation in m3	80811cum.	Nil	-do-
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc		This mine is not working since 21stMarch 2009, for want of Stage II Forest Clearance.Therefore,mine development could not be done .	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	1	Nil	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.
3b	Quantity of ROM mineral production proposed	749950MT	Nil	-do-
3с	Recovery of sailable/usable mineral from ROM production	674231MT	Nil	-do-
3d	Quantity of mineral reject generation	Nil	Nil	-do-
3e	Grade of mineral rejects generation and threshold value declared.	Nil	Nil	-do-

3f	Quantity of sub grade mineral generation.	94649MT	Nil	-do-
3g	Grade of sub grade mineral generation	45-55% Fe	Nil	-do-
3h	Manual / Mechanised method adopted for segregating from ROM	Mechanised	No work	-do-
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	Proposed to carry out beneficiation study centrally for utilisation of Subgrade Ore.	nil	-do-
3j	Provision of drilling and blasting in mineral benches	Wet drilling and Use of dealy detonators	nil	-do-
3k	Provision of mining machineries in mineral benches	Hydraulic excavators (Back Hoe) 3nos.,Front End Loaders 3nos,Dumpers 10/16 tonne capacity ,80nos, Drills IR260 3nos. Dozers 1no.,Water Tanker 12KL,2nos. Jackhammer drills 2nos.,Air Compressors 450cfm 3nos.	nil	-do-
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	6mts	6m	-do-
3m	Total area covered under excavation/pits	7.48ha.	7.48ha.	Not working
3n	Ore to OB ratio for the pit/mine during the year.	1:0.11	Nil	-do-

30	Total area put in use under different heads at the end of year	7.48ha.,Waste Dump 0.6ha.,	Excavated area 7.48ha.,Waste Dump 0.6ha., Subgrade ore Dump/Fines Dump 1.61ha.,Infrastructure 0.12ha.,Roads 1ha.	Not working
3р	Production of ROM mineral during the last five year period as applicable		Year Production 2014-15 0 2015-16 0 2016-17 0 2017-18 0 2018-19 0	-do-
3q	General remarks of inspecting officers on method of mining etc.		Production of Iron Ore could not be done as mine was not working since 21st March 2009, for want of Stage II Forest Clearance.	

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	Separate dumping of top soil,OB and mineral reject.	Nil	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.
4b	Location of topsoil, OB and mineral reject dumps	part of the Main	On the eastern part of the Main Quarry.One subgrade dump on the NNW of Broken area.	-do-
4c	Number of dumps within lease area and outside of lease area	1	1	Not working
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Out side the pit	Out side the pit	Not working
4e	Number of active and alive dumps.	1	nil	-do-

4f	Number of dead dumps.	nil	1	-do-
4g	Number of dumps established.	1	1	-do-
4h	Whether Retaining wall or garland drain all along dumps are there.	or garland drain all	Retaining wall or garland drain all along dumps .	-do-
4i	Length of Retaining wall or garland drain all along dumps	500m	Nil	-do-
4j	Number of settling ponds	1	1	-do-
4k	Specific comments of inspecting officer on waste dump management		Mine not working since 21st March 2009, for want of Stage II Forest Clearance. Therefore, Solid waste management (dumping)could not be done as per approved Modified Mining Plan.	

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal	nil	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.
5b	Area under backfilling of mined out area	No proposal	Not Applicable	-do-
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Use in plantation	nil	-do-
5d	Total area fully reclaimed and rehabilitated	No proposal	Not Applicable	-do-

5e General remarks of inspecting officers on backfilling and reclamation etc.

Mine was not working since 21st March 2009,for want of Stage II Forest Clearance. There is no proposal for reclamation or rehabilitation of any part of the mine and waste dump during the next five years.

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
ба	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	Yes	Yes	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.
6b	Area available for rehabilitation (ha) .	Nil	Not Applicable	-do-
бс	afforestation done (ha).	0.lha	0.1ha	-do-
6d	No. of saplings planted during the year	500	100(Outside Mining Lease)	-do-
бе	Cumulative no .of plants	N.A.	2500(WML)+ 15580 (OML)	-do-
6f	Any other method of rehabilitation	No	N.A.	-do-
бд	Cost incurred on watch and care during the year	Not Specific.	Nil	-do-
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	NA	NA	-do-
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	NA	Nil	-do-

6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	NA	NA	-do-
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	NA	NA	-do-
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	NA	NA	-do-
бm	Compliance of rehabilitation of waste land within lease (i)afforestation	NA	NA	-do-
бn	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	NA	NA	-do-
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	NA	NA	-do-
бр	Compliance of environmental monitoring (core zone and buffer zone)	Yes, Air -3 stations per quarter Water - 4 stations per quarter Noise - 5 stations per quarter	Yes, Air -3 stations per quarter Water - 4 stations per quarter Noise - 5 stations per quarter	-do-

бq	General remarks	Not working since	Not working since	
	of inspecting	21stMarch 2009, for want	21stMarch 2009,	
	officers on PMCP	of Stage II Forest	for want of Stage	
	compliance and progressive closure operations etc.	Clearance.Therefore,	II Forest Clearance.	

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	Average 62.5 % Fe	Nil	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Not specific	Nil	-do-
7c	Different grade of mineral sorted out at mines.	Sub grade fines + 59% Fe will be blended with blue dust ore having 64% Fe%	Nil	-do-
7d	Any beneficiation process at mines	No beneficiation except crushing aand screening.	Nil	-do-
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues		Not working since 21stMarch 2009, for want of Stage II Forest Clearance.	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	No proposal	Nil	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.

8b	Concurrent use or storage of topsoil	For plantation	Nil	-do-
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	2	2	-do-
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No proposal	Nil	-do-
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No proposal	Nil	-do-
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	No proposal	Nil	-do-
8g	Survival rate	No proposal	60%	-do-
8h	Water sprinkling on roads to control airborne dust	Proposed.	Nil	-do-
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area		Mine was not working since 21st March 2009, for want of Stage II Forest Clearance. The aesthetic beauty in and around mines area is good.	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks

9a Status of M.R. Submitted M.R. Submitted up to Not working since submission of February, 2019 21stMarch 2009, up to Monthly and February, 2019 A.R. submitted up to for want of Stage Annual returns 2018-19 II Forest A.R. submitted up Clearance. to 2018-19 9b Scrutiny of Sri S.S.Rao, Sri S.S.Rao, Mining Not working since Annual return Mining Engineer & Sri 21stMarch 2009, for information Engineer & Sri R.K.Naik, Geologist were for want of Stage on Mining R.K.Naik, Geolo present during II Forest Engineer, gist inspection. Clearance. Geologist and Manager 9c Scrutiny of Current O/C Excavated Area-7.48ha. The area given for Annual return on Mining Area-Waste Dumps-0.6ha. other purpose land use pattern 7.48ha. Sub-Grade Ore Dump/ Fine (Sorting & sizing Waste Dumpsdump-1.61ha. for area under of ore, subgrade pits, reclaimed Infrastructure-0.12ha. 0.6ha. ,afforestation)see area, dumps etc. Plant, Roads-1.00ha ms to be on higher building, resid side. ential, welfare building-1.12ha., Other purpose(Sorting & sizing of ore, subgrade ,afforestation)24.02ha. 9d Scrutiny of 100nos Outside Found correct. Not working since Annual return on Mining 21stMarch 2009, afforestation Lease, survival for want of Stage rate 60% II Forest Clearance. 9e Scrutiny of Nil Nil Not working since Annual return on 21stMarch 2009, mineral reject for want of Stage generation II Forest (Grade and Clearance. quantity)

9£	Scrutiny of Annual return on ROM stock and/or graded ore	closing Stock		Not working since 21stMarch 2009, for want of Stage II Forest Clearance.
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Nil	Found Correct.	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.
9h	Scrutiny of Annual return on fixed assets		It appears on higher side.	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.
9k	Scrutiny of Annual return on mining machineries	Dozer 320HP 1no.	Found Correct.	Not working since 21stMarch 2009, for want of Stage II Forest Clearance.

Details of violations observed during current inspection and compliance position of violation pointed out						
Violation observed				Show couse position		
Rule NO.	Issued on	Compliance	on	Rule NO.	Issued on Compliance on	

Date :

(B.P KERKETTA)

Indian Bureau of Mines