VIOLATION LETTER

संख्या

एचपी / एसआरएम / एलएसटी-27

Mine Code 38HPR10029

रजिस्टर्ड ए० डी० 100-ओल्ड नेहरू कालोनी, देहरादून,(उत्तराखण्ड),

दिनांक : 27.10.2015

सेवा में :

श्री सोहन सिंह मीत सिंह, गांव एवं पो०ऑ०-कामरू तहसील – पांवटा साहिब, जिला-सिरमौर (हि०प्र०)

विषय

Violation of provisions of Mineral Conservation & Development Rules, 1988 in respect Of your Bhimgoda Limestone Mine in Sirmour District of Himachal Pradesh State

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 1988 were found violated in your above mine during the inspection made on 08.09.2015 by the undersigned in presence of Shri Kuldeep

D. i. a.s.	Nature of violation observed in Made on 08.09.2015 by the undersigned in presence of Shri Kuldeep
Rule No.	Nature of violation observed in detail
13(1)	The minimum observed in detail
	The mining operations are carried out in violeties Co.
	The mining operations are carried out in violation of following provisions of approved Scheme of Mining (Approved on 11-12-2013): - 1) In Para 5.0 it was proposed to decide the second of the secon
	1) In Para 5.0 it was proposed to develop mine by forming benches each of 6m in height with width and irregular faces have been developed.
	more than the height whereas at some places the height of the benches more than 10m with width and irregular faces have been developed. 2) In Para 4.0 of PMCP during the year (2014) 150, 75
	and irregular faces have a some places the height of the bench.
	2) In Para 4.0 of PMCP to been developed.
	but no such retain.
. 45(5) (a)	2) In Para 4.0 of PMCP during the year (2014-15) 75m retaining wall was proposed around the dump Monthly returns for month of June 2015 have
02. In th	Monthly returns for month of June 2015 has not been submitted to the correction of the dump

Monthly returns for month of June 2015 has not been submitted to this office.

In this connection, it is brought to your notice that the above violations constitute an offence punishable under 02. Rule 58 of MCDR, 1988. 03.

The mining operation can be suspended under rule 13(2) of MCDR 1988 if compliance of rule 13(1) of MCDR

You are advised to rectify the above violations immediately and intimate the position to this office on letter pad 04. signed by the owner within 45 (forty-five) days from the date of issue of this letter.

(डी०आर० गूर्जर

सहायक खान नियंत्रक भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ-

खान नियंत्रक (उ०), भारतीय खान ब्यूरो, अजमेर।

निदेशक, उद्योग विभाग, उद्योग भवन, हि०प्र०सरकार, शिमला ।

अधीक्षण खनिज अर्थशास्त्री, खनिज सांख्यकीय प्रभाग, भारतीय खान ब्यूरो, नागपुर

भारतीर

भारतीय खान ब्यूरो