भारत सरकार खान मंत्रालय भारतीय खान ब्यूरो क्षेत्रीय खान नियंत्रक का कार्यालय

VIOLATION LETTER रजिस्टर्ड ए० डी०

संख्या :

एचपी / एसआरएम / एलएसटी-35

Mine Code: 38HPR10030

100—ओल्ड नेहरू कालोनी, देहरादून,(उत्तराखण्ड),

सेवा में :

श्री वीं कें वालिया ग्राम व पोस्ट – ददाहू तहसील– रेनुका, जिला– सिरमौर (हिं प्र0) दिनांक : 02.03.2016

विषय

Violation of provisions of Mineral Conservation & Development Rules, 1988 in respect of your

Bhotmari Limestone Mine in Sirmour District of Himachal Pradesh state.

महोदय,

The following provisions of the Mineral Conservation and Development Rules, 1988 were found violated in your above mine during the inspection made on 15.02.2016 by the undersigned in presence of Shri D.K. Sinha, Mine Manager

Rule No.	Nature of violation observed in detail
13(1):	The mining operations are carried out in violation of following provisions of approved Modified Mining Mining (approved on 07/09/2012): -
	(i) In Chapter 7.0 During the year 2015-16 it was proposed that 88m retaining wall & 88m water drain along inter burden shall be constructed but no such work has been carried out.
25	The owner, agent, mining engineer or manager of every mine shall send to Controller General, Controller of mines and the Regional Controller of mines an intimation in Form C of reopening of a mine after temporary discontinuance, so as to reach then within fifteen date from the such reopening. But you have not sent such intimation in Form C after reopening of your mine.

- 02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of MCDR, 1988.
- 03. The mining operation can be suspended under rule 13(2) of MCDR 1988 if compliance of rule 13(1) of MCDR 1988 is not found satisfactory.
- O4. You are advised to rectify the above violations immediately and intimate the position to this office on letter pad signed by the owner within 45 (forty-five) days from the date of issue of this letter.

Olc

प्रतिलिपि सूचनार्थ-

1. खान नियंत्रक (उ०), भारतीय खान ब्यूरो, अजमेर।

2. निदेशक, उद्योग विभाग, उद्योग भवन, हि०प्र०सरकार, शिमला ।

010

भारतीय खान ब्यूरो

सहायक खान नियंत्रक

सहायक खान नियंत्रक भारतीय खान ब्यूरो

तिवारी cll D:\desktop dated 01-07-2014\DRG\Hindi VL\Hindi VL DRG 15 feb 2016 and 16 feb 2016\VL 1516 Bhotmari_VKW.doc