INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR INSPECTION REPORT

Ajmer regional office

Mine file No : RAJ/BLW-220/GT-13 Mine code : 26RAJ06016

(i)Name of the Inspecting : $\mathbf{G} \bigcirc \mathbf{21}$) \mathbf{D} \mathbf{R} $\mathbf{G} \mathbf{U} \mathbf{R} \mathbf{J} \mathbf{A} \mathbf{R}$

Officer and ID No.

(ii) Designation : Sr. Asst. Contrl. Mines

(iii) Accompaning mine : Shri Anil Kumar Dasot, Partner of AKG Gem Garnet Mine

Official with

Designation

(iv) Date of Inspection : 04-DEC-19 Prev.inspection date : 11-MAR-17 (v)

PART-I : GENERAL INFORMATION

(a) Mine Name : KODUKOTA

(b) Registration NO. : IBM/6648/2011

(C) Category : B Manual (d) Type of Working Opencast

(e) Postal address

> State : RAJASTHAN District BHILWARA Village KODUKOTA Taluka SUWANA Post office : KODUKOTA Pin Code : 311001

FAX No. : 01482-251109

E-mail : anildasot12@yahoo.com

01482-270057, 242845, 9414: Phone

: BHILWARA (f) Police Station First opening date : 21-MAY-01 (g)

Weekly day of rest (h) : SUN

Address for : 5, SURANA BHAVAN,

correspondance SHASTRI NAGAR, BHILWARA

3. (a) Lease Number : RAJ1956 (b) Lease area : 4.27 Period of lease : 20 (C)

> (d) Date of Expiry : 13-MAY-21

Mineral worked 4. : GARNET Main 5. Name and Address of the

Lessee : AKD GEM GARNET MINES

F-203

NEAR MAHAPRAGYA CIRCLE, AZAD NAGAR, BHILWARA BHILWARA RAJASTHAN

Phone: 01482-242845,9414115557

FAX :

Owner : AKD GEM GARNET MINES

F-203

N, NEAR MAHAPRAGYA CIRCLE,

AZAD NAGAR BHILWARA BHILWARA RAJASTHAN Phone: 01482-242845(0)

FAX :

Manager

Name : Mahaveer Das Bairagi

Qualification : Forman's Certificate Holder

Appointment/ : 01-DEC-19

Termination date

6. Date of approval of Mining : Fresh under rule 22 MCR1960 09-JAN-01 Plan/Scheme of Mining Mining Scheme rule 12 MCDR1988 28-JUL-06 FMCP under 23C(1) 29-JAN-08 Modif.of approved Mining Plan 16-AUG-10 MP modif under MCR 1960 04-APR-16

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	During the previous year 2018-19 no exploration was proposed.	No exploratory work has been carried out during the last year.	During the last Modified Mining Plan period in the year 2016 & 2017 total 05 trenches were proposed but only two exploratory trial pits were dug hence violation of Rule 11(1) of MCDF 2017 issued to the lessee.
1b	Exploration over lease area for geological axis 1 or 2	During the previous year 2018-19 no exploration was proposed.	No exploratory work has been carried out during the last year.	During the last Modified Mining Plan period in the year 2016 & 2017 total 05 trenches were proposed but only two exploratory trial pits were dug hence violation of Rule 11(1) of MCDR 2017 issued to the lessee.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	No such proposal given in the approved Scheme of Mining.	During the last Modified Mining Plan period Rs. 15000 has been spent in the exploratory pits.	Nil
1d	Balance area to be explored to bring Geological axis in 1 or 2	No such proposal given in the earlier approved Modified Mining Plan.	Only 2 exploratory trail pits were dug during the last modified mining plan period.	

1e	Balance reserve as on 01/04/20	Resreve as on 01.01.2020 111-ROM 753405 T (113011T Abrasive & Gem garnet 15% of ROM) 121/122-ROM 171132 T (25670 T Abrasive & Gem garnet 15% of ROM)	Resreve as on 01.01.2020 111-ROM 753405 T (113011T Abrasive & Gem garnet 15% of ROM) 121/122-ROM 171132 T (25670 T Abrasive & Gem garnet 15% of ROM)	As per approved Review of Mining Plan(Approved on 20.01.2020)
1f	General remarks of inspecting officers on geology, exploration etc			During the last Modified Mining Plan period in the year 2016 & 2017 total 05 trenches were proposed but only two exploratory trial pits were dug hence violation of Rule 11(1) of MCDR 2017 issued to the lessee.

Development :

Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	Mine development was proposed in existing old pit along the boundary pillar AD.	Mine development has been carried out on proposed location, however bench height & width have not been maintained as per approved proposal.	Bench height & width have not been maintained as per approved proposal hence violation of Rule 11(1) of MCDR 2017 issued to the lessee.
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	Yes	Yes	However bench height & width have not been maintained as per approved proposal hence violation of Rule 11(1) of MCDR 2017 issued to the lessee.
2c	Stripping ratio or ore to OB ratio	1:9	1:9.25	Nil

2d	Quantity of topsoil generation in m3	No top soil generation proposal during the last year.	No to soil generated during the last year.	Nil
2e	Quantity of overburden generation in m3	2018-19 29820 T	2018-19 27002 T	Nil
2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc			Mine development has been carried out on proposed location, however bench height & width have not been maintained as per approved proposal hence violation of Rule 11(1) of MCDR 2017 issued to the lessee.

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	One	One	Nil
3b	Quantity of ROM mineral production proposed	2018-19: ROM- 33133 T	2018-19: ROM- 29820 T & Production of Mineral- 2918T	Nil
3c	Recovery of sailable/usable mineral from ROM production	2018-19 3313T	2018-19 2918T	Nil
3d	Quantity of mineral reject generation	No proposal	Nil	Nil
3e	Grade of mineral rejects generation and threshold value declared.	No proposal	Not applicable	NII
3f	Quantity of sub grade mineral generation.	No subgrade mineral generation proposal	No subgrade mineral generated during the last year.	Nil
3g	Grade of sub grade mineral generation	No subgrade mineral generation proposal	No subgrade mineral generated hence not applicable.	Nil

3h	Manual / Mechanised method adopted for segregating from ROM	No proposal of segregation.	None	Nil
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	No such proposal given	None	Nil
3j	Provision of drilling and blasting in mineral benches	Drilling by Jack hammer & blasting was proposed.	As per proposal	Nil
3k	Provision of mining machineries in mineral benches	Manual mining proposed & transportation by truck	As per proposal	Nil
31	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	Yes	Bench height & width have not been maintained as per approved proposal hence violation of Rule 11(1) of MCDR 2017 issued to the lessee.	Bench height & width have not been maintained as per approved proposal hence violation of Rule 11(1) of MCDR 2017 issued to the lessee.
3m	Total area covered under excavation/pits	At the end of modified mining plan period i.e. 2019-20 area will be covered under pits- 1.05 Hect.	As per recently approved review of mining plan the current area under pit is 0.4161 hect.	Nil
3n	Ore to OB ratio for the pit/mine during the year.	1:9	1:9.25	Nil
30	Total area put in use under different heads at the end of year	In the approved modified mining plan the total area put to use at the end of year 2019-20 under different heads will be 1.819 hect.	Currently total area put to use under different heads is 1.0361	Nil

Production of 2015-16: 19421 2015-16: 6525 T Nil 3р ROM mineral 2016-17: 13154 T, during the last 2016-17: 21079 2017-18: 31337.33 T, five year period T, 2018-19: 27002 T, 2017-18: 29470 2019-20: 4142 T(Up to as applicable Dec 2019) 2018-19: 29820 2019-20: 37463 General remarks Method of mining 3q of inspecting is suitable to the type of deposit. officers on method of mining etc.

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	Proposal given for separate dumping of OB/IB	Separate dumping of OB/IB has been carried out.	Nil
4b	Location of topsoil, OB and mineral reject dumps		Waste dumping has been carried out North Eastern part of the lease area.	Nil
4c	Number of dumps within lease area and outside of lease area	One	One	
4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	Outside of UPL	Outside of UPL	Nil
4e	Number of active and alive dumps.	01	01	Nil
4f	Number of dead dumps.	Nil	NIl	Nil
4g	Number of dumps established.	No proposal	Nil	Nil
4h	Whether Retaining wall or garland drain all along dumps are there.	No specific proposal has been given in the approved modified mining plan for the year 2018-19.	Garland drain was observed.	Nil

4i	Length of Retaining wall or garland drain all along dumps		No garland drain reported during the last year.	Nil
4j	Number of settling ponds	No proposal	Nil	Nil
4k	Specific comments of inspecting officer on waste dump management			No issue was observed related to waste dump management.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual	work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	No proposal of backfilling was given for the year 2018- 19	Nil		Area is not matured for backfilling.
5b	Area under backfilling of mined out area	No proposal of backfilling was given for the year 2018- 19	None		Nil
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	No top soil generation proposed duirng the year 2018-19		soil generated the last year.	Nil
5d	Total area fully reclaimed and rehabilitated	No proposal given for the year 2018-19.	None		Nil
5e	General remarks of inspecting officers on backfilling and reclamation etc.				Area is not fully matured for backfilling & reclamation.
	Progressive Mine (Clousre Plan:			
Sl.No.	Item	Propasals	Actual	work	Remarks

6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	PMCP report of every year should be submitted up to 1st July .	PMCP report for the year 2018-19 has not submitted by the lessee.	Violation of Rule 26(2) of MCDR 2017 issued to the lessee for non submission of PMCP report for the year 2018-19.
6b	Area available for rehabilitation (ha) .	0.02 hect.	Not reported	Violation of Rule 26(2) of MCDR 2017 issued to the lessee for non submission of PMCP report for the year 2018-19.
6c	afforestation done (ha).	.02 hect.	Not reported	Violation of Rule 26(2) of MCDR 2017 issued to the lessee for non submission of PMCP report for the year 2018-19.
6d	No. of saplings planted during the year	50 nos.	20 nos.	Violation of rule 11(1) of MCDR 2017 issued to the lessee for less plantation from approved proposal.
6e	Cumulative no .of plants	Not specified	Not reported	Violation of Rule 26(2) of MCDR 2017 issued to the lessee for non submission of PMCP report for the year 2018-19.
6f	Any other method of rehabilitation	No proposal	None	Nil
6g	Cost incurred on watch and care during the year	Rs. 2500	Not reported	Violation of Rule 26(2) of MCDR 2017 issued to the lessee for non submission of PMCP report for the year 2018-19.
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	No such proposal given in the approved modified mining plan.	Not reported	Violation of Rule 26(2) of MCDR 2017 issued to the lessee for non submission of PMCP report for the year 2018-19.

6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	No backfilling proposal during the year 2018-19	No backfilling has larried out duirng last year.		Nil
6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestati on on backfilled area	No proposal of afforestation on backfilled area.	None		Nil
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	No such proposal given	Rain water was accumulated at the pottom.	pit	Nil
61	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	No proposal given	None		Nil
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	50 nos.(2018- 19)	20 nos. (2018-19)		Violation of rule 11(1) of MCDR 2017 issued to the lessee for less plantation from approved proposal.
бn	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	0.02 hect. by plantation	Not reported		Violation of Rule 26(2) of MCDR 2017 issued to the lessee for non submission of PMCP report for the year 2018-19.
60	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	Plantation	Plantation		Nil
бр	Compliance of environmental monitoring (core zone and buffer zone)		Regular monitoring being carried out.	is	Nil

6q General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.

Violation of Rule 26(2) of MCDR 2017 issued to the lessee for non submission of PMCP report for the year 2018-19.

Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
7a	ROM Mineral dispatch or grade-wise sorting within lease area	sorting from ROM	Usable mineral sorting from ROM exacavation.	Nil
7b	Method of grade- wise mineral sorting i.e. manual or mechanical.	Manual	Manual	Nil
7c	Different grade of mineral sorted out at mines.	Abrasive granet sorted from ROM exacavation.	Abrasive granet sorted from ROM exacavation.	
7d	Any beneficiation process at mines .	No proposal	None	Nil
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues			No issue was observed related to mineral coservation.

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	geneartion	No top soil generated	Nil
8b	Concurrent use or storage of topsoil	No top soil generation proposal given	Not generated.	Nil

8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	Separate dumping of OB/IB proposed		Nil
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	No such proposal given for the last year	None	Nil
8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	No such proposal given for the year 2018-19	None	Nil
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	During the year 2018-19 total 50 nos. plantation was proposed.	planted during the year 2018-19.	Violation of rule 11(1) of MCDR 2017 issued to the lessee for less plantation from approved proposal.
8g	Survival rate	Not specified	Not reported	Violation of Rule 26(2) of MCDR 2017 issued to the lessee for non submission of PMCP report for the year 2018-19.
8h	Water sprinkling on roads to control airborne dust		As per proposal	Nil
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area			Aesthetic beauty is good in and around mine area except land degraded by pit & waste dump.
Compliance of Rule 45:				

Actual work

Remarks

Sl.No.

Item

Propasals

9a	Status of submission of Monthly and Annual returns	Monthly return submitted up to Dec 2019 Annual return 2018-19 not submitted.	Monthly return submitted up to Dec 2019 Annual return 2018-19 not submitted.	Violation of rule 45(5)(C) of MCDR 2017 issued to the lessee for non submission of anuual return for the year 2018-19.
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Annual return for the year 2018-19 not submitted by the lessee.	Due to non submission of annual return 2018-19, Violation of rule 45(5)(C) of MCDR 2017 issued to the lessee.	
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	-		
9d	Scrutiny of Annual return on afforestation	Annual return for the year 2018-19 not submitted by the lessee.	Due to non submission of annual return 2018-19, Violation of rule 45(5)(C) of MCDR 2017 issued to the lessee.	
9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Annual return for the year 2018-19 not submitted by the lessee.	Due to non submission of annual return 2018-19, Violation of rule 45(5)(C) of MCDR 2017 issued to the lessee.	
9f	Scrutiny of Annual return on ROM stock and/or graded ore	_	Due to non submission of annual return 2018-19, Violation of rule 45(5)(C) of MCDR 2017 issued to the lessee.	
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Annual return for the year 2018-19 not submitted by the lessee.	Due to non submission of annual return 2018-19, Violation of rule 45(5)(C) of MCDR 2017 issued to the lessee.	
9h	Scrutiny of Annual return on fixed assets	Annual return for the year 2018-19 not submitted by the lessee.	Due to non submission of annual return 2018-19, Violation of rule 45(5)(C) of MCDR 2017 issued to the lessee.	
9k	Scrutiny of Annual return on mining machineries	Annual return for the year 2018-19 not submitted by the lessee.	Due to non submission of annual return 2018-19, Violation of rule 45(5)(C) of MCDR 2017 issued to the lessee.	

Details of violations observed during current inspection and compliance position of violation pointed out

	Violation	observed		Show co	ouse position
Rule 1	NO.	Issued on	Compliance on	Rule NO.	Issued on Compliance on
MCDR17	Rule 11(1)	31-DEC-19			
MCDR17	Rule 26(2)	31-DEC-19			
MCDR17	Rule 45(5)(c 31-DEC-19			

Date: (D R GURJAR)

Indian Bureau of Mines