



भारत सरकार  
GOVERNMENT OF INDIA  
खान मंत्रालय  
MINISTRY OF MINES  
भारतीय खान ब्यूरो  
INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय  
OFFICE OF REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499  
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,  
गोरगुंटापाल्या येशवंतपुर,  
बेंगलुरु -560022

सं/No.KNT/BLR/FE/125/BNG/VOL-II Mine-code:30KAR03055दिनांक/Dated:30/08/2022

To,  
Shri Syed Ahmed,  
Nominated Owner & Managing Partner  
Dharmapur Iron ore Mine  
M/s. Zeenath Transport Company.  
Zeenath House, Cowl Bazar  
Ballari District, Karnataka-583 102  
Email id-[ztco2000@yahoo.com](mailto:ztco2000@yahoo.com)

विषय/Subject: **Violation of provisions of MCDR 2017 read with MCDR(Amendment),2021 in respect of your Dharmapur Iron ore Mine, ML 2309 of M/s.Zeenath Transport Company over an extent of 36.42 ha(as per lease deed), in Ramgad Village, SandurTaluk, Ballari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 read with Mineral Conservation and Development (Amendment) Rules, 2021 were found violated in your above mine during inspection on 18.08.2022by undersigned in presence of Shri Pompathi G, Mine Manager, Shri Imthiyaz V, Mining Engineer, Shri M. Peddanna, Geologist and other mining officials:

Rules	Nature of Violations observed
11 (1)	Modification to the approved review and updation of Mining Plan was approved by IBM vide letter no. 279/68/89/BNG dated 02/08/2021, for the period 2021-22(balance period) to 2024-25. The deviations observed in mining operation vis-à-vis approved document are given below. i) The waste dumping for the year 2021-22 was proposed at temporary dump location N-1674862 to 1674890, E-656307 to 656341. It was observed during inspection that temporary dumping was not carried out at the earmarked location as per the

	proposal.  ii)It was observed during inspection that noise monitoring in core and buffer zone are not carried out as per the proposal and mine plan conditions
<b>31(4)</b>	The plans and sections required under these rules shall be maintained up to date showing also the respective proposal of approved mining plan for various activities pertaining to that year, within three months in case of category 'A' mines as referred to in clause (a) of sub-rule (2) of rule 55. It was observed during inspection that the plans maintained have not shown the respective proposal of approved mining plan as per the provision of this rule.
<b>34(A)(2)</b>	The satellite image has not been submitted in accordance with the Standard Operating Procedures under sub rule (5) of rule 34A of MCDR, 2017 for carrying out drone survey and submission of Digital Aerial Images of Mining areas. The submitted image resolution is 1.6 m which is not as per the SOP. Also, the establishment of Ground Control points, Data output and format, Output data submission form for satellite image for the year, have not been done in accordance with the SOP.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR (Amendment), 2021

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

**(Sandeep Kumar Singh)**

Assistant Controller of Mines

Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

**(Sandeep Kumar Singh)**

Assistant Controller of Mines

Indian Bureau of Mines