

**VIOLATION LETTER**

REGD/AD

भारत सरकार GOVERNMENT OF INDIA
खान मंत्रालय MINISTRY OF MINES
भारतीय खान ब्यूरो INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक के कार्यालय
OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0674-2352463;
TeleFax: 0674-2352490;

eMail:
ro.bhubaneshwar@ibm.gov.in

Plot No.149, Pokhariput
BHUBANESWAR-751016
Date:05.09.2018

No.: OR/CR/JJP/MCDR-13/BBS-III/

Date: 05/09/2018

सेवा में,

Shri Shantanu Mohapatra, Nominated Owner
M/s Balasore Alloys Limited.
At: Balgopalpur, PO: Mitrapur, Dist: Balasore
Odisha – 756020

Sub: Violation of provisions of MCDR, 2017 in respect of your Kaliapani Chromite Mine over an area of 64.463 Ha in Jajpur district of Odisha State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 29.08.2018 by the undersigned accompanied by S/Shri Tarini Prasad Mohanty, Agent, Amar Nath Dhar, Mine Manager of your mine.


Rule No.	Proposed in the approved mining plan / Rule	Violation
11 (1)	As per the approved mining scheme dated 27/03/2015, i) It is proposed to maintain waste dump-3 with maximum height of 60 m, i.e. up to 225 mRL in 3 no of terraces with common dumping proposal with M/s JSL.	i) During inspection it is observed that the an approx. area of dimension 120 m x 80 m on waste dump-3 was heightened up to 235 mRL as a 4 th terrace which is not proposed in the approved mining plan.
37 (1) & (6)	Every holder of a prospecting licence, prospecting license cum mining lease or a mining lease shall take steps so that the overburden, waste rock, rejects and fines generated during prospecting and mining operations or tailings, slimes and fines produced during sizing, sorting and beneficiation or metallurgical operations shall be stored in separate dumps. The fines, rejects or tailings from mine, beneficiation or metallurgical plants shall be deposited and disposed in a specially prepared tailings disposal area such that they are not allowed to flow away and cause land degradation or damage to agricultural field, pollution of surface water bodies and ground water or cause floods.	During inspection it is observed that the tailings generated from the COB plant are dumped over waste dump-3, whereas both should not be mixed. The tailings material disposed also are not within the limit of constructed retaining wall for the purpose at grid location between 300N-420N.

02. It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR, 2017.

Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.

03. You are advised to rectify the above violations immediately and intimate the position to this office within **45 (forty-five) days** from the date of issue of this letter.

Yours faithfully,


(Ramkishan R) 9/118

Senior Assistant Controller of Mines
Indian Bureau of Mines

मूल प्रति पर नही / Not on Original प्रतिलिपि निम्न को सादर सूचनार्थ अग्रेषित

- (1) **The Controller of Mines (EZ), भारतीय खान ब्यूरो / Indian Bureau of Mines, Kolkata-700091.**
- (2) **डायरेक्टर ऑफ माइन्स / The Director of Mines, डायरेक्टोरेट ऑफ माइन्स / Directorate of Mines, उड़ीसा सरकार / Government of Orissa, हेडस ऑफ डिपार्टमेंट बिल्डिंग / Heads of Department Building, न्यू कैपिटल / New Capital, भुवनेश्वर / Bhubaneswar-751 001 : For information & further necessary action on following :**



(Ramkishan R)

Senior Assistant Controller of Mines

कृते क्षेत्रीय खान नियंत्रक / For Regional Controller of Mines