

GOVERNMENT OF INDIA MINISTRY OF MINES INDIAN BUREAU OF MINES NAGPUR REGIONAL OFFICE



6th Floor,'B & C'Block,

Indira Bhavan, Civil Lines,

NAGPUR-440 102.

Date:06/07/2021

www.ibm.gov.in

Tele Fax :-2565089

Mail: rcom.nr@ibm.gov.in
File No.MAH/NAG/Mn-137/NGP

Mine Code:-40MSH14051.

To: Shri P.V.V.Patnaik,

Nominated Owner,

M/s MOIL Limited,

IA-MOIL Bhavan, Katol Road,

Nagpur- 440013.

Sub :- Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Munsar Mine, over an extent of 0.97Ha. Situated in Chargaon-village, Teh-Ramtek, and Nagpur District of Maharashtra State.

Sir,

The following provision of Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection on 18/06/2021(A/N), by Shri Kalmata. M.K, Regional Mining Geologist, in presence of Shri .U.M.Bhujade., Mines Manager.

Rule	Nature of Violation observed
11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5 or approved by the competent authority of the Atomic Minerals Directorate for Exploration and Research, in respect of minerals specified in Part B of the First Schedule to the Act where the grade of such atomic minerals is equal to or above the threshold value limits declared under Schedule-A of the Atomic Minerals Concession Rules, 2016. The following deviations were observed in the approved Mining Plan dated 10.07.2020. a) In the approved Mining plan dated 10.07.2020; there was a proposal to produce 52 T of Clean Ore in the year 2020-21. However during inspection it was observed that no such production was carried out by the lessee and deviation is minus 100 percent. If the mining operations are not carried out in accordance with the approved or certified mining plan or any information contained in the mining plan is found to be incorrect, misleading or non-compliant with applicable laws including these rules, the competent authority may by order, suspend all or any of the mining operations and permit

	continuance of only such operations as are required to restore the conditions in the
	mine as envisaged under the approved or certified mining plan or modified mining plan,
	for the purpose of restoration to the extent possible.
45 (7)	Following deficiencies were observed in the annual returns submitted for the year 2019-
	20.
	a) As per the approved document area under mineral dump is 0.20Ha, Area covered by Infrastructure is 0.16Ha, and area under green belt 0.20Ha, but in the annual returns
	submitted for the year 2019-20, the land use details under different heads is shown as
	zero at point no-12 of Part-I.
	b) Under capital structure value of fixed asset is shown as zero.

- 02. In this connection, it is brought to your notice that the above violation constitutes an offence, punishable under Rule 62 of MCDR, 2017.
- 03. The mining operations can be suspended under Rule 11(2), if compliance of MCD Rules 2017 is not found satisfactory, or prosecution can be made, or both can be done.
- 04. You are advised to rectify the above violation immediately and intimate the position to this office within 45 (Fourty five) days from the date of issue of this letter.

Yours faithfully,`

(Chandresh Bohra)
Deputy Controller of Mines,
Indian Bureau of Mines.

Copy forwarded to: -

- 1. The Controller of Mines, CZ, Indian Bureau of Mines, Nagpur.
- 2. The Director, Directorate of Geology & Mining, Govt.of Maharashtra, Khanij Bhavan, plot No-27, Shivaji Nagar, Cement Road, Nagpur-440010.

(Chandresh Bohra)
Deputy Controller of Mines,
Indian Bureau of Mines.