दिनांक : 31.12.2019

माखुपूरा औद्वोगिक क्षेत्र,

Makhupura, Industrial Area

Ajmer- 305 002 (Rajasthan)

अजमेर.-305 002 (राजस्थान)





भारत सरकार

Government of India खान मंत्रालय

Ministry of Mines भारतीय खान ब्यूरो

Indian Bureau of Mines

Mine Code: 30RAJ06002

संख्या : RAJ/BHL-439/IRON ORE-02

प्रेषित : M/s Jindal Saw Ltd., Araji No. 9697/6711,

Near Tiranga Hills, Village-Pur,

Tehsil & District-Bhilwara 311 802 (Rajasthan)

E-mail: sunil.pandey@jindalsaw.com, dinesh.patil@jindalsaw.com

Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your Lampiya

Iron Ore Mine (M.L. 627/05, Lease area 433.1033 Hect.) in Bhilwara District of Rajasthan State.

महोदय.

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection made on 05.12.2019 by the undersigned in presence of Shri Dinesh Patil,

Mine Agent & Shri Sanjay Pandey, Mine Manager:	
Rule No.	Nature of violation observed in detail
Rule 11(1)	The mining operations are carried out in violation of following provisions of approved Modified
	Mining Plan(Approved on 27.07.2018): -
	(i) Bench height & width have not been maintained as per approved proposals.
	(ii) Plantation has not been carried out as per approved proposals.
26 (2)	A yearly report to be submitted before 1 st July of every year setting forth the extent of protective and
	rehabilitation works carried out as envisaged in the approved progressive mine closure plan has not
	been submitted to this office for the year 2018-19.
35(2)	Every holder of a mining lease shall monitor his mining and allied activities as per the notified template of
	star rating in the format prescribed in this behalf by the Indian Bureau of Mines from time to time, and shall
	submit online its self-assessment report before the 1 st day of July every year for the previous financial year,
	alongwith the soft copy (in the standard format), of high resolution satellite images obtained from
	CARTOSAT-2 satellite LISS-IV sensor on the scale of cadastral map, as on the 31 st day of March for that
	financial year, covering the mining lease and an area of two kilometers, from the lease boundary, to the Regional Controller or the authorized officer of the Indian Bureau of Mines. But, it has been observed that
	you have submitted online star rating template only and till date you have not submitted the satellite images
	as stipulated under the rule.
D 1- 45(7)	In annual return 2018-19 following descripencies were observed:
Rule 45(7)	1) Under item 3 of Part IV, the OB removed has been shown 33843 tonnes whereas in item 4.2
	(C) (ii) during the year 870560 tonnes of OB/Waste has been dumped in external dumps.
	2) Under item 1 of part III, the consumption of material has been shown Zero except explosive
	consumption.
	3) Under item 3 of Part VI no grade wise production, dispatched and ex mine price shown.
	4) In Part VII cost of production Rs. 195.09 per tonne has been shown under head
	transportation.
00 1 1	

In this connection, it is brought to your notice that the above violations constitute an offence punishable 02. under Rule 62 of MCDR, 2017 and in case of non compliance of the above rules following action may be initiated under MCDR, 2017:

(a) Mining operations may be suspended under rule 11(2) of MCDR, 2017.

(b) Prosecution may be launched against you.

You are advised to rectify the above violations immediately and intimate the compliance to this office 03. within 45 (forty five) days from the date of issue of this letter

> वरिष्ठ सहायक खान नियंत्रक भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा) । 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर। 3 खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, भीलवाड़ा।

- ४ रक्षित पत्रावली।

वरिष्ठ सहायक खान नियंत्रक भारतीय खान ब्यूरी