

भारतसरकार
खानमंत्रालय
भारतीय खानब्यूरो
क्षेत्रीय खाननिर्बंधक कार्यालय
माखपुराऔद्योगिक क्षेत्र अजमेर 305002
ई-मेल: ro.ajmer@ibm.gov.in



Violation letter (Speed post & email)

Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines,
Makhupura Industrial Area, Ajmer- 305002
Ph-145-2695165 / 2695476 Fax-2695202

संख्या : RAJ/BAR-18/Selenite-11

दिनांक: 28/02/2020

To,

✓ Sh. A. K. Chaudhary
M/s R.S.M.M. Ltd
4 Gandhi Nagar Scheme,
Distt: Bikaner,
Rajasthan: 334001
Email: info.rsmml@rajasthan.gov.in, akchoudhary.rsmml@rajasthan.gov.in

Sub: Violation of provision of Mineral Conservation and Development Rule, 2017 in respect of your Thob-I selenite Mine (M.L. Number 10/92) in Barmer District of Rajasthan State.

महोदय,

The following provision of Mineral Conservation and Development Rules, 2017 (hereinafter referred as MCDR, 2017) were found to violate in your above said mine during inspection on 30/01/2020 by undersign in presence of Sri B.S. Rathore, Mine Manager your mines.


Rule	Status and extent of violation
11(1)	Mining operations have not been carried out in accordance to Review of Mining Plan approved vide letter dated 19/05/2017 to the extent given below: (1) Exploration proposed by exploratory pit namely PP-54 to PP-63 during the year 2018-19 has not been carried out.
26(2)	The yearly report for the extent of protective and rehabilitative works carried out as specified in the rule has not been submitted to the Regional Controller of the Mines, Indian Bureau of Mines, Ajmer for the year 2018-19.
45(7)	On examination of annual return for the year 2018-19 following discrepancies have been observed. (i) Part I, Para 12: The information of land use furnished under para is not matching with the actual land use. (ii) Part IV, Para 2 & 3: The quantity of total production and overburden removed has not been furnished in the relevant para. (iii) Part V, Section 3: The position of the Mineral Reserve and Remaining Resource at the end of the year has not been furnished. (iv) Part V, Section 4 (Mining Operation during the year), para 4.4: Information has not been furnished on number of trees planted within and outside of the lease area along with survival rate. (v) Part V, Section 4 (Mineral Reject), para 4.2: During inspection it has been reported that there is no mineral reject generation during the year 2018-19. However, a quantity of 46 tonnes has been furnished under mineral reject generation. (vi) Part VI, Para 2: The figure of Ex-mine price furnished as 4089720.00 per tonne is abnormally high which apparently is incorrect. Further, as per return 2044.860 tonnes of Selenite mineral has been dispatched from the mine. However, details like Consignee name, registration number, nature of dispatch etc. has not been furnished under para 5 of part VI.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत :

- (क) आपकी खदान की सारी संकियाएं बंद की जा सकती है।
- (ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
- (ग) राज्य सरकार को खनन पट्टे की समप्ति की सिफारिश।

03. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की दिनांक से 45 (पैंतालिस) दिनों के भीतर इस कार्यालय को सूचित करें।

भवदीय



(दिलीप जैन)

वरिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा)
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 3 खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, Barmer.
- 4 रक्षित पत्रावली।

(दिलीप जैन)

वरिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो