Violation letter (Speed post & email)

भारतसरकार खानमंत्रालय भारतीय खानव्यूरो क्षेत्रीय खाननियंत्रक काकार्यालय माखुपुराओद्योगिक क्षेत्र अजमेर 305002 ई—मेलः ro.ajmer@ibm.gov.in





Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines.
Makhupura Industrial Area, Ajmer- 305002
Ph-145-2695165 / 2695476 Fax-2695202

दिनांकः 10/02/2020

संख्या : RAJ/JSL/-7/S.Earth-1

To,

Dr. Ramesh Chandra Ojha, Proprietor,

M/s Sema Minerals & Metals, 203-A, Mewar Industrial Area,

Road No.: 11/F, Madri, Post: Udaipur (Raj.)

Pin: 313003

(e-mail: seemamineral@hotmail.com, mkchittora@hotmail.com)

Sub: Violation of provision of Mineral Conservation and Development Rule, 2017 in respect of your Kapuria Siliceous Earth Mine (M.L. Number \$\circ{\chi}{1}/2001)\$ in Jaisalmer District of Rajasthan State.

महोदय,

The following provision of Mineral Conservation and Development Rules, 2017 (hereinafter referred as MCDR, 2017) were found to violate in your above said mine during inspection on 09/01/2020 by undersign in presence of your Sri Radheyshyam Paliwal, Mining Engineer of your Mine:

Mine:	
Rule	Status and extent of violation
11(1)	Mining operations have not been carried out in accordance to Review of Mining Plan approved vide letter dated 19/05/2017 to the extent given below:
	(1) Exploration proposed by exploratory pit namely PTP-6 to PTP-08 and PTP-09 to PTP10 during the year 2017-18 and 20-18-19 respectively has not been carried out.
26(2)	The yearly report for the extent of protective and rehabilitative works carried out as specified in the rule has not been submitted to the competent authority for the year 2018-19.
33	The plan and sections mentioned under rule has not been submitted to the Regional Controller of Mines, Ajmer on or before the 30th day of June.
45(7)	On examination of annual return for the year 2018-19 following discrepancies have been observed.
, ,	(i) Part I, Para 12: The details of the land use furnished as on 01/04/2019 is appears to be incorrect.
	(ii) Part IV, Para 2 and 3: The quantity of total production during the year and overburden removed has not been furnished in the relevant para.
	(iii) Part V, Section 3: The position of Mineral Reserve and Remaining Resource furnished are not updated as on 01/04/2019.
7 - X	(iv) Part V, Section 4 (Mining Operation during the year), para 4.2: Total quantity of Overburden/Waste removed during the year has not been furnished.
	(v) Part VI: ROM production has been reported as of 5405.00 tonnes and after adding same in opening stock, closing stock of 17350.598 tonnes has been furnished. In the table of grade wise production, again production of 5405.00tonnes has been mentioned. Hence, it is perceived that entire ROM is processed and same should not be consider for estimation of closing stock of the ROM. Accordingly, figures of ROM closing stocks to be rectified.

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत :

(क) आपकी खदान की सारी संकियाएं वंद की जा सकती है।

(ख) आपके विरूध्द अभियोग दायर किया जा सकता है।

(ग) राज्य सरकारा को खनन पट्टे की समप्ति की सिफारिश ।

03. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की रिथति की सूचना इस पत्र के जारी होने की दिनांक से 45 (पैतालिस) दिनों के भीतर इस कार्यालय को सूचित करें।

भवदीय

(दिलीप जैन) वरिष्ठ खनन भूविज्ञानी भारतीय खान व्यूरो

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा)
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 3 खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, Jaisalmer.
- 4 रक्षित पत्रावली।

(दिलीप जैन) वरिष्ठ खनन भूविज्ञानी भारतीय खान ब्यूरो