खान मंत्रालय भारतीय खान ब्यूरो क्षेत्रीय खान नियंत्रक का कार्यालय Mine code 38HPR10020

स्पीड पोस्ट

संख्या

एचपी / एसआरएम / एलएसटी-51

100 ओल्ड नेहरू कालोनी, देहरादून (उत्तराखंड) दिनांक : 25.03.2015

110 : 25.03.2

सेवा में :

मैसर्स सोहन सिंह मीत सिंह गांव एवं पोस्ट- कमरऊ

जिला- सिरमौर (हिमाचल प्रदेश)

विषय

हिमाचल प्रदेश राज्य के सिरमौर जिले में स्थित आपकी भीमगोडा चूनापत्थर खान पर खनिज संरक्षण एवं

विकास नियमावली 1988 के निम्नलिखित नियमों का उल्लंघन।

महोदय,

इस कार्यालय के श्री एस0 सकलानी, सहायक खनन भूवैज्ञानिक द्वारा श्री केदारेश्वर मिश्र, खान प्रबन्धक की उपस्थिति में दिनांक 22.02.2015 को आपकी उपरोक्त वर्णित खान का निरीक्षण किया गया। निरीक्षण के दौरान खनिज संरक्षण एवं विकास नियमावली 1988 के निम्नलिखित प्रावधानों का उल्लंधन पाया गया:—

## RULE NO.

## NATURE OF VIOLATION OBSERVED

13(1): Mining operations were being carried out in violation of following provisions of scheme of mining approved vide letter no. 614(2)/MSB-34/97-DDN dated 11.12.2013.

(i) As per proposal made on page 28 & 29 and plate 5A and 5B, 6 meters height benches commencing from 2000 mRL to 1976 mRL were to be made in the north eastern portion of the lease area. Similarly the vertical escarpment of the north western portion was proposed to be sliced down commencing from 2054 mRL to 2036 mRL.

During the inspection it was observed that the vertical escarpment from north west side has not been sliced down.

23(F): Since regular deployment of excavator is observed during the inspection, minimum requisite amount of financial assurance is two lakhs but you have furnished only one lakh.

o2. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of Mineral Conservation and Development Rules, 1988.

03. The mining operations can be suspended under Rule 13(2), if compliance of rule 13(1) is not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45(Forty Five) days from the date of issue of this letter.

261031.15. Askerb

भवदीय

कें एस0 यादव) क्षेत्रीय खान नियंत्रक भारतीय खान ब्यूरो

प्रतिलिपि -

1. खान नियंत्रक (उत्तर),भारतीय खान ब्यूरो, अजमेर।

2. राज्य भूवैज्ञानिकए उद्योग विभाग, उद्योग भवन, शिमला, (हि० प्र०)

कि एस0 यादव) क्षेत्रीय खान नियंत्रक