

Speed post (तीव्र डाक)

भारतसर्वकार
खानमंत्रालय
भारतीय खानब्यूरो
क्षेत्रीय खाननियंत्रक कार्यालय
माखपुराऔद्योगिक क्षेत्र अजमेर 305002
ई-मेल: ro.ajmer@ibm.gov.in

**Violation letter/उल्लंघन पत्र**

Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines,
Makhupura Industrial Area, Ajmer- 305002
Ph-145-2695165 / 2695476 Fax-2695202

संख्या: RAJ/BLW-439/IO-02-AJM

दिनांक: 04/05/2021

प्रेषित Shri Dinesh Patil, Mine Agent,
Lampiya Iron Ore, Copper and Associate Minerals Mine,
M/s Jindal Saw Limited,
Araji Number: 9697/6711, Near Tiranga Hills,
Village: Pur, District: Bhilwara (Rajastaha),
PIN: 311802.
(e-mail: dinesh.patil@jindalsaw.com)

विषय: Violation of provision of Mineral Conservation & Development Rules, 2017 in respect of your Lampiya Iron Ore, Copper and Associate Minerals Mine over an area of 433.1033 Hect. in Bhilwara District of Rajasthan State.

महोदय,

The following provision of Mineral Conservation and Development Rules, 2017 (hereinafter referred as MCDR, 2017) were found to violated in your above said mine during inspection on 14 April 2021 by the undersigned in presence of your good-self, Shri Sanjay Kumar Pandey, Mine Manager and Shri Divakar Arora, Geologist of your Mine:

Rule	Status and extent of violation
11(1)	<p>Mining operations have not been carried out in accordance to Review of Mining Plan approved on 20/01/2020 to the extent given below for the year 2020-21:</p> <p>(1) Ore to Overburden ratio (stripping ratio) was achieved 1:0.62 (CuM/CuM) against the proposed ratio of 1:0.43 (CuM/CuM).</p> <p>(2) It was proposed to maintain height and width of the benches at 8 to 10 and 15 meters respectively. However, it is observed that height and width of the benches have not been maintained as per approved proposal.</p> <p>(3) The mineral stacking was proposed between grid lines N2814540 to 2814425/E463790 to 463940. However, mineral stacking was observed other than the proposed limit between N2814430 to 2814580/E463800 to 464120 and N2814140 to 2814220/E463340 to 463420.</p> <p>(4) Retaining wall of 320 mts proposed along the foot of waste dump has not been constructed.</p> <p>(5) Plantation proposed over 1.0 hect. with 1000 number of plants has not been carried out.</p>
45(7)	<p>On examination of annual return for the year 2019-20 following discrepancies have been observed.</p> <p>(1) Part V, Section 1: The grade of mineral reject has been mentioned as 13%. However, under section 4 quantity of mineral reject generation has been mentioned as "Zero" or NIL. Further, during mine inspection also no mineral reject generation was reported.</p> <p>(2) Part VII: Exploration work has been reported as NIL under part V, Section 4. However, Rs. 10.26 per tone of exploration cost has been considered under cost of production. Further, Rs. 3.83 per tone depreciation cost has been considered under cost of production, whereas, value of fixed asset has been furnished as NIL or Zero. The transportation cost Rs. 195.09 per tone considered under cost of production is too high.</p>

02. इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उल्लंघन खनिज संरक्षण एवं विकास नियमावली, 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है एवं उपरोक्त नियमों का उल्लंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली, 2017 के अंतर्गत :

- (क) आपकी खदान की सारी सक्रियताएं बंद की जा सकती हैं।
- (ख) आपके विरुद्ध अभियोग दायर किया जा सकता है।
- (ग) राज्य सरकार को खनन पट्टे की समिति की सिफारिश।

03. अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनों का अतिशीघ्र सुधार करें एवं इसके सुधार की स्थिति की सूचना इस पत्र के जारी होने की दिनांक से 45 (पैंतालिस) दिनों के भीतर इस कार्यालय को सूचित करें।

भवदीय

(दिलीप जैन)

वरिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो

प्रतिलिपि सूचनार्थ प्रेषित :-

- 1 खान नियंत्रक (उत्तर), भारतीय खान ब्यूरो, उदयपुर (ई मेल द्वारा)
- 2 निदेशक, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, उदयपुर।
- 3 खनि अभियंता, खान एवं भूविज्ञान विभाग, राजस्थान सरकार, Bhilwara.
- 4 रक्षित पत्रावली।


वरिष्ठ खनन भूविज्ञानी
भारतीय खान ब्यूरो