



भारत सरकार / GOVERNMENT OF INDIA

खान मंत्रालय / MINISTRY OF MINES

भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES

कमरा नंबर 603, छठवाँ तल, सी0जी0ओ0 टॉवर्स, / Room No. 603, 6th Floor, CGO Towers,
कवाडीगुडा, सिकंदराबाद (तेलंगाना) - 500080 / Kavadiguda, Secundrabad, (Telangana) - 500080

फोन: 040-29555603, 29554603, 29553603, ई-मेल: ro.hyderabad@ibm.gov.in

Violation Notice / उल्लंघन पत्र

Reg. AD/Speed Post/
Email/Fax

No. AP/KSN/LSt-17/Hyd Vol. V

Mine Code: 38APR10010

Date: 09/09/2021

प्रति,

श्री अजीत कुमार सक्सेना,
निदेशक (संचालन) एवं नामित मालिक,
सर्वश्री राष्ट्रीय इस्पात निगम लिमिटेड,
विशाखापट्टणम इस्पात संयंत्र,
प्रशासनिक भवन,
विशाखापट्टणम (आन्ध्र प्रदेश) - 530031

To

Shri Ajit Kumar Saxena,
Director (Operation) & Nominated Owner,
M/s Rashtriya Ispat Nigam Limited,
Visakhapatnam Steel Plant,
Administrative Building,
Visakhapatnam (Andhra Pradesh) - 530031

Sub: Violation of provisions of MCDR, 2017 in respect of your Jaggayyapeta Limestone Mine over an extent of 1295.00 ha. situated in Budawada Village, Jaggayyapeta Mandal, Karishna District of Andhra Pradesh State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 (MCDR, 2017) were found violated in the above mine during the inspection on 01/09/2021 by the undersigned in presence of the mine officials Shri K. K. Dhruvw, Mining Engineer and Shri K. Srinivas Rao, Geologist.

Rule No.	Nature of violation
Rule 11 (1)	The following deviations have been found in the mine from the approved Modified Mining Plan vide letter no. AP/KSN/MP/LST-7/HYD Hyderabad dated 26/05/2020 for the period of F.Y. 2020-21 to 2024-25: Exploration: During F.Y. 2020-21 and F.Y. 2021-22; it was proposed to drill 10 nos. of boreholes with the cumulative depth of 917.0 meters, whereas, none of the boreholes have been drilled so far.
Rule 26 (1)	During inspection, it has been found that an old worked out pit/quarry situated in between UTM Co-ordinates N680000 to N680500 and E2750500 to E2751000 within lease area is left abandoned. The mineral was mined out earlier, and later no Protective Measures was taken around this quarry. Hence, suitable Protective Measures should be taken around this non-working quarry.
Rule 45 (7)	Annual Return F.Y. 2020-21: Part - VI (Production, Dispatches And Stock): For Captive Users, Ex-mine price should be reported similar to the Cost of Production as computed in Part VII.

02. In this connection, it is brought to your notice that the violation of aforesaid rule constitutes an offence punishable under Rule 62 of MCDR, 2017.

03. The mining operations can be suspended under rule 11(2) and 45(7), if compliance of rule 11(1) and 45(7) are not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Continue...2...

(शैवाल कार्तिकेय)
वरिष्ठ खनन् भूविज्ञानी
भारतीय खान ब्यूरो, हैदराबाद

प्रतिलिपि: सूचनार्थ हेतु :-

1. खान नियंत्रक (दक्षिण), भारतीय खान ब्यूरो, बंगलूर (कर्नाटक) – 560022
2. The Director of Mines and Geology, Government of Andhra Pradesh, Sri Anjaneya Towers, Door No.7-104, B-Block, 5th and 6th Floors, BTPS Road, PO Ibrahimpatnam-521456, Vijayawada, Krishna District.
3. Shri B. U. V. N. Raju, Agent (Mines), Jaggayyapeta Limestone Mine, M/s Rashtriya Ispat Nigam Limited, Visakhapatnam Steel Plant, Village Budawada, Post – Limestone Township, Mandal Jaggayyapeta, District Krishna, State Andhra Pradesh, Pin Code: 521175

(शैवाल कार्तिकेय)
वरिष्ठ खनन् भूविज्ञानी
भारतीय खान ब्यूरो, हैदराबाद