



भारत सरकार

खान मंत्रालय

भारतीय खान ब्यूरो, क्षेत्रीय कार्यालय रायपुर

दूसरी मंजील, जीएसआई फील्ड प्रशिक्षण केन्द्र

महालेखाकार आफिस कोम्प्लेक्स, पोस्ट-विधान सभा- रायपुर- (छ.ग)-492005

फोन- 0771--2282530/2285590/95 [मेल- ro.raipur.ibm@ibm.gov.in](mailto:ro.raipur.ibm@ibm.gov.in)

No- CHG/BBR/LST-38CHG19004

दिनांक -10/08/2021

प्रेषिति- श्री के.सी.झाँवर, नामित मालिक,  
सर्वश्री अल्ट्राटेक सीमेंट लिमिटेड,  
रावण सीमेंट वर्क्स,  
पोस्ट- ग्रसीम विहार रावण,  
जिला-बलोदा बाजार(छ.ग.)-493196

Email: abhishek.osharma@adityabirla.com

विषय- छत्तीसगढ़ राज्य के बलोदा बाजार जिले में स्थित आपकी गुमा चूना पत्थर खदान 157.122 हे. में खनिज संरक्षण एवं विकास नियमावली 2017 के नियमों के उलंघन के संबंध में-

महोदय

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated during inspection of the above mine on 16.07.2021 by undersigned accompanied by Shri Mayank Saini, Manager(Mines) & Shri Abhijit Maji, Geologist.

Rule	Nature of Violation observed					
11(1)	<p>Mining operations should have been undertaken in accordance with the approved Mining Plan. The Mining Plan was approved vide letter no. 314(3)2010-MCCM(CZ)/MP-25,NAGPUR dated 14.02.2011 and following deviation was observed during inspection</p> <ol style="list-style-type: none"> <li>The mining operation is not carried out as per proposal and production is proposed 3220000 MT and achievement is only 1126277.93MT which is less than 35% and dispatch is only 22% reported.</li> <li>There is huge gap of proposal and achievement of Top soil, OB generation and mineral reject, proposal is given for 193000 m<sup>3</sup>. 300000 MT &amp; 280000 Mt Whereas achievement is only 16488 m<sup>3</sup>, 12130 MT &amp; Nil in 2020-21.</li> <li>The Dump is not done as per proposal and following deviation observed:</li> </ol> <table border="1"> <thead> <tr> <th>Proposal</th> <th>Actual</th> </tr> </thead> <tbody> <tr> <td><b>Top soil Dump- Not Proposed.</b> Dump (O.B.) N 2386830 to 2386600 E610397 to 610737 Reject <b>Dump 1</b> - N 2388068 to 2387871 E 609732 to 609919 Reject <b>Dump 2</b> - N 2387649 to 2387361 E 609519 to 609798</td> <td><b>Top soil- Stacked at</b> N – 2387354-2387561 E – 610953.9-611154  <b>OB/Waste Dump</b> N-2387580-2387820 E-610409-610908</td> </tr> </tbody> </table>		Proposal	Actual	<b>Top soil Dump- Not Proposed.</b> Dump (O.B.) N 2386830 to 2386600 E610397 to 610737 Reject <b>Dump 1</b> - N 2388068 to 2387871 E 609732 to 609919 Reject <b>Dump 2</b> - N 2387649 to 2387361 E 609519 to 609798	<b>Top soil- Stacked at</b> N – 2387354-2387561 E – 610953.9-611154  <b>OB/Waste Dump</b> N-2387580-2387820 E-610409-610908
Proposal	Actual					
<b>Top soil Dump- Not Proposed.</b> Dump (O.B.) N 2386830 to 2386600 E610397 to 610737 Reject <b>Dump 1</b> - N 2388068 to 2387871 E 609732 to 609919 Reject <b>Dump 2</b> - N 2387649 to 2387361 E 609519 to 609798	<b>Top soil- Stacked at</b> N – 2387354-2387561 E – 610953.9-611154  <b>OB/Waste Dump</b> N-2387580-2387820 E-610409-610908					
37(1)	<p>The existing protective measures taken around waste dump are insufficient and it has been found that the waste material was escaping and washing away from the dumps and was contaminating the nearby area and extending outside lease boundary and no retaining wall constructed. A proper protective measure should be taken to prevent the escape of the material from the existing waste dumps. The retaining wall around dump almost fill and now the retaining wall is at surface level therefore proper retaining wall should be constructed.</p>					
45(5)(c)(i)	<p>While scrutiny of Annual returns 2020-21 it was observed that for calculation of fixed asset Industrial, plant and machinery including transport equipment is taken into consideration whereas all the equipment is contractual and Ex-mine price is Rs 187.32/- in lower side with compared to other captive mine Rs 210.79/- &amp; Rs 242.72/- of M/S Ultratech Cement Balodabazar.</p>					

- 2 इस संदर्भ में आपका ध्यान आकर्षित किया जाता है कि उपरोक्त नियमों का उलंघन खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 62 के अंतर्गत दंडनीय अपराध है। एवम इस नियम का उलंघन की अनुपालना नहीं होने पर खनिज संरक्षण एवं विकास नियमावली 2017 के नियम 11(2) एवम 45(7)(क) के अंतर्गत (क) खान की सारी खनन संक्रियाएँ बंद की जा सकती हैं।

- (ख) आपके विरुध अभियोग दायर किया जा सकता है 1
- (ग)खनन पट्टे को निरस्त करने की सिफारिस राज्य सरकार से की जा सकती है1
- 3 अतः आपको सलाह दी जाती है कि आप उपरोक्त उल्लंघनो का अतिशिघ्र सुधार करे एवम इसके सुधार की सूचना इस पत्र के जारी होने से 45 दिन के भितर इस कार्यालय को सूचित करे1

भवदीय

(राजेश कुमार दास)  
वरिष्ठ सहायक खान नियंत्रक  
भारतीय खान ब्यूरो, रायपुर