VIOLATION LETTER



भारत सरकारGOVERNMENT OF INDIA खान मंत्रालय MINISTRY OF MINES भारतीय खान ब्यूरो INDIAN BUREAU OF MINES क्षेत्रीय खान नियंत्रक के कार्यालय OFFICE OF THE REGIONAL CONTROLLER OF MINES



Phone: 0674-2352463; TeleFax: 0674-2352490; eMail: ro.bhubaneshwar@ibm.gov.in Plot No.149, Pokhariput BHUBANESWAR-751020

Date: 06/09/2019

No.: ORJ/IRON/SNG/MCDR-7/BBS/II

सेवामें,

Sri D.K.Saraogi, Nominated Owner,

T.R.B. iron Ore Mine

M/s Jindal Steel & Power Limited.

At/Po: Tensa, Dist: Sundergarh

Odisha-770042

Sub: Violation of provisions of MCDR, 2017 in respect of your TRB Iron Mines, over an area of 207.113hectare in Sundargarh district of Odisha State

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above said mine during inspection on 21.08.2019 by the undersigned accompanied by S/Shri C.Mallick, Senior Inspector of Mines, DDM Office, Koira, State Govt., Of Odisha,

P.K.Patra, Agent, B.D.Sahoo, Manager of your mine.

r.K.Faiia,	Agent, B.D.Sahoo, Manager of your mine.	
Rule No.	Proposed in the approved mining plan / Rule	Violation
11 (1)	As per the approved mining plan dated	i) During inspection it is observed that
	05.12.2018	the bench height and width are not
	i) It is proposed to maintain a bench height of 9	maintained as per the dimensions
	m and width of more than 12 m in the patch-2	proposed in the mining plan proposed
	quarry.	in the quarry western side of quarry.
		and the bench width and height are
		less than 12 m and 9 m.
45 (7)	Holder of mining lease shall not submit	i) During scrutiny of annual return it is
	incomplete or wrong or false information in	observed that details furnished under
	daily or monthly or annual returns.	Part-III, item no.2(a) as royalty paid
		information, but during inspection it is
		observed that it includes payments
		made to DMF and NMET.

02. It is brought to your notice that these violations constitute an offence punishable under Rule 62 of MCDR,2017.

Besides, inability to comply with the provision of Rule 11 (1) is liable for suspension of mining operations according to the provisions of Rule 11 (2) of MCDR, 2017.

Further, in view of the above position, the information furnished under Rule 45(5) in the Annual return is construed as furnishing wrong or false information, which leads this office to advise the state government under rule 45 (7) to,-

- (i) Order suspension of all mining operations in the mine and to revoke the order of suspension only after ensuring proper compliance;
- ii) Take action to initiate prosecution under these rules;
- (iii) Recommend termination of the mining lease, in case such suppression or misrepresentation of information indicates abetment or connivance of illegal mining;

03. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

Yours faithfully,

(Ramkishan R)

Senior Assistant Controller of Mines Indian Bureau of Mines

मूलप्रतिपर नहीं / Not on Original प्रतिलिपिनिम्नकोसादरसूचनार्थअग्रेषित

- (1) The Controller of Mines (EZ),भारतीय खानब्यूरो/Indian Bureau of Mines, Kolkata-700091.
- (2) डायरेक्टरऑफमाइन्स/The Director of Mines, डायरेक्टोरेटऑफमाइन्स / Directorate of Mines, उड़ीसासरकार /Government of Orissa, हेडसऑफडिपार्टमेंटबिल्डिंग /Heads of Department Building, न्यूकैपिटल /New Capital, भुवनेश्वर /Bhubaneswar-751 001 : For information & further necessary action on following :

(Ramkishan R)

Senior Assistant Controller of Mines

कृते क्षेत्रीय खाननियंत्रक/For Regional Controller of Mines