



o/c 1345

Government of India
Ministry of Mines
Indian Bureau of Mines
Office of the Regional Controller of Mines, Jabalpur

Email/Post



File No.: MP/Katni/Lst-236 6256-6258

Jabalpur, Dated: 16.11.2021

To,

Shri.Madan Lal Grover
Civil Lines Katni
Katni (M.P.)-483501.

Sub.: Violation of provisions of Mineral Conservation and Development Rules, 2017, in respect of your Salaiya Paharai limestone Mine (4.69 Ha), Mine code 38MPR47069 in Katni District of (M.P.).

Sir,


Following provisions of MCDR 2017 were found violated in your above mine during the inspection by the Undersigned on **01/11/2021** in the presence of Shri Manoj Kumar Roy (Mines Head) & Shri Sachin Kumar Mishra (Mining Engineer).

Rule No	Nature of violation observed in detail
11(1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section (2) of section 5. It was proposed to carryout plantation of 100 nos of saplings over an area of 0.1 ha of backfilled area during the year 2020-21. But during inspection only 50 nos(approx..) of saplings which are over 01 year old found.
37(2)	The dumps shall be properly secured to prevent escape of material there from in harmful quantities which may cause degradation of environment and to prevent causation of floods. During the inspection it was observed that Garland drains were not properly maintained around the toe of the waste dumps in the lease.
40	Every holder of mining lease shall take all possible measure to keep air pollution due to fines, dust, smoke or gaseous emissions during mining, beneficiation or metallurgical operations and related activities, within permissible limits. No water sprinkling arrangement is there to suppress the dust arising out of the mining activities.
45(7)	The following deficiencies were observed in the Annual Return submitted for the year 2020-21: i. Part-V, 4.2 (C): Total quantity of Overburden/Waste removed during the year is not furnished. ii. The details of taxes furnished in cost per tonne calculation in Part-VII are not matching with the amount submitted in the Part-III, Sl.No.5. iii. In the cost per tonne calculation, the details of overhead cost is not matching with the amount submitted in the Part-III, Sl.No.6. iv. The details of DMF and NMET have not been furnished in the cost of production table of Part-VII.

1. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of Mineral Conservations and Development Rules, 2017.
2. The mining operations can be suspended under the rule 11(2) of MCDR-2017, if compliance of rule 11(1) of MCDR-2017 is not found satisfactory.

3. You are advised to rectify the violations of abovementioned rules immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

Yours faithfully


(Robert Simon C)


Asst. Controller of Mines,
Jabalpur Region, IBM

~~DRAC~~
as

Copy to:

- 1) The Controller of Mines (CZ), IBM, Nagpur,
- 2) The Director, Directorate of Geology & Mining, Khanij Bhavan, Arera Hills, Bhopal (MP).

o/c


(Robert Simon C)

Asst. Controller of Mines,
Jabalpur Region, IBM