

S.L.No- 64C1)  
48C1)

Violation letter  
Registered Post

भारत सरकार/GOVERNMENT OF INDIA  
खान मंत्रालय/MINISTRY OF MINES  
भारतीय खान ब्यूरो/INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक, गोवा का कार्यालय/OFFICE OF THE RCOM, GOA  
(आयएसओ 9001:2008)

Phone No.: 0832-2741757  
Fax No. : 0832-2741758  
E-mail: [ro.goa@ibm.gov.in](mailto:ro.goa@ibm.gov.in)

Opp. Old R.T.O. Office,  
P.O. Fatorda,  
MARGAO, GOA-403602

File No. KNT/BJP/Lst-59/GOA

Dated 19<sup>th</sup> September 2016

Mine code: **38KAR26022**

To,

**Shri B.C.Udapudi,**

Main Bazar Road, Mudhol Road,

P.O.Lokapur-587 122

Tal: Mudhol, District-Bagalkot,

Karnataka

Sub: Violation of provisions of Mineral Conservation and Development Rules, 1988, in respect of your Muddapur Limestone & Dolomite Mine (ML No. 2534) over an extent of 14.580 Ha. in Bagalkot district.

Sir,

The following provisions of the Mineral Conservation and Development Rules, 1988 were found violated in your above mine during the inspection on **26/08/2016** by undersigned in presence of the mine officials Shri Gururaj B. Udapudi , Mining Engineer.

Rule No.	Nature of Violations observed
13(1)	In the approved Scheme of Mining it was proposed to maintain benches of 6 meters height in the ore zone. However, it was observed during the inspection that proper benches of regular heights are not maintained.
13(1) & 23(E) 2	An yearly report on Progressive Mine Closure Plan before 1st July of every year setting forth the extent of protective and rehabilitation work carried out as envisaged in the approved progressive mine closure plan has not been submitted for the year 2015-16 so far.
42(1)(c)(i) & (ii)	The mine is working as Category 'A' mine. However, the Mining Engineer Shri Gururaj B. Udapudi appointed in the mine does not have minimum ten years of professional experience of working in a supervisory capacity in the field of mining.

-844-  
Issued  
P.O.  
19/09/16

63	A self-appraisal note to be submitted by the mines owner/lessee stating extent of implementation of approved mining plan/scheme of mining during the year 2015-16 along with supporting plan & sections ,representative photographs is not submitted to this office so far in hard as well as soft copy.
45(7)	It was observed while scrutinizing the Annual Returns in respect of 2015-16 that the quantity of total dispatch indicated at Item No. 2 of Part VI (Production, Dispatches & Stocks) is not tallying with Sales/Dispatch indicated in Item No. 5 of Part VI (Production, Dispatches & Stocks).

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 58 of Mineral Conservations and Development Rules, 1988.
03. The mining operations can be suspended under rule 13(2) and 45(7) (i) (a), if compliance of rule 13(1) & 45 (7) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

Yours faithfully

ccckale  
19/9/2016

(Dr. Y.G.KALE)

Regional Controller of Mines  
Indian Bureau of Mines

QC

Copy forwarded to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mines & Geology, Government of Karnataka, No.49, Khanija Bhavan, Race Course Road, Bangalore-560001.

ccckale  
19/9/2016

(Dr. Y.G.KALE)

Regional Controller of Mines  
Indian Bureau of Mines

QC

845  
846