



भारत सरकार / GOVERNMENT OF INDIA

खान मंत्रालय / MINISTRY OF MINES

भारतीय खान ब्यूरो / INDIAN BUREAU OF MINES

क्षेत्रीय खान नियंत्रक कार्यालय / OFFICE OF THE REGIONAL CONTROLLER OF MINES

कमरा नंबर 603, छठवाँ तल, सी0जी0ओ0 टॉवर्स, / Room No. 603, 6th Floor, CGO Towers,

कवाडीगुडा, सिकंदराबाद (तेलंगाना) - 500080 / Kavadiguda, Secundrabad, (Telangana) - 500080

फोन / Phone: 040-29555603, 29554603, 29553603, ई-मेल / E-mail: ro.hyderabad@ibm.gov.in

Violation Notice / उल्लंघन पत्र

Reg. AD/Speed Post/

Email/Fax

File No. AP/KSN/LSt-25/Hyd Vol.II

Mine Code: 38APR10026

Date: 23/09/2021

To

**Shri P. R. Venketrama Raja, Charman, Managing Director & Nominated Owner,
M/s The Ramco Cements Limited,
Auras Corporate Center, V Floor,
98-A, Dr. Radhakrishnan Road,
Mylapore, Chennai (Tamil Nadu) – 600 004**

Sub: Violation of provisions of MCDR, 2017 in respect of your Ravirala Limestone Mine over an extent of 60.72 ha. situated in Ravirala Village, Jaggayyapet Mandal, Karishna District of Andhra Pradesh State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 (MCDR, 2017) were found violated in the above mine during the inspection on 08/09/2021 by the undersigned in presence of the mine officials Shri P. Jani Reddy, Agent (Mines).

Rule No.	Nature of violation
Rule 11 (1)	The following deviations have been found in the mine from the approved Modified Mining Plan vide letter no. AP/KSN/MP/LST-2/HYD Hyderabad dated 16/03/2020 for the period of F.Y. 2019-20 (01/01/2020) to 2022-23: (1) It has been found that as per the approved Modified Mining Plan, 49.65 Ha lease area has been considered for calculation of Financial Assurance up to the end of the Plan Period, i.e. up to F.Y. 2022-23, whereas, 53.17 Ha. area has been utilized till the end of F.Y. 2020-21. (2) The overburden and waste material excavated during mining operations should have been dumped separately at the designated OB/Waste dump. It is found that the certain quantity of limestone and oversize boulders of limestone found in dump with waste material.
Rule 45 (7)	Annual Return F.Y. 2020-21: Part IIA; Capital Structure: 1. Since the furnished value under the section of Fixed Assets is for Ravirala Mining Lease (38APR10026) and this value of Fixed Assets is not combined with another mining lease, hence, the written Mine Name, Mine Code (38APR10026) and Mineral Name should be removed from this section. Part V; General Geology & Mining (Sec 1/2 for Limestone); Section 5/6/8/9: Since the dewatering is being done from the Pit, hence, the details of the machinery used for dewatering should be given in this section. Part – VII; Cost of Production: For computation of cost of production, cost of transportation from mining lease up to the captive plant should not be added.

02. In this connection, it is brought to your notice that the violation of aforesaid rule constitutes an offence punishable under Rule 62 of MCDR, 2017.

Continue...2...

03. The mining operations can be suspended under rule 11(2) and 45(7), if compliance of rule 11(1) and 45(7) are not found satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

(शैवाल कार्तिकेय)
वरिष्ठ खनन् भूविज्ञानी
भारतीय खान ब्यूरो, हैदराबाद

प्रतिलिपि: सूचनार्थ एवं आवश्यक कार्यवाही हेतु :-

1. खान नियंत्रक (दक्षिण), भारतीय खान ब्यूरो, बंगलूर (कर्नाटक) – 560022
2. The Director of Mines and Geology, Government of Andhra Pradesh, Sri Anjaneya Towers, Door No.7-104, B-Block, 5th and 6th Floors, BTPS Road, PO Ibrahimpatnam-521456, Vijayawada, Krishna District.
3. Shri P. Jani Reddy, Agent (Mines), The Ramco Cements Limited, KSR Nagar, Jaggayypet Mandal, Krishna District, Andhra Pradesh - 521457

(शैवाल कार्तिकेय)
वरिष्ठ खनन् भूविज्ञानी
भारतीय खान ब्यूरो, हैदराबाद