

REPORT ON CHECK UP INSPECTION OF Rajanka Limestone MINE OF M/s ACC Ltd. SITUATED IN VILLAGE TEHSIL DISTRICT West Singhbhum STATE Jharkhand

File No:

Mine code **38JHK18003**

Name & Designation of the Inspecting Officer: **PK Bhattacharjee, RCOM**

Date of inspection: **18.8.2021**

1. General Information about the Mine:

- (i). Mine Name: **Rajanka Limestone Mine**
- (ii). Owner: **M/s ACC Ltd.**
- (iii). Nominated owner: **Mr. Sridhar Balakrishnan**
- (iv). Mining Engineer: **Mr. Sanjeev Tripathi**
- (v). Geologist: **Mr. Pankaj Sharma / Mrs. B. Basu**
- (vi). Agent: **Mr. R Gurung, Unit Head**
- (vii). Mines Manager: **Mr. Sanjeev Tripathi**
- (viii). Lease Area: **63.7 Ha.**
- (ix). Location: **Rajanka Limestone Mine**
- (x). Lease Period: **As per MMDR Act, 2015**
- (xi). Date of Expiry: **Upto 31.3.2030**
- (xii). Date of Approval of Mining Plan: **20.8.2015**
- (xiii). Date of Approval of Modification/Review of Mining Plan/Mining Scheme/FMCP etc. **26.11.2020 (RMP)**
- (xiv). Period of Mining Plan/Mining scheme/FMCP: **2020-21 to 2024-25**

2. Status of compliance of MCDR'2017 during the last 3 years:

SN	Date of Inspection	Name of Inspecting Officer	Violation of MCDR, 2017 Observed & pointed out	Rectification of violation	Remarks
1	8.11.2019	N Ekka, JMG	NIL	NA	-

3. Observations/ remarks on the earlier inspection carried out by sub-ordinate officer(s) with specific thrust on systematic and scientific mining, mineral conservation and environmental protection and other sensitive/important aspects pertaining to the mine area or surroundings (CRZ/ Western Ghats/ Wildlife Sanctuaries etc.):

- 1) Name of inspecting officer: **As mentioned in table 2 above.**
- 2) Date and Type of inspection: **As detailed in table 2 above (MCDR/ SDF inspection)**
- 3) Observations/Remarks w.r.t. the inspection carried out by the sub-ordinate officer(s) and shortfalls in the inspection report, if any, thereof: **The mine has been presently under temporary discontinuance due to non-availability of resources & the entire downstream cement plant is closed for shortage of raw materials.**

4. Communication / Direction(s) issued to the concerned IO based on the check-up inspection for further necessary action accordingly: The mine is already under temporary discontinuance.

Place: **Ranchi**

Date: **20.9.2021**


Signature