

REPORT ON CHECK UP INSPECTION OF Kendadih Copper MINE OF M/s Hindustan Copper Ltd. SITUATED IN VILLAGE Rakha DISTRICT East Singhbhum STATE Jharkhand

File No:

Mine code 14BHR27001

Name & Designation of the Inspecting Officer: PK Bhattacharjee, RCOM

Date of inspection: 17.9.2021

1. General Information about the Mine:

- (i). Mine Name: **Rakha Copper Mine**
- (ii). Owner: **M/s Hindustan Copper Ltd.**
- (iii). Nominated owner: **Mr. Sanjay Panjiyar**
- (iv). Mining Engineer: **Mr. Sampath Kr. Sangi**
- (v). Geologist: **Mr. Amit Degvekar**
- (vi). Agent: **Mr. SK Singh**
- (vii). Mines Manager: **Mr. Sampath Kr. Sangi**
- (viii). Lease Area: **785.091 Ha.**
- (ix). Location: **Rakha Copper Mine**
- (x). Lease Period: **As per MMDR Act, 2015**
- (xi). Date of Expiry: **Upto 28.8.2021.**
- (xii). Date of Approval of Mining Plan: **Not applicable. Lease not extended yet by Govt. of Jharkhand.**
- (xiii). Date of Approval of Modification/Review of Mining Plan/Mining Scheme/FMCP etc. **Lease not extended yet by Govt. of Jharkhand. Submitted mining plan not approved on 27.9.2021 due to above reason.**
- (xiv). Period of Mining Plan/Mining scheme/FMCP: **Not applicable**

2. Status of compliance of MCDR'2017 during the last 3 years:

SN	Date of Inspection	Name of Inspecting Officer	Violation of MCDR,2017 Observed & pointed out	Rectification of violation	Remarks
1	NIL	NIL	NIL	N.A	NII

3. Observations/ remarks on the earlier inspection carried out by sub-ordinate officer(s) with specific thrust on systematic and scientific mining, mineral conservation and environmental protection and other sensitive/important aspects pertaining to the mine area or surroundings (CRZ/ Western Ghats/ Wildlife Sanctuaries etc.):

- 1) Name of inspecting officer: **As mentioned in table 2 above.**
- 2) Date and Type of inspection: **Not applicable**
- 3) Observations/Remarks w.r.t. the inspection carried out by the sub-ordinate officer(s) and shortfalls in the inspection report, if any, thereof: **Lease not extended yet by Govt. of Jharkhand. Submitted mining plan not approved on 27.9.2021 due to above reason. One mine opening (Ventilation shaft) lying abandoned has not been properly barricaded.**

4. Communication / Direction(s) issued to the concerned IO based on the check-up inspection for further necessary action accordingly: Lease not extended yet by Govt. of Jharkhand.

Place: Ranchi
Date: 27.9.2021


Signature