

VIOLATION CUM SHOWCAUSE NOTICE
REGISTERED A/D

GOVERNMENT OF INDIA
MINISTRY OF MINES
INDIAN BUREAU OF MINES
OFFICE OF THE REGIONAL CONTROLLER OF MINES

No.: BIH/ROH/LST/346/RRO

318/B, Road No.3
Ashok Nagar, Ranchi-834002
TEL:0651-2242903/2242889
FAX: 0651 2242903
Date: 23.07.2015

To,

Sri B C Srivastava
Director cum Nominated Owner
M/s Kalyanpur Cements Ltd
At&PO.-Banjari
Dist.-Rohtas-821303(BHR).

Sub. : Violation of provisions of Mineral Conservation & Development Rules, 1988 in respect of your Murlipahari Limestone Mine (53.78 hect.) in Rohtas district, Bihar State.

Sir

The following provisions of Mineral Conservation and Development Rules, 1988 were found violated in your above mine during the inspection on 18.06.2015 by Sri B K Singh, Asstt. Mining Geologist, of Indian Bureau of Mines, Ranchi accompanied by Sri S K Singh GM(Mines) & Sri V D Sharma, Survey Officer.:

Rule No.	Nature of violations observed in details.
Rule-27(4)-:	The plan and section required under the rule shall be maintained up to date within three months in case of category 'A' mine. In your case it has been observed that same have not been maintained up to date.
Rule-29:	The Owner, agent mining engineer or manager of every mine shall (on or before 30 th day of June) every year shall submit to the Controller General, Controller of Mines and the Regional Controller of Mines a copy of Plans and sections maintained under Rule -28 of MCDR, 1988. It is observed that the updated plans and sections as required under the rule have not been submitted to this office.
Rule-33(2):	The dumps shall be properly secured to prevent escape of material there from in harmful quantities which may cause degradation of environment and to prevent causation of floods.
Rule-42(1)(c)(i)-:	A Whole time Mining engineer and Geologist have not been employed in your "A" category mines to carry out mining operations as required under the rule.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule-58 of MCDR-1988. The relevant extract of the rule 58 is given below:

"58 Penalty: - Whoever contravenes any of the provisions of these rule shall be punishable with imprisonment for a term which may extend up to **two years**, or with fine extending to **fifty thousand rupees** or with both, and in the case of continuing contravention with an additional fine which may extend up to **five thousand rupees** for every day during which such contravention continues, after conviction for the first such contravention. Provided that for repeated contravention the punishment should be in the form of imprisonment only".

03. You are, therefore advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully

-sd-
(R Purohit)
Regional Controller of Mines

Copy forwarded for kind information to: -

The Director of Mines, DMG, Govt of Bihar, New secretariat Building, Patna-800015.

- (a). "For examination & extent of the pit / quarries and its development /proposals etc. there is requirement of the boundary pillars. But physical presence of the boundary pillars of the lease boundary /area have not been seen at the time of inspection as per rule 31 of MCR -1960 and item 2, part VII of Form 'K'.
- (b). The lessee shall comply with the Mineral Conservation and Development rules 1988 framed under section 18 of the Mines and Minerals (Regulation & Development) Act, 1957 as required under rule 27(1)(u) of MCR 1960. But above said violations have not been complied by the lessee under MCDR 1988.

-sd-
(R Purohit)
Regional Controller of Mines

N.O.O.:

Copy forwarded for kind information to:

1. **The Controller of Mines (CZ), Indian Bureau of Mines, Indira Bhawan, Civil Lines, Nagpur- 440001.**

-sd-
(R Purohit)
Regional Controller of Mines