



भारत सरकार  
GOVERNMENT OF INDIA  
खान मंत्रालय  
MINISTRY OF MINES  
भारतीय खान ब्यूरो  
INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय  
OFFICE OF REGIONAL CONTROLLER OF MINES



दूरभाष: 080-29505368 / 29501827  
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,  
गोरगुंटापाल्या येशवंतपुर,  
बेंगलुरु -560022

सं/No.: KNT/GLB/LST-7/BNGMine-code:38KAR10012

दिनांक/Dated: 04/10/2021

To,  
Shri Seetharamulu Ch.,  
Agent & Director Plant,  
Wadi Cement Works Limestone Mine  
M/s. ACCLimited, Wadi  
Taluk-Chittapur  
Dist-Gulbarga  
Karnataka-585 225

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Wadi Cement works limestone Mine, ML 2641 of M/s.ACCLimited., over an extent of 471.03 ha, inIngalgi & Ravoor Villages, ChittapurTaluk, Kalaburagi District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 22.09.2021 by the undersigned in presence of Shri Vikram Singh- Mine Manager & Shri Jagadish K Madival-Geologist and other mining officials:

Rules	Nature of Violations observed
11 (1)	Modification to the approved Review and updation of Mining Plan was approved by IBM vide letter no. 279/116/89/BNG dated 09/09/2020, for the period 2020-21 to 2022-23(18/02/2023). The deviations observed in mining operation vis-à-vis approved document are given below. i) It was observed during site inspection that development of OB 1 <sup>st</sup> bench between Sec 6A-6A' to Sec 8A-8A' of the eastern pit were not advanced as per the proposal. Also, at the Western pit systematic development of OB 1 <sup>st</sup> bench between Sec 8-8' to 10-10' were not advanced as per the proposal.
31(4)	The plans & sections were not found maintained properly up to date as per the provision of this rule. The plan was not prepared and updated in UTM grid.

<b>45(7)</b>	<p>The online Annual return for the year 2020-21 has been submitted by the Lessee; Following discrepancies are noted in the submitted copy as observed during site inspection.</p> <p><b><u>Part-I:</u></b> The land use (area in ha) as given in Part-I (12) under 12(iii) have not been reported correctly in accordance with Para-8.6(Financial Assurance), of the approved document.</p> <p><b><u>Part-III:</u></b> The DMF and NMET amount has not been reported in Sec (5) (c).</p> <p><b><u>Part-V:</u></b> a) The details of Mineral Resource is not reported correctly under UNFC code-331 in Sec 3(B)(3) as per the approved document, for Limestone. b) The total quantity of Overburden/Waste removed during the year(tonnes) in Sec 4.2(C) &amp; Quantity backfilled in Sec 4.2(C)(i) have not been reported correctly.</p>
--------------	--

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (Forty-Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

**(Sandeep Kumar Singh)**

Assistant Controller of Mines

Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

**(Sandeep Kumar Singh)**

Assistant Controller of Mines

Indian Bureau of Mines