

**INDIAN BUREAU OF MINES
MINERALS DEVELOPEMMENT AND REGULATION DIVISION**

MCDR INSPECTION REPORT

Chennai regional office

Mine file No : TN/TCR/LST-71/MDS

Mine code : 38TMN24010

- (i) Name of the Inspecting : **T003**) **S.THIRUNAVUKKARASU**
Officer and ID No.
- (ii) Designation : Senior Mining Geologist
- (iii) Accompanying mine : Shri.Muthukaruppan rep of owner
Official with
Designation
- (iv) Date of Inspection : 31/10/2019
- (v) Prev.inspection date : 24/09/2002

PART-I : GENERAL INFORMATION

1. (a) **Mine Name** : **MARUVATHUR**
- (b) **Registration NO.** : **IBM/563/2011**
- (c) Category : B Manual
- (d) Type of Working : Opencast
- (e) Postal address
- State : TAMIL NADU
- District : PERAMBALUR
- Village :
- Taluka :
- Post office :
- Pin Code :
- FAX No. : 04312670042
- E-mail : dcplmaruthi@gmail.com
- Phone : 4312670364
- (f) Police Station : Perambalur
- (g) First opening date : 20/10/1995
- (h) Weekly day of rest : SUN
2. Address for : S.SARAVANAN, NO.24, AKIL NAGAR, T.V.KOIL,
correspondance TRICHY-5
3. (a) Lease Number :
- (b) Lease area :
- (c) Period of lease :
- (d) Date of Expiry :
4. Mineral worked : LIMESTONE Main

5. Name and Address of the

Lessee : S.SARAVANAN
23,AKILA NAGAR
TIRUVINAIKOIL, TRICHY
TIRUCHIRAPALLI TAMIL NADU
Phone:433006
FAX :

Owner : S.SARAVANAN
24,AKILA NAGAR, T.V.KOIL,
TRICHY-5 TIRUCHIRAPALLI
TAMIL NADU
Phone:
FAX :

6. Date of approval of Mining	:	Mining Scheme rule 12 MCDR1988	15/01/2001
Plan/Scheme of Mining		Mining Scheme rule 12 MCDR1988	01/07/2014
		Renewal under rule 24 MCR1960	02/12/2014

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.	Item	Proposals	Actual work	Remarks
1a	Backlog of previous year	NIL	NA	No proposal, 9 Nos BH drilled total met rage of 72 m
1b	Exploration over lease area for geological axis 1 or 2	NIL	NA	Explored under G1 & G 2 level
1c	Exploration Agencies and Expenditure in lakh rupees during the year	NIL	NA	NIL
1d	Balance area to be explored to bring Geological axis in 1 or 2	NIL	NA	NIL
1e	Balance reserve as on 01/04/20	---	111 -286036 tons 221) - 380624 tons 222-115808 TONS	NIL
1f	General remarks of inspecting officers on geology, exploration etc	----	---	Addition exploration proposed in the ROMP period 2020-21-2025-26 ,to prove the depth existence etc

Development :

Sl.No.	Item	Proposals	Actual work	Remarks
2a	Location of development w.r.t.lease area	Existing pit - 1	NIL	Mine not working
2b	Separate benches in topsoil, overburden and minerals (Rule 15)	1	NA	Mine not working
2c	Stripping ratio or ore to OB ratio	1:0.20	NIL	Mine not working
2d	Quantity of topsoil generation in m3	5994 tonns	NIL	Mine not working
2e	Quantity of overburden generation in m3	NIL	NA	Mine not working

2f	General remarks of inspecting officers on development of pit w.r.t. type of deposit etc	---	----	Mine not working
----	---	-----	------	------------------

Exploitation:

Sl.No.	Item	Propasals	Actual work	Remarks
3a	Number of pit proposed for production	1	Na	Mine was temporarily discontinued from 20.02.2017.
3b	Quantity of ROM mineral production proposed	51920	NIL	Mine not working
3c	Recovery of sailable/usable mineral from ROM production	41536	NIL	Mine not working
3d	Quantity of mineral reject generation	10384	NIL	Mine not working
3e	Grade of mineral rejects generation and threshold value declared.	SiO2 below4.01	NIL	Mine not working
3f	Quantity of sub grade mineral generation.	NIL	NA	NIL
3g	Grade of sub grade mineral generation	NIL	NA	NIL
3h	Manual / Mechanised method adopted for segregating from ROM	machanised	NIL	Mine not working
3i	Any analysis or beneficiation study proposed and carried out for sub grade mineral and rejects.	NIL	NA	NIL
3j	Provision of drilling and blasting in mineral benches	NIL	NA	NIL

3k	Provision of mining machineries in mineral benches	NIL		NA		NIL
3l	Whether height of benches in overburden and mineral suitable for method of mining proposed in MP/SOM	4		NIL		Mine not working
3m	Total area covered under excavation/pits	2.59.8		NIL		Mine not working
3n	Ore to OB ratio for the pit/mine during the year.	1:0.20		nil		Mine not working
3o	Total area put in use under different heads at the end of year	2.59.8		nil		Mine not working
3p	Production of ROM mineral during the last five year period as applicable	2015-16 12310 2016-17 62554 2017-18 59302 2018-19 50707 2019-20 41536		2015-16 4950 2016-17 140 2017-18 NIL 2018-19 NIL 2019-20 NIL		Mine was temporarily discontinued from 20.02.2017
3q	General remarks of inspecting officers on method of mining etc.	---		----		Mine was temporarily discontinued from 20.02.2017

Solid Waste Management - Dumping:

Sl.No.	Item	Propasals	Actual work	Remarks
4a	Separate dumping of topsoil, OB and mineral rejects (Rule 32,33)	NIL	NA	Mine was temporarily discontinued from 20.02.2017
4b	Location of topsoil, OB and mineral reject dumps	Mineral reject dumpN1125-N1050 -E-1200-E1050	NIL	Mine not working
4c	Number of dumps within lease area and outside of lease area	1 Nos	1 Nos	Mine not working

4d	Location of dumps w.r.t. ultimate pit limit (Rule 16)	NIL	NA		NIL
4e	Number of active and alive dumps.	nos	1	1 nos	NIL
4f	Number of dead dumps.	NIL	NA		NIL
4g	Number of dumps established.	NIL	NA		NIL
4h	Whether Retaining wall or garland drain all along dumps are there.	NIL	NIL		NIL
4i	Length of Retaining wall or garland drain all along dumps	NIL	NA		NIL
4j	Number of settling ponds	NIL	NA		NIL
4k	Specific comments of inspecting officer on waste dump management	---	---		Inspection carried out for ROMP, Mine is not working during the time of inspection

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	NIL	NA	NIL
5b	Area under backfilling of mined out area	NIL	NA	NIL
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	NIL	NA	NIL
5d	Total area fully reclaimed and rehabilitated	NIL	NA	NIL

5e	General remarks of inspecting officers on backfilling and reclamation etc.	--	---	Mine was temporarily discontinued from 20.02.2017
----	--	----	-----	---

Progressive Mine Clousre Plan:

Sl.No.	Item	Propasals	Actual work	Remarks
6a	Whether Annual report on PMCP submitted on time and correctly. Rule 23 E(2).	YES	Not Submitted	Mine was temporarily discontinued from 20.02.2017
6b	Area available for rehabilitation (ha) .	NIL	NA	NIL
6c	afforestation done (ha).	20 Nos	NIL	MINE NOT WORKING
6d	No. of saplings planted during the year	20	nil	Mine not working
6e	Cumulative no .of plants	NIL	NIL	NIL
6f	Any other method of rehabilitation	NIL	NIL	NIL
6g	Cost incurred on watch and care during the year	NIL	NIL	NIL
6h	Compliance on reclamation and rehabilitation by backfilling (i) Voids available for backfilling (Lx B x D	NIL	NIL	NIL
6i	Compliance on reclamation and rehabilitation by backfilling (ii) Voids filled by waste / tailings	NIL	NIL	NIL

6j	Compliance on reclamation and rehabilitation by backfilling (iii)Afforestation on on backfilled area	NIL	NIL	NIL
6k	Compliance on reclamation and rehabilitation by backfilling (iv) Rehabilitation by making water reservoir	NIL	NIL	NIL
6l	Compliance on reclamation and rehabilitation by backfilling (v)any other specific means.	NIL	NIL	NIL
6m	Compliance of rehabilitation of waste land within lease (i)afforestation	NIL	NIL	NIL
6n	Compliance of rehabilitation of waste land within lease (ii)Area rehabilitation (ha)	NIL	NIL	NIL
6o	Compliance of rehabilitation of waste land within lease (iii)Method of rehabilitation	NIL	NIL	NIL
6p	Compliance of environmental monitoring (core zone and buffer zone)	NIL	NIL	NIL
6q	General remarks of inspecting officers on PMCP compliance and progressive closure operations etc.	----	----	Mine was temporarily discontinued from 20.02.2017

 Mineral Conservation:

Sl.No.	Item	Propasals	Actual work	Remarks
--------	------	-----------	-------------	---------

7a	ROM Mineral dispatch or grade-wise sorting within lease area	41536 (2019-20) 41536 (2019-20)	NIL	Mine was temporarily discontinued from 20.02.2017
7b	Method of grade-wise mineral sorting i.e. manual or mechanical.	NIL	NA	NIL
7c	Different grade of mineral sorted out at mines.	NIL	NA	NIL
7d	Any beneficiation process at mines	NIL	NANIL	
7e	General remarks of inspecting officer on Mineral conservation and beneficiation issues	---	----	Mine not working

Environment:

Sl.No.	Item	Propasals	Actual work	Remarks
8a	Separate removal and utilization of topsoil (Rule 32)	Top soil propose for Afforestation	NIL	Mine was temporarily discontinued from 20.02.2017
8b	Concurrent use or storage of topsoil	Top soil propose for Afforestation	Top soil propose for Afforestation	NIL
8c	Separate dumps for overburden, waste rock, rejects and fines (Rule 33)	1 nos	1 nos	
8d	Use of overburden, waste rock, rejects and fines dumps for restoring the land to its original use	OB & mineral reject dump	NIL	Mine not working

8e	Phased restoration, reclamation and rehabilitation of lands affected by mining operations (Pits, dumps etc)	NIL	NA	NIL
8f	Baseline information on existence of plantation and additional plantation done (Rule 41)	Proposed	NIL	Mine not working
8g	Survival rate	70%	70%	NIL
8h	Water sprinkling on roads to control airborne dust	Proposed	NIL	Mine not working
8i	General remarks of inspecting officer on aesthetic beauty in and around mines area	----	----	Mine was temporarily discontinued from 20.02.2017

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	Given in the format	Annual return for 2019-20 submitted	nil
9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Given in the format	nil	Part-I Sl.No.8&9 & Part-II, Employment & Wages
9c	Scrutiny of Annual return on land use pattern for area under pits, reclaimed area, dumps etc.	Given in the format	0	Part-I Sl.No.12
9d	Scrutiny of Annual return on afforestation	Given in the format	Not given	Part-I Sl.No.12

9e	Scrutiny of Annual return on mineral reject generation (Grade and quantity)	Given in the format	NIL	Part-V General Geology, Sl.No.4.2(B)
9f	Scrutiny of Annual return on ROM stock and/or graded ore	Given in the format	0	Part-VI, Sl.No.2
9g	Scrutiny of Annual return on sale value, Ex. Mine price and production cost	Given in the format	Mine price = 0 production cost =0 Mine is not working	PART - VII (COST OF PRODUCTION)
9h	Scrutiny of Annual return on fixed assets	Given in the format	Rs.350000/-	PART III, Sl.No. 2 (Royalty and Rents)
9k	Scrutiny of Annual return on mining machineries	Given in the format	Not given	PART - V (General Geology & Mining) Sl.No.5

Details of violations observed during current inspection and compliance position of violation pointed out

Violation observed		Show cause position	
Rule NO.	Issued on Compliance on	Rule NO.	Issued on Compliance on

Date :

(S. THIRUNAVUKKARASU)

Indian Bureau of Mines