भारत सरकार खान मंत्रालय भारतीय खान ब्यूरो

क्षेत्रीय खान नियंत्रक का कार्यालय Mine Code-30ORI13054 दि 28/09/2018 फाईल सं.: ORI/IRON/SNG/MCDR-22/BBS

Sri R.L Mohanty, Managing Partner

M/s M.G. Mohanty,

5A, Forest park, Bhubaneswar-751009

Sub: Violation of provisions of Mineral Conservation & Development Rules, 2017 in respect of your in respect of your Patabeda Iron Mines over an area of 14.0 hectare in Sundergarh District.

The following provisions of MCDR,2017 were found violated in your above mine during

inspection on 21/09/2018 by undersigned in presence of Sri Balaram Behera, Mines Manager.

Rule No.	Nature of violations observed
11(1)	Mining operations have not been carried out in accordance to Scheme of Mining, approved vide this office letter number MS/FM/20-ORI/BHU/2015-16, dated 18.03.2016 to the extent given below: In 2017-18, it was proposed to construct the retaining wall of 200mX1MX1.5m along the boundary line D2-D3 but it has been observed that the proposed retaining wall has not been constructed.

02 In this connection, it is brought to your notice that the above violations constitute an offence punishable under rule 62 of Mineral Conservation and Development Rules, 2017.

03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found

satisfactory.

04. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty-five) days from the date of issue of this letter.

(D. Upadhyay) Senior Assistant Controller of Mines Indian Bureau of Mines

Copy forwarded to:

1. The Controller of Mines (EZ) / Indian Bureau of Mines / Kolkata.

2. The Director of Mines / Directorate of Mines / Government of Orissa / Heads of Department Doyanand upadhyay Building / New Capital / Bhubaneswar-751 001.

(D. Upadhyay) Senior Assistant Controller of Mines Indian Bureau of Mines