



भारत सरकार/ GOVERNMENT OF INDIA
खान मंत्रालय/ MINISTRY OF MINES
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय/
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287

दूरभाष: 080-23371027 / 23375366/67

Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब ॥ स्टेज,, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.: KNT/MYS/Ky-1/BNG

दिनांक/Date: 12/10/2021

सेवा में ,To,

Sri Shivayogi S.S, GPA Holder,
Karigala Kyanite Mine,
No.228, 'Neralu' First floor,
8th Cross, 1st Main, 2nd Stage,
Srirampura, Mysuru-570 034.
shivayogi.ec@gmail.com

विषय/Sub: Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Karigala Kyanite Mine (ML No. 2286)** over an area of **12.14 Ha** having mine code 33KAR14004 in Karigala village, HD Kote Taluk, Mysore District, Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by Sri. H.M.Shivakumar-Assistant Mining Engineer in presence of Sri. Shivayogi, GPA Holder, Dr. C.P.Prasanna Kumar- Geologist on **06/10/2021**.

Rule	Nature of violations observed
11 (1)	<p>RUMP along with PMCP was approved vide letter No. 279/635/99/BNG dated 12/03/2020 for the period from 2020-21 to 2024-25. The deviations observed in mining operations vis-a-vis approved document are given below:</p> <p>-It was proposed to 4 exploratory trenches each during 2020-21 & 2021-2022 but it is not done.</p> <p>-It was proposed to produce 26879 Tones of saleable Kyanite Ore during 2020-21 but only 3780 Tones is reportedly produced and is only 13% of the total proposed production.</p> <p>-It was proposed to construct One Check dam during 2020-21 outside the lease boundary on South-Western part the lease which is not done.</p> <p>-7.5m safety Zone is not properly demarcated on the ground and maintained.</p>
26(2)	<p>A yearly report as per the format specified by the Indian Bureau of Mines has not been submitted before 1st July 2021 setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan.</p>

33	Surface plan, Geological Plans and Sections as per the Rule 32 of MCDR, 2017 are not submitted before 30 th June 2021 for the year 2020-2021.
Rule 45(7)	<p>As part -V of the Annual Returns submitted for FY 2020-21, Quantity of Overburden/ Waste is wrongly submitted as 17071 which is not in tune with only 13% of the proposed production achieved. Since this is float ore mining the Quantity of waste disposal are not proportionate to the production achieved.</p> <p>As per part VII of the Annual Returns submitted for FY 2020-21, DMF, NMET & Royalty paid details have not been furnished and accounted for arriving at the cost of Production.</p>
Rule 55 (1) (c) (ii)	For Carrying out mining operations in accordance with the rules Category "B" mines, a part-time mining engineer and a part-time Geologist should be employed. No part-time mining engineer is employed in the Mine.

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(अरुणकुमार)/Arun Kumar
उपखाननियंत्रक/Dy. Controller of Mines
भारतीयखानब्यूरो/Indian Bureau of Mines

प्रतिलिपिसूचनार्थ/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining & Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001.

Sd/-

(अरुणकुमार)/Arun Kumar
उपखाननियंत्रक/Dy. Controller of Mines
भारतीयखानब्यूरो/Indian Bureau of Mines

