



भारत सरकार/ GOVERNMENT OF INDIA  
खान मंत्रालय/ MINISTRY OF MINES  
भारतीय खान ब्यूरो/ INDIAN BUREAU OF MINES  
क्षेत्रीय खान नियंत्रक कार्यालय/  
OFFICE OF REGIONAL CONTROLLER OF MINES



फैक्स: (080) 23371027 / 23373287  
दूरभाष: 080-23371027 / 23375366/67  
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब ॥ स्टेज,, तुमकुर रोड,  
गोरगुंटापाल्या येशवंतपुर,  
बेंगलुरु -560022

सं/No.: KNT/BLR/Fe-455- Vol-I

दिनांक/Date: 12/10/2021

सेवामें/To,  
Sri. Syed Ahmed,  
Managing partner,  
M/s. Zeenath Transport Company,  
"Zeenath House", Cowl Bazaar,  
Ballari-583 102.  
Ztco2000@yahoo.com

**विषय/Sub:** Violation of provisions of Mineral Conservation and Development Rules, 2017 in respect of your **Ramgad Iron Ore Mine (ML.No.2547)** over an extent of **49.73 Ha** having mine code 30KAR03160 in Ramgad village, Sandur Taluk, Ballari District, Karnataka state.

महोदय/Sir,

The following provisions of the Mineral Conservation & Development Rules, 2017 were found violated in your above mine during the inspection carried out by the undersigned along with Shri. H.M.Shivakumar-Assistant Mining Engineer in presence of Shri. J. Srikanth Manager (Mines) & Shri. Veeresh Kumar K.J -Geologist on **28/09/2021**.

Rule	Nature of violations observed
11 (1)	RMP with PMVP was approved vide letter <b>No. 279/419/94/BNG dated 08/11/2016</b> for the period from 2017-18 to 2021-2022. The deviations observed in mining operations vis-a-vis approved document are given below:  It was proposed to maintain 7.5m bench height and 10m bench width. During the inspection it is observed that at some places i.e. between sections M-M' & -N-N', the height of the benches are exceeding the approved height thereby creating high walls. It is also observed that the excavations are extending beyond the approved proposals in south eastern part of the working pit for the year 2021-22.  A huge quantity of ROM is stacked between N-1667944-1667886 & E-660741 - 660771. The stacking of ROM in this location is not proposed in the approved Mining Plan.
26(2)	A yearly report as per the format specified by the Indian Bureau of Mines has not been submitted before 1 <sup>st</sup> July 2021 setting forth the extent of protective and rehabilitative works carried out as envisaged in the approved mine closure plan.
Rule 45(7)	As per part VII of the Annual Returns submitted for FY 2020-21, DMF, NMET & Royalty paid details have not been furnished and accounted for arriving at the cost of Production.

-2-

सं/No.: KNT/BLR/Fe-455- Vol-I

02. In this connection it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR 2017.

03. You are advised to rectify/explain the above violations immediately and intimate the position to this office within 45 (Forty Five) days from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(वी. जयाकृष्णा बाबू / V.Jayakrishna Babu)

क्षेत्रीय खान नियंत्रक/Regional Controller of Mines  
भारतीय खान ब्यूरो/Indian Bureau of Mines

प्रतिलिपिसूचनार्थ/Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Department of Mining &Geology, No.49, Khanijabhavan, R.C. Road, Bangalore-560 001.

Sd/-

क्षेत्रीय खान नियंत्रक/Regional Controller of Mines  
भारतीय खान ब्यूरो/Indian Bureau of Mines