



भारत सरकार
GOVERNMENT OF INDIA
खान मंत्रालय
MINISTRY OF MINES
भारतीय खान ब्यूरो
INDIAN BUREAU OF MINES
क्षेत्रीय खान नियंत्रक कार्यालय
OFFICE OF REGIONAL CONTROLLER OF MINES



दूरभाष: (080) 39505368 / 29720499
Email ID: ro. bangalore@ibm.gov.in

29, इंडस्ट्रियल सबर्ब, II स्टेज, तुमकुर रोड,
गोरगुंटापाल्या येशवंतपुर,
बेंगलुरु -560022

सं/No.: KNT/BLR/Fe-494/BNG Mine-code: 30KAR03185

दिनांक/Dated: 14/10/2021

To,
Dr. Vinod Nowal,
Nominated Owner, Rama Iron ore mine
M/s JSW Steel Ltd,
JSW Mining Office, Near Talur Cross
Vidyanagar (Post), Toranagallu, Sandur Taluk
Bellary Dist, Karnataka-583275

विषय/Subject: **Violation of provisions of MCDR 2017 in respect of your Rama Iron ore Mine, ML 0009 over an extent of 32.56 ha, in Ramgad Village, Sandur Taluk , Bellari District of Karnataka State.**

Sir,

The following provisions of the Mineral Conservation and Development Rules, 2017 were found violated in your above mine during inspection on 20.09.2021 by the undersigned along with Shri K. Srinivas, AMG in presence of Shri M.V. Sundra Raja, Mines Manager, Shri Karani Singh, AGM (Geology), Shri Karthik Gujjal, Mining Engineer and other mining officials:

Rules	Nature of Violations observed
11 (1)	Modified Mining plan was approved by IBM vide letter no. 279/1092/2017/BNG/276 dated 18/02/2021, for the period 2020-21 to 2023-24. The deviations observed in mining operation vis-à-vis approved document are given below. i) For the year 2020-21, under development 92,600 tonnes of waste has been proposed. It was observed during site inspection that the only 14,800 tonnes of waste has been handled against 92,600 tonnes during the year 2020-21. The deviation is more than 80%.
45(7)	The online Annual return for the year 2020-21 has been submitted by the Lessee; Following discrepancies are noted in the submitted copy as observed during site inspection. <u>Part-VI</u> : The Ex-mine price reported in Part-VI (3) has not been reported correctly. In case of Captive mines, the Ex-mine price per tonne is the per unit cost of production.

02. In this connection, it is brought to your notice that the above violations constitute an offence punishable under Rule 62 of MCDR, 2017.
03. The mining operations can be suspended under rule 11(2), if compliance of rule 11(1) is not found satisfactory.
04. You are advised to rectify the above violations immediately and intimate the position to this office **within 45 (Forty-Five) days** from the date of issue of this letter.

भवदीय/Yours faithfully,

Sd/-

(Arun Kumar)
Deputy Controller of Mines
Indian Bureau of Mines

Copy for kind information to:

1. The Controller of Mines (SZ), Indian Bureau of Mines, Bangalore.
2. The Director, Dept. of Mines & Geology, 49, Khanij Bhavan, Race Course Road, Bangalore-560001.

Sd/-

(Arun Kumar)
Deputy Controller of Mines
Indian Bureau of Mines