

| Hkjr ljdkj/Government of India | [kku eæky;/Ministry of Mines | Hkjrh; [kku 0;jkk/Indian Bureau of Mines हैदराबाद {keh; dk;ky;/Hyderabad Regional Office



F.No. AP/NLG/LST-24/HYD

603, NBk ry /603, 6th Floor,
I hthvksVkWI I/CGO Towers,
dokMhxVIIk /Kavadiguda,
fl dUnjkckn/secunderabad-500 080.
Date: 22.10.2021

To
The Agent(Mines),
Anjani Limestone Mine-I,
M/s Anjani Portland Cements Limited,
Chintalapalem Village & Mandal,
Suryapet district-508246,
Telangana State.

Sub: Violation of provisions of MCDR, 2017 in respect of Anjani Limestone Mine-I over an area of 57.52 ha in Chintalapalem Village & Mandal, Suryapet district, Telangana State.

Sir,

The following provisions of Mineral Conservation and Development Rules, 2017 were found violated in your above mine during the inspection on 08.10.2021 by the undersigned accompanied by Sri V.Ramachandram, Mines Manager.

Rule No-	Nature of violation
11 (1)	No holder of a mining lease shall commence or carry out mining operations in any area except in accordance with the mining plan approved, modified or reviewed by the Indian Bureau of Mines or prepared and certified in accordance with the system established by the State Government pursuant to the proviso to clause (b) of sub-section(2) of section 5. (a) It was proposed to develop the Mine by maintaining a Bench Height of 6-7 meters. However, during the inspection it was observed that on the Eastern side of the working pit the bench height is more than the proposed height. (b) Further, two benches have been merged on the Southeast corner of the working pit and made more than 8 meters height. (c) The bund height on either side of the haul road is less than 1 meter of height.
31(1)	Every plan or section prepared or submitted in accordance with the provisions of the MCDR,2017. "In the surface Plan all the features have not been properly marked. An updated Surface Plan to be submitted."

- 02. In this connection, it is brought to your notice that the above said violations constitute an offence punishable under Rule-62 of MCDR, 2017. Further, inability to comply the provision of Rule 11(1) is liable for suspension of mining operations under Rule 11(2) of MCDR,2017.
- O3. You are advised to rectify the above violations immediately and intimate the position to this office within 45 (forty five) days from the date of issue of this letter.

Yours faithfully

Sd/-(Shailendra Kumar) Regional Controller of Mines

eny ifr ij ught/Not on the Original:

- 1) [kku fu;æd (n),Hkkjrh; [kku C;ÿkkj c&ykj dksifrfyfi l ppukFkZ∨xf"krA
- 2) The Director, Department of Mines & Geology, Govt. of Telangana, II floor, My Home Sarovar Plaza, Adarsh Nagar, Hyderabad-500063.
- 3) The ADMG, Govt. of TS,opp Vinayaka Temple,Pathakunta,Adarsh Nagar,Saipur,Tandur Town,Vikarabad-501141.

Sd/-

(Shailendra Kumar) Regional Controller of Mines