INDIAN BUREAU OF MINES MINERALS DEVELOPMENT AND REGULATION DIVISION

MCDR inspection REPORT

Hyderabad regional office

Mine file No : AP/ANP/L.ST-26/HYD Mine code : 38APR02036

(i) Name of the Inspecting : $\mathbf{S41}$) \mathbf{Y} \mathbf{M} \mathbf{SIVA} \mathbf{PRASAD}

Officer and ID No.

(ii) Designation : Assistant Mining Engineer

(iii) Accompaning mine : Sri Balaram, Mines Manager.

Official with Designation

(iv) Date of Inspection : 07/09/2017
(v) Prev.inspection date : 03/01/2017

PART-I : GENERAL INFORMATION

. (a) Mine Name : NAGARUR(4.311 HA)

(b) Registration NO. :

(e) Postal address

State : ANDHRA PRADESH

District : ANANTAPUR
Village : NAGARUR
Taluka : YADIKI
Post office : NAGARUR
Pin Code : 515455

FAX No. :
E-mail :
Phone :

(f) Police Station : YADIKI

(g) First opening date : 10/10/2006

(h) Weekly day of rest : SUN

2. Address for : A.SURESH , MINEOWNER, NEAR CHANDANA GATE

correspondance RAYALACHERUVU(PO)-515455

ANANTAPUR DT ANDHRAPRADESH

3. (a) Lease Number : APR2451
(b) Lease area : 4.62
(c) Period of lease : 20

(d) Date of Expiry : 09/04/2026

4. Mineral worked : DOLOMITE Associated

LIMESTONE Main

PAGE : 2

5. Name and Address of the

Lessee : A.SURESH

NEAR CHANDANAGATE

RAYALACHERUVU (V) TADIPATRI

(M) ANANTAPUR ANDHRA

PRADESH
Phone:
FAX:

Owner : A.SUREH

NEAR CHANDANA GATE RAYALACHERUVU(PO &V) TADIPATRI(M) ANANTAPUR

ANDHRA PRADESH

Phone: FAX :

6. Date of approval of Mining : Fresh under rule 22 MCR1960 30/08/2005 Plan/Scheme of Mining : Mining Scheme rule 12 MCDR1988 13/10/2016

Remarks

PART - II : OBSERVATION/COMMENTS OF INSPECTING OFFICERS

Exploration :

Sl.No.

Item

1a	Backlog of previous year	Three Bore holes.	The lessee did not takeup the exploration by means of drilling. However eight trialpits were dug.	It is reported that due to economic constraints the drilling could not takenup and instead 08 trialpits were dug.
1b	Exploration over lease area for geological axis 1 or 2	Core bore	The lessee has not carried out exploration.	The lessee is not carrying out mining operation in the mine. The lessee has submitted Temporary discontinuance notice under rule 28(1) of MCDR 2017. to this office w.e.f. 01.04.2017.
1c	Exploration Agencies and Expenditure in lakh rupees during the year	N I L	N IL	
1d	Balance area to be explored to bring Geological axis in 1 or 2			
1e	Balance reserve as on 01/04/20	0.071 million tonnes.	0.071 million tonnes.	
Deve	elopment :			
Sl.No.	Item	Propasals	Actual work	Remarks
2a	Location of development w.r.t.lease area	5 No's of working pits.	It was observed during inspection mining operations were not carried out.	

Propasals Actual work

Number of pit 05 No's. NIL proposed for production

Lessee has submitted Temporary discontinuance notice to this office w.e.f.

Quantity of ROM 10,000 tonnes. N I L. 3b mineral production

Lessee has submitted Temporary discontinuance notice to this

01.04.2017

3h Manual / Manual open N I L Mechanised cast method. method adopted for segregating

Lessee has submitted Temporary discontinuance notice to this office w.e.f.

01.04.2017

office w.e.f. 01.04.2017

3k Provision of N IL. mining

machineries in mineral benches

proposed

from ROM

Excavator :

0.9Cu.M.

Front End Loader : 1.7Cu.M. Jack Hammer Drilling Machine : 32mm dia.

Production of 3р ROM mineral during the last five year period 15 : N I L. as applicable

2012-13 : N 2012-13 : 6685 tonnes, IL. 2013-14: 2013-14: N I L. 2014-2014- 15 : N I L. NIL. 2015-16 : N I L 2016-17 : N I L

2015-16 : N I L 2016-17: 10000 tonnes

Solid Waste Management - Dumping:

Sl.No. Item Propasals Actual work Remarks 4a Separate dumping No proposal of topsoil, OB and mineral rejects (Rule 32,33) 4b Location of No proposal N I L topsoil, OB and mineral reject dumps 4c Number of dumps 05 Dumps NIL within lease within ML area and outside area. of lease area 4h Whether Retaing Wall N I L Retaining wall : N - 1656347 or garland drain TO 1656373 all along dumps are there.

Lessee has not carried out mining operations.Lessee has submitted temporary discontinuace notice w.e.f. 01.4.2017

E - 802342 TO 802364

Dimention: $106m L \times 1.0 m$ w x 1.0 m h.

Garlaind Drain: Dimension: 109mL X 1.0 m W x 1.0m H. Location: N - 1656335 to 1656352 E802341 to 802364.

Solid Waste Management - Backfilling:

Sl.No.	Item	Propasals	Actual work	Remarks
51.110.	I Celli	FIOPASAIS	Accual Work	Kemarks

Sl.No.	Item	Propasals	Actual work	Remarks
	Progressive Mine (Clousre Plan:		
5c	Concurrent use of topsoil for restoration or rehabilitation of mineral out area (Rule 32)	Top soil generated during mining operations stored at topsoil storage temporarily within lease areaand it will be used for plantation work on thesafety zone& side by land.	N I L	Lessee submitted temporary discontinuance notice in Form E under rulke 28(1) of MCDR 2017 w.e.f. 01.4.2017.
5a	Status of part or full extraction of mineral from mined out area before starting backfilling.	First year ie 2016-17 after the extractionof the mineral , the area is extending in the 7.5 m safety zone will be restored by backfilling the waste.		The lessee has not carried out mining operations in the mine during the year 2016-17. The lessee has submitted temporary discontinuance notice in Form E w.e.f. 01.4.2017.

Mine	eral Conser	vation:		
Sl.No.	Item	Propasals	Actual work	Remarks
Envir	onment:			
Sl.No.	Item	Propasals	Actual work	Remarks

Compliance of Rule 45:

Sl.No.	Item	Propasals	Actual work	Remarks
9a	Status of submission of Monthly and Annual returns	submit Monthly returns and	Lessee is submitting monthly returnsand annual return forthe year 2016-17through ON-LINE.	

9b	Scrutiny of Annual return for information on Mining Engineer, Geologist and Manager	Shri BalaramPrasad as Mines Manager.	Shri BalaramPrasad as Mines Manager	
9f	Scrutiny of Annual return on ROM stock and/or graded ore	N IL	N I L	The mine is under temporary discontinuance w.e.f. 01.4.2017

PAGE : 8

Details of violations observed during violation pointed out	g current inspection and compliance position of
Violation observed	Show couse position

Violation observed		Show couse position		
Rule NO.	Issued on	Compliance on	Rule NO.	Issued on Compliance on

Date :

(Y M SIVA PRASAD)

Indian Bureau of Mines